

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

3a. Indicate Type of Lease	
State ☐	Fee ☒
3. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER- Carbon Dioxide		7. Unit Agreement Name
2. Name of Operator SCHWARTZ CARBONICS		8. Farm or Lease Name Norman & Esther Libby
3. Address of Operator Box 37, Solano, New Mexico 87746		9. Well No. Schwartz IX
4. Location of Well UNIT LETTER <u>G</u> <u>1637</u> FEET FROM THE <u>North</u> LINE AND <u>1650</u> FEET FROM THE <u>East</u> LINE, SECTION <u>30</u> TOWNSHIP <u>20 N</u> RANGE <u>31 E</u> NMPM.		10. Field and Pool, or Wildcat Bueyeros Pool
15. Elevation (Show whether DF, RT, GR, etc.) 3' above GL		12. County Harding

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☒
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☒	OTHER <u>Repair casing leaks</u> ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Ran 1907' of 4 1/2" 11.60# flush joint K55 casing. Casing was set at 1910' and cemented with 100 sacks of Class C cement. Bump plug with 1500# @ 2:23 p.m. on 9/21/84. Circulated 42 sacks to the pit and WOC 24 hrs. Tested casing to 1000# for 30 minutes. Tested O.K. Drilled cement out of casing and ran internally coated Guiberson ER-6 packer with 2 3/8" 4.7# J-55 internally coated tubing. Packer was set at 1884'. Backside was loaded with inhibited packer fluid and tested to 600# with no leaks. Acidize open hole section 2080' to 1976' with 5000 gals. Halliburton MOD 101 acid containing clay stabilizer with 1000 scf CO2 per bbl./acid. MTP 1600# ATP 1550# MIR 4.5 bpm AIR 3.6 bpm isip 1000# 10M sip 900#. Flowed well back to clean up and placed well in production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Regional Production Manager DATE 11-12-84

APPROVED BY _____ TITLE DIC DATE 11-26-84

CONDITIONS OF APPROVAL, IF ANY: