

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-183
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.	30-021-20229
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	West Bravo Dome CDG Unit
8. Well No.	18
9. Pool name or Wildcat	West Bravo Dome
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
5411'	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER CO2 Supply <input type="checkbox"/>
2. Name of Operator OXY USA Inc.
3. Address of Operator P.O. Box 50250 Midland, TX. 79710
4. Well Location Unit Letter <u>F</u> : <u>1650</u> Feet From The <u>North</u> Line and <u>1650</u> Feet From The <u>West</u> Line Section <u>18</u> Township <u>19N</u> Range <u>29E</u> NMPM <u>Harding</u> County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: Yearly Bradenhead Test (SI Well) <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

WBDCDGU #18 - TD-2925' PBDT-2881' PERFS-2756-2796'				
YEAR	DATE	TBG PSI	CSG PSI	BLEED DOWN TIME
1990	----	----	----	----
1991	10/30	560	0	
1992				
1993				
1994				
1995				
1996				
1997				
1998				
1999				
2000				

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE Production Accountant DATE 11/26/91

TYPE OR PRINT NAME David Stewart TELEPHONE NO 9156855717

(This space for State Use)

APPROVED BY Ry E Johnson TITLE DISTRICT SUPERVISOR DATE 12-9-91

CONDITIONS OF APPROVAL, IF ANY:

AUTHORIZATION FOR MAINTENANCE IN SHUT-IN OR
TEMPORARY ABANDONMENT STATUS EXPIRES 10-30-92

WEST BRAVO DOME CDU #18
 1650' FNL & 1650' FNL SEC 18 T19N R29E


ELEVATION: KB: 5424'
 GL: 5411'

9 5/8" SURFACE CASING @ 608'
 CNTD W/ 500 SX CNT. CIRC.

1 - 2 3/8" X 5 1/2" GJIB UNI VI	6.50
1 - 2 3/8" GJIB ON/OFF TOOL	2.45
1 - 2 3/8" CHROME SUB	6.05
88 - JTS 2 3/8" 4.7# J55 TBG	2610.74
4 - 2 3/8" FB SUBS	26.05
1 - 2 3/8" CHROME SUB	6.10
TOTAL	2644.89
KB	13.00
SET AT	2657.89

PACKER EQUIPPED 1.781 PROFILE NIPPLE

	SURFACE	PRODUCTION	TUBING
SIZE	9 5/8"	5 1/2"	2 3/8"
WEIGHT	38 #	15.5 #	2000 #
GRADE	K-55	K-55	FB
THREAD	STBC	LTBC	8rd EUE
DEPTH	608'	2919'	2888'



5 1/2" PACKER @ 2658'

TUBG PERFS (2756' - 2796')

PREP'D BY: JOE M. FLEKING
 DATE : MAY 15, 1991

P8TD @ 2881'
 5 1/2" CSB @ 2919' CNTD W/ 900 SX
 TD @ 2925' CNT CIRC

Bob Brach
673-2939

handwritten
over
water well

OXY USA

CO₂ well

water well supply

18-19N-29E

w Bravo some chat

Hardy Woly

WBO COG4 21-1

named 18

11-4-92