

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	☒
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

OCT 10 1980

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

CLERK OF THE COMMISSION
SANTA FE

59. Indicate Type of Lease

State ☒

Fee ☐

5. State Oil & Gas Lease No.

L-6240

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CEMENT OR PLUG BACK TO A DIFFERENT RESERVOIR.
SEE APPLICATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☒ GAS WELL ☐ C02 OTHER-	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Form or Lease Name State FF
3. Address of Operator P. O. Box 68 Hobbs, NM 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>E</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>36</u> TOWNSHIP <u>22-N</u> RANGE <u>32-E</u> NMPM.	10. Field and Pool, or Wildcat Und. Tubb
15. Elevation (Show whether DF, RT, GR, etc.) 4668 RDB	12. County Union

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to cement behind 4-1/2" production casing per the following procedure:

Kill well. Pull tubing and packer. Set a retrievable bridge plug at 2000' and cap with 10' sand. Run pipe recovery log to determine cement top. Perforate 4-1/2" casing 20' above top of cement. Run tubing and packer. Set packer 300' above perfs. Establish circulation. Pump 16 bbls. colored dye. Pump sufficient Class C cement to circulate. WOC. Pull tubing and packer. Pull bridge plug. Run tubing and packer.

0+2-NMOCD, SF 1-Hou 1-Susp 1-LBG

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bob Davis

TITLE Admin. Analyst

DATE 10-8-80

APPROVED BY Carl Heug

TITLE SENIOR PERFORMING ENGINEER

DATE 10/10/80

CONDITIONS OF APPROVAL, IF ANY: