

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Frontier Field Services, LLC	Contact John Prentiss	
Address 65 Mercado Street, Suite 250, Durango, CO 81301	Telephone No. 575-676-3528	
Facility Name Anderson Ranch 8" Lateral	Facility Type Condensate transport line	
Surface Owner Frontier Field Services, LLC	Mineral Owner	API No. N/A

LOCATION OF RELEASE

Unit Letter	Section 5	Township 17S	Range 32E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
-------------	------------------	---------------------	------------------	---------------	------------------	---------------	----------------	-------------------

Latitude **32.8560794 N** Longitudes **-103.7830705 W**

NATURE OF RELEASE

Type of Release Historic LOPC of condensate from buried pipeline	Volume of Release Estimated 20bbl subsurface	Volume Recovered: >5bbl recovered from Sub-surface. Excavation underway.
Source of Release Historic pinhole leak discovered in buried heavy condensate pipeline	Date and Hour of Occurrence Historic	Date and Hour of Discovery 6/01/2015
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jones Kellie Environmental Specialist, District 1	
By Whom? Harley Everhart	Date and Hour 6/1/15 @10:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		

RECEIVED

By OCD District 1 at 2:52 pm, Jun 01, 2015


Describe Cause of Problem and Remedial Action Taken.*

- On 4/30/2015, Frontier Field Services discovered a historic release along the Anderson Ranch Pipeline 8" Lateral. Frontier estimated the release not to exceed 5bbl; therefore, there were no notifications to NMOCD.
- On 4/30/2015, Excavation commenced to restore the integrity of the pipeline and prepare for the remediation process.
- From 5/1/2015 to 5/29/2015, the remediation project was delayed due to several massive rainfalls which prevented heavy equipment from entering the remediation area.
- On 6/01/2015, during the remediation process, Frontier estimated the subsurface release to exceed 5bbl and made prompt notifications to NMOCD.
- On 6/1/2015, Excavation has commenced to delineate and remove contaminated soils to an OCD approved location.

Describe Area Affected and Cleanup Action Taken.*

Once excavation has uncovered the pipeline, problem areas will be identified and repaired. Excavation will continue until TPH, BTEX, and Benzene are below the levels outlined in "NMOCD Guidelines for Remediation of Leaks, Spills, and Releases". Impacted soils will be transported to an OCD approved facility for disposal and the area will be backfilled with clean soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Harley Everhart		Approved by Environmental Specialist: 	
Title: EHS Technician III		Approval Date: 06/01/2015	Expiration Date: 09/01/2015
E-mail Address: heverhart@akaenergy.com		Conditions of Approval: Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.	
Date: 06/01/2015 Phone: 575.513.4922		Attached <input type="checkbox"/> 1RP-3656	

* Attach Additional Sheets If Necessary

pKJ1515255548
nKJ1515255177