

Submit 3 Copies To Appropriate District Office

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-025-06041

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name:

L. Van Etten

1. Type of Well:
Oil Well Gas Well Other

8. Well No.
1

2. Name of Operator
Chevron USA Inc

9. Pool name or Wildcat
Eumont, Yates, 7 Rvrs, Queen

3. Address of Operator
15 Smith Rd, Midland, TX, 79705

4. Well Location
Unit Letter L : 1980 feet from the South line and 660 feet from the West line
Section 9 Township 20-S Range 37-E NMPM Lea County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK PLUG AND ABANDON
TEMPORARILY ABANDON CHANGE PLANS
PULL OR ALTER CASING MULTIPLE COMPLETION
OTHER:

SUBSEQUENT REPORT OF:
REMEDIAL WORK ALTERING CASING
COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
CASING TEST AND CEMENT JOB
OTHER: Replug

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

- 1. Tag 7" CIBP at 3240, spot 25sx, plug from 3240-3140 (Eumont, Yates, 7 Rvrs, Queen) Tag at 3113.
- 2. Displace hole w/MLF 9.5# Brine w/25# gel P/BBL.
- 3. Perf 4 holes at 2700, unable to sqz, spot 100sx, plug from 2700-2300, Tag at 2174 (9 5/8 Shoe, Yates, B-Salt).
- 4. Perf 4 holes at 1300, sqz 55 sx from 1300-1200 (T-Salt) Tag at 1134.
- 5. Perf 4 holes at 300, Circ cmt from 300-Surf w/365sx, 7 x 9 5/8 x 13 csg (13" Shoe) Tag at Surf.
- 6. Install dry hole marker 4-29-04.

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Field Supervisor/Sunset DATE 4/29/04

Type or print name Jimmy Bagley Telephone No. (432) 561-8600

APPROVED BY [Signature] TITLE FIELD REPRESENTATIVE II/STAFF MANAGER DATE MAY 14 2004

Conditions of approval, if any: