## **CONDITIONS OF APPROVAL**

API#	Operator	Well name & Number
30-025-	MESQUITE SWD INC	PADUCA SWD # 001Y

Applicable conditions of approval marked with XXXXXX

## Administrative Orders Required

Completion & Production

XXXXXXX XXXXXXX

XXXXXX	Will require administrative order for SWD prior to placing the well on injection
Other wells	
Orilling	
XXXXXXX	Once the well is spud, to prevent ground water contamination through whole or partial conduits from the surface, the operator shall drill without interruption through the fresh water zone or zones and shall immediately set in cement the water protection string
Casing	
XXXXXX	SURFACE & INTERNEMIATE(1) CASING - Cement must circulate to surface
XXXXXX	PRODUCTION CASING - Cement must circulate to surface
XXXXXX	LINER - Top of Cement must come to top of liner
XXXXXXX	If cement does not circulate to surface, must run temperature survey or other log to determine top of cement  South Area
XXXXXXX	Surface casing must be set 25' below top of Rustler Anhydrite in order to seal off protectable water
Pits	
XXXXXX	If using a pit for drilling and completions, must have an approved pit form prior to spudding the well

Must notify Hobbs OCD office prior to conducting MIT (575) 393-6161 ext. 114

Must conduct MIT prior to any injection