CONDITIONS OF APPROVAL

API#	Operator	Well name & Number
30-025-46236	MEWBOURNE	Cuttroat 7 B2PA State Com 001H

Applicable conditions of approval marked with XXXXXX

Drilling

XXXXXXX	Once the well is spud, to prevent ground water contamination through whole or partial conduits from the surface, the operator shall drill without interruption through the fresh water zone or zones and shall immediately set in cement the water protection string

Casing

XXXXXXX	SURFACE & INTERNEMIATE(1) CASING - Cement must circulate to surface
XXXXXXX	PRODUCTION CASING - Cement must tie back into intermediate casing
XXXXXXX	If cement does not circulate to surface, must run temperature survey or other log to determine top of cement
XXXXXX	Surface casing must be set 25' below top of Rustler Anhydrite in order to seal off protectable water

Lost Circulation

XXXXXXX	Must notify OCD Hobbs Office if lost circulation is encountered at 575-370-3186

Water flows

XXXXXXX	Must notify OCD Hobbs Office of any water flow in the Salado formation at 575-370-3186. Report depth
	and flow rate.

Stage Tool

XXXXXXX	If stage tool was not part of original drilling plan must notify OCD Hobbs Office prior to running Stage Tool at 575-370-3186
XXXXXXX	
XXXXXXX	When using a Stage Tool on Intermediate or Production Casing Stage must be a minimum of 50 feet below previous casing shoe.

Completion & Production

XXXXXXX	Will require a directional survey with the C-104