
Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103
Office District I – (575) 393-6161 Energy, Minerals and Natural Resources		Revised August 1, 2011
District I – (575) 393-6161 Energy, Wilherars and Natural Resources - 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 7848-1283 OCD OIL CONSERVATION DIVISION		WELL API NO. 30-025-39746
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Lease
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 Santa Fe, NM 87505		STATE X FEE
District IV – (505) 476-3460	Santa Fe, NM 8/303	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	EIVED	E-9713
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		7. Lease Name or Unit Agreement Name PEDRO 11 STATE
PROPOSALS.)		8. Well Number
1. Type of Well: Oil Well X Gas W	Yell Other	1 O OCRID Mussland
2. Name of Operator MANZANO, LLC		9. OGRID Number 231429
3. Address of Operator P.O.BOX 2107, ROSWELL, NM 88202-	-2107	10. Pool name or Wildcat San Andres MESCALERO UPPER PENN NORTH
4. Well Location		
Unit Letter F: 2025 feet from the NORTH line and 1985 feet from the WEST line		
Section 11 Township 10S Range 32E NMPM LEA County		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
4269' GL		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK		· —
TEMPORARILY ABANDON		
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ CASING/CEMENT JOB ☐ DOWNHOLE COMMINGLE ☐		
DOWNHOLE COMMINGLE		·
OTHER:	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE-RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
proposed completion of recompletion.		
9/20/12 RIH w/CCL and CIBP. set CIBP @ 3936		
9/25/12 MIRU Scientific Drilling. RIH w/wireline and orient whipstock @ 39.27 degrees. Set whipstock on		
CIBP @ 3936' w/4k. Start milling on casing. Milled for 15min before cut hole in the casing		
9/26/12 Drilled 125' of new formation. RIH w/ Packer Plus Port system (details below), and 5 ½" hanger		
to 3916'. Set Perma Plus packer at 3916', open hole packer at 4018', 2 nd open hole packer at 4059'		
and pump out sub at 4060'. 10/0/12 MIRLI Polyan Hyphas A sidiging Promod 2 000sl of 159/ NIEEE asid at a rate of 2RRM & at		
MIRU Baker Hughes Acidizing. Pumped 2,000gl of 15% NEFE acid at a rate of 2BPM & at average treating pressure of 1722psi.		
average treating pres	ssure of 1722psi.	
10/10/12-10/19/12 Swab test with 1-5% oil cut and 30-50 BWPD. Rig down pulling unit and get plugging		
orders.		
Spud Date: 5-31-2010	Rig Release Date: 7-06-2010)
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
Thereby certify that the information above to true and complete to the cost of my knowledge and certain		
$// \sim 0$	0 0	
SIGNATURE Can Legica	uleTITLE_OTHER	DATE 11/12/2012
Type or print namePAUL RAGSDALE		
For State Use Only		
APPROVED BY TITLE DIST. MGB DATE //- 15-2017		
Conditions of Approval y): NOV 2.8 2012 Chin		

MANZANG - LLC WELLBORE Diagram (as of 11/15/12)



Cement 2nd Stage w/1400sx Hall Lite
Tail in w/250sx Prem Plus - Circ 27sx to pits