OCD Hobbs Form 3160-5 UNITED STATES (August 2007) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT					FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010 5. Lease Serial No.				
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					NM-89174 6. If Indian, Allottee or Tribe Name				
SUBMIT IN TRIPLICATE – Other instructions on page 2.					7. If Unit of CA/Agreement, Name and/or No.				
1. Type of Well ☐ Gas Well ☐ Other					8. Well Name and No. Zia 6 Federal #1				
2. Name of Operator Devon Energy Production Co., LP					9. API Well No. 30-025-32505				
3a. Address 333 W Sheridan Avenue, Oklahoma City, OK 7	(include area code	<i>,</i>	10. Field and Pool or Exploratory Area						
405-552-4615 4. Location of Well ( <i>Footage, Sec., T.,R.,M., or Survey Description</i> ) 1980' FNL & 660' FEL; Sec 6-T24S-R32E					11. Country or Parish, State Lea, NM				
12. CHE0	CK THE APPROPRIATE BC	X(ES) TO IND	CATE NATURE	OF NOTIC	E, REPORT OR OTH	IER DATA			
TYPE OF SUBMISSION	PE OF SUBMISSION TYPE OF A					TION			
Notice of Intent	Acidize	Deepe	n ire Treat		ction (Start/Resume) Water Shut-Off mation Well Integrity				
Subsequent Report	Casing Repair		Construction	_	mplete Other				
Final Abandonment Notice	Change Plans Convert to Injection	₽lug a	nd Abandon Back		porarily Abandon er Disposal				
following completion of the invol- testing has been completed. Final determined that the site is ready for Wellbore Plugged & Abandoned 1. 2/6/13-MIRU workover rig. POC 2. TIH w/2-7/8" tbg. Tagged @ 5,99 3. Spot 40 sx cement @ 4,600'. Ta 4. Cut 5-1/2" casing @ 4,200'. POC 5. Spot 40 sx cement @ 1,278'. Ta 6. Spot 40 sx cement @ 1,278'. Ta 6. Spot 40 sx cement @ 648'. Tagg 7. Circulate 50 sx cement from 126' 8. Cut wellhead off and set dry hole	Abandonment Notices must or final inspection.) DH w/2-7/8" production tubi 55'. Spot 35 sx cement . T gged TOC @ 4,271'. DH w/5-1/2" casing. Spot 5 gged TOC @ 1,150'. ged TOC @ 528'. to surface. Top out casin	be filed only afte ng. RIH w/tubi agged TOC @ 50 sx cement @ g.	ng and packer to 5,688'. Displace 9,4,271'. Tagged	, including r 5,950'. P e hole with d TOC @ 4	eclamation, have bee umped 450 sx cen mud. 1,009'.	en completed and the o	perator has		
		MOBBS OC MAR 2 2 21		Accepted as to plugging of the well hore. Liability under bond is retained until Surface restoration is completed.					
	RECEIVED								
<ol> <li>I hereby certify that the foregoing is t Name (Printed/Typed)</li> </ol>									
Ronnie Slack			Title Operations Technician						
Signature Rommie Slack			Date 3-5-13 ACCEPTED FOR RECORD						
	THIS SPACE	FOR FEDE	RAL OR STA	TE OFF			7		
Approved by					MA	R 2 0 2013			
Conditions of approval, if any, are attached that the applicant holds legal or equitable t entitle the applicant to conduct operations				E LAND MANACE					
Title 18 U.S.C. Section 1001 and Title 19 fictitious or fraudulent statements or repre-	U.S.C. Section 1212, make in a sentation as to any matter with	crime for any per	son knowingly and	willfully to	make to any department		ed States any false,		
(Instructions on page 2)				N.r.		APR O	2 2013		

۳.

4

