Submit 3 Copies To Appropriate District State of New Mexico	Form C-103 May 27, 2004
District I 1625 N. French Dr., Hobbs, NM 88240 Energy, Minerals and Natural Resources	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 8821 OBBS OLD CONSERVATION DIVISION District III 1220 South St. Francis Dr.	30-025-31020 5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	West Pearl Queen Unit
1. Type of Well: Oil Well Gas Well Other	8. Well Number 190
2. Name of Operator State of New Mexico formerly Xeric Oil & Gas Corporation	
3. Address of Operator 1625 N. French Drive Hobbs NM 88240	10. Pool name or Wildcat Pearl Queen
4. Well Location	
Unit Letter I :1440feet from theSouthline and _90feet from the _Eastline Section 29 Township 19S Range 35E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
Pit or Below-grade Tank Application or Closure Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB	
OTHER:	
 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 	
3/5/13Pulled 134 rods out of well, pulled 142 jts tbg out of well. RIH w/ gauge ring & Tag @ 4520'. Set CIBP @ 4510'.	
3/6/13Spot 25 sxs cmt @ 4490'	
Spot 25 sxs cmt @ 3407' Spot 25 sxs cmt @ 1815'	
Brought well to surface from 450' w/ 45 sxs cmt.	Plugging of well bore only.
which may be	found a control well Plugging)
Forms, www.co	mnrd.state.nm.us/ocd.
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below- grade tank has been/will be constructed or closed according to NMOCD guidelines \square , a general permit \square or an (attached) alternative OCD-approved plan \square .	
SIGNATURE	(Basic Energy Services) DATE _3/11/13
Type or print name: Greg Bryant E-mail address: For State Use Only Image: Compare the second	Telephone No. 432-563-3355
APPROVED BY	E DATE 3-21-2013
Conditions of Approval (if any):	
	х

í