Office	TICM MICK	aco	F0(m C-105
District I – (575) 393-6161 Energy, Minerals	s and Natura	al Resources	Revised August 1, 2011
1605 M Franch De Wahle MM 99240			WELL API NO.
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 Electrical III - (575) 748-1283 OIL CONSERVATION DIVISION		OTTOTON	30-025-05402
		· ·	5. Indicate Type of Lease
District III - (505) 334-6178 1220 South St. Francis Dr.		cis D r.	STATE x FEE
1000 Rio Brazos Rd., Aztec, NM 87410 [107 & 8 dd \ Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		22566
87505			22300
SUNDRY NOTICES AND REPORTS O	N WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEE		G BACK TO A	State V
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FOR	RM C-101) FOR	RSUCH	
PROPOSALS.)			8. Well Number#1
1. Type of Well: Oil Well x Gas Well Other			
2. Name of Operator		9. OGRID Number #	
Vanguard Permian LLC		258356	
3. Address of Operator		10. Pool name or Wildcat	
P. O Box 1570 Eunice, New Mexico 88231		Lovington Paddock	
4. Well Location		· · · · · · · · · · · · · · · · · · ·	
	.1 310	A POPULATION OF THE POPULATION	1 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7
	om theNO	RTH	line and 660 feet from the
_Westline			
Section 5 Township	17S	Range 37E	NMPM LEA County
11. Elevation (Show w			
3813 DFT		,,	
3. 100.00 00 A 3 (10.00 00 00 00 00 00 00 00 00 00 00 00 00			The state of the s
10.01.1.1.7.7			
12. Check Appropriate Box to In	ndicate Na	iture of Notice,	Report or Other Data
MATINE OF MITCHETION TO	ř.	01.15	ACAUCUT BEBABT AS
NOTICE OF INTENTION TO:			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK X PLUG AND ABANDON	NLI	REMEDIAL WOR	K ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS		COMMENCE DRI	LLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL		CASING/CEMENT	r Job 🗍
DOWNHOLE COMMINGLE			
DOMANOEE OCIMINATORE	1		
	t t		
OTHER:		OTHER:	П
OTHER: 13 Describe proposed or completed operations. (Clearly)		OTHER:	d give pertinent dates including estimated date
13. Describe proposed or completed operations. (Clearl	ly state all pe	ertinent details, and	d give pertinent dates, including estimated date
 Describe proposed or completed operations. (Clearl of starting any proposed work). SEE RULE 19.15.7 	ly state all pe	ertinent details, and	d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearl	ly state all pe	ertinent details, and	d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearl of starting any proposed work). SEE RULE 19.15.7 proposed completion or recompletion. 	ly state all po 7.14 NMAC.	ertinent details, and For Multiple Cor	d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearl of starting any proposed work). SEE RULE 19.15.7 proposed completion or recompletion. Cement squeeze Lovington Paddock with 300 sxs of the complete of the comple	ly state all po 7.14 NMAC.	ertinent details, and For Multiple Cor	d give pertinent dates, including estimated date appletions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearl of starting any proposed work). SEE RULE 19.15.7 proposed completion or recompletion. Cement squeeze Lovington Paddock with 300 sxs of Drill out cement. 	ly state all po 7.14 NMAC.	ertinent details, and For Multiple Cor	d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearl of starting any proposed work). SEE RULE 19.15.7 proposed completion or recompletion. Cement squeeze Lovington Paddock with 300 sxs of Drill out cement. Log and perforate Lovington Abo 8100-8200'. 	ly state all pe 7.14 NMAC.	ertinent details, and For Multiple Cor ut.	d give pertinent dates, including estimated date appletions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearl of starting any proposed work). SEE RULE 19.15.7 proposed completion or recompletion. Cement squeeze Lovington Paddock with 300 sxs of Drill out cement. Log and perforate Lovington Abo 8100-8200'. Stimulate Abo with 2000 gals 15% nefe acid down? 	ly state all pe 7.14 NMAC.	ertinent details, and For Multiple Cor ut.	d give pertinent dates, including estimated date repletions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearl of starting any proposed work). SEE RULE 19.15.7 proposed completion or recompletion. Cement squeeze Lovington Paddock with 300 sxs of Drill out cement. Log and perforate Lovington Abo 8100-8200'. 	ly state all pe 7.14 NMAC.	ertinent details, and For Multiple Cor ut.	d give pertinent dates, including estimated date appletions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearl of starting any proposed work). SEE RULE 19.15.7 proposed completion or recompletion. Cement squeeze Lovington Paddock with 300 sxs of Drill out cement. Log and perforate Lovington Abo 8100-8200'. Stimulate Abo with 2000 gals 15% nefe acid down? 	ly state all pe 7.14 NMAC.	ertinent details, and For Multiple Cor ut.	d give pertinent dates, including estimated date appletions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearl of starting any proposed work). SEE RULE 19.15.7 proposed completion or recompletion. Cement squeeze Lovington Paddock with 300 sxs of Drill out cement. Log and perforate Lovington Abo 8100-8200'. Stimulate Abo with 2000 gals 15% nefe acid down? 	ly state all pe 7.14 NMAC.	ertinent details, and For Multiple Cor ut.	d give pertinent dates, including estimated date appletions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearl of starting any proposed work). SEE RULE 19.15.7 proposed completion or recompletion. Cement squeeze Lovington Paddock with 300 sxs of Drill out cement. Log and perforate Lovington Abo 8100-8200'. Stimulate Abo with 2000 gals 15% nefe acid down 25. Equip well to pump. 	rly state all pe 7.14 NMAC. class c cemer 2.7/8" tubin	ertinent details, and For Multiple Cor ut.	d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearl of starting any proposed work). SEE RULE 19.15.7 proposed completion or recompletion. Cement squeeze Lovington Paddock with 300 sxs of Drill out cement. Log and perforate Lovington Abo 8100-8200'. Stimulate Abo with 2000 gals 15% nefe acid down 25. Equip well to pump. 	ly state all pe 7.14 NMAC.	ertinent details, and For Multiple Cor ut.	d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearl of starting any proposed work). SEE RULE 19.15.7 proposed completion or recompletion. Cement squeeze Lovington Paddock with 300 sxs of Drill out cement. Log and perforate Lovington Abo 8100-8200'. Stimulate Abo with 2000 gals 15% nefe acid down 25. Equip well to pump. 	rly state all pe 7.14 NMAC. class c cemer 2.7/8" tubin	ertinent details, and For Multiple Cor ut.	d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearl of starting any proposed work). SEE RULE 19.15.7 proposed completion or recompletion. Cement squeeze Lovington Paddock with 300 sxs of 2. Drill out cement. Log and perforate Lovington Abo 8100-8200'. Stimulate Abo with 2000 gals 15% nefe acid down 25. Equip well to pump. Spud Date: Rig	rly state all pe 7.14 NMAC. class c cemer 2 7/8" tubin g Release	ertinent details, and For Multiple Cor nt.	npletions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearl of starting any proposed work). SEE RULE 19.15.7 proposed completion or recompletion. Cement squeeze Lovington Paddock with 300 sxs of Drill out cement. Log and perforate Lovington Abo 8100-8200'. Stimulate Abo with 2000 gals 15% nefe acid down 25. Equip well to pump. 	rly state all pe 7.14 NMAC. class c cemer 2 7/8" tubin g Release	ertinent details, and For Multiple Cor nt.	npletions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearl of starting any proposed work). SEE RULE 19.15.7 proposed completion or recompletion. Cement squeeze Lovington Paddock with 300 sxs of 2. Drill out cement. Log and perforate Lovington Abo 8100-8200'. Stimulate Abo with 2000 gals 15% nefe acid down 25. Equip well to pump. Spud Date: Rig	rly state all pe 7.14 NMAC. class c cemer 2 7/8" tubin g Release	ertinent details, and For Multiple Cor nt.	npletions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearl of starting any proposed work). SEE RULE 19.15.7 proposed completion or recompletion. Cement squeeze Lovington Paddock with 300 sxs of 2. Drill out cement. Log and perforate Lovington Abo 8100-8200'. Stimulate Abo with 2000 gals 15% nefe acid down 25. Equip well to pump. Spud Date: Rig	rly state all pe 7.14 NMAC. class c cemer 2 7/8" tubin g Release	ertinent details, and For Multiple Cor nt.	npletions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearl of starting any proposed work). SEE RULE 19.15.7 proposed completion or recompletion. Cement squeeze Lovington Paddock with 300 sxs of 2. Drill out cement. Log and perforate Lovington Abo 8100-8200'. Stimulate Abo with 2000 gals 15% nefe acid down 25. Equip well to pump. Spud Date: Rig	rly state all pe 7.14 NMAC. class c cemer 2 7/8" tubin g Release	ertinent details, and For Multiple Cor nt.	npletions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearl of starting any proposed work). SEE RULE 19.15.7 proposed completion or recompletion. Cement squeeze Lovington Paddock with 300 sxs of 2. Drill out cement. Log and perforate Lovington Abo 8100-8200'. Stimulate Abo with 2000 gals 15% nefe acid down 25. Equip well to pump. Spud Date: Rig	rly state all pe 7.14 NMAC. class c cemer 2 7/8" tubin g Release	ertinent details, and For Multiple Cor nt. ng.	e and belief.
13. Describe proposed or completed operations. (Clearl of starting any proposed work). SEE RULE 19.15.7 proposed completion or recompletion. 1. Cement squeeze Lovington Paddock with 300 sxs of 2. Drill out cement. 3. Log and perforate Lovington Abo 8100-8200'. 4. Stimulate Abo with 2000 gals 15% nefe acid down 25. Equip well to pump. Spud Date: Rig	rly state all per 7.14 NMAC. class c cemer 2.7/8" tubin g Release	ertinent details, and For Multiple Cor nt. ng.	e and belief.
13. Describe proposed or completed operations. (Clearl of starting any proposed work). SEE RULE 19.15.7 proposed completion or recompletion. 1. Cement squeeze Lovington Paddock with 300 sxs of 2. Drill out cement. 3. Log and perforate Lovington Abo 8100-8200'. 4. Stimulate Abo with 2000 gals 15% nefe acid down 25. Equip well to pump. Spud Date: Rig	rly state all pe 7.14 NMAC. class c cemer 2 7/8" tubin g Release	ertinent details, and For Multiple Cor nt. ng.	npletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 19.15.7 proposed completion or recompletion. 1. Cement squeeze Lovington Paddock with 300 sxs of 2. Drill out cement. 3. Log and perforate Lovington Abo 8100-8200'. 4. Stimulate Abo with 2000 gals 15% nefe acid down 25. Equip well to pump. Spud Date: Rig	ry state all per 7.14 NMAC. class c cemer 2.7/8" tubin Release ete to the bes	ertinent details, and For Multiple Cornt. Int.	e and belief. DATE 4-16-2013
13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 19.15.7 proposed completion or recompletion. 1. Cement squeeze Lovington Paddock with 300 sxs of 2. Drill out cement. 3. Log and perforate Lovington Abo 8100-8200'. 4. Stimulate Abo with 2000 gals 15% nefe acid down 2. 5. Equip well to pump. Spud Date: Rig I hereby certify that the information above is true and complete the structure of the start of the st	ry state all per 7.14 NMAC. class c cemer 2.7/8" tubin Release ete to the bes	ertinent details, and For Multiple Cornt. Int.	e and belief.
13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 19.15.7 proposed completion or recompletion. 1. Cement squeeze Lovington Paddock with 300 sxs of 2. Drill out cement. 3. Log and perforate Lovington Abo 8100-8200'. 4. Stimulate Abo with 2000 gals 15% nefe acid down 25. Equip well to pump. Spud Date: Rig	rly state all per 7.14 NMAC. class c cemer 2 7/8" tubin g Release cte to the best cte to the best commail address:	ertinent details, and For Multiple Cornt. Int.	e and belief. DATE 4-16-2013 WAR LLC GPHONE: 390-4611
13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 19.15.7 proposed completion or recompletion. 1. Cement squeeze Lovington Paddock with 300 sxs of 2. Drill out cement. 3. Log and perforate Lovington Abo 8100-8200'. 4. Stimulate Abo with 2000 gals 15% nefe acid down 2. 5. Equip well to pump. Spud Date: Rig I hereby certify that the information above is true and complete the print name with a superior print name. The state Use Only	ry state all per 7.14 NMAC. class c cemer 2 7/8" tubin g Release lete to the best patricular address:	ertinent details, and For Multiple Cornt. Int.	e and belief. DATE 4-16-2013 WAR LLC GPHONE: 390-4611 MAY 0 1 2012
13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 19.15.7 proposed completion or recompletion. 1. Cement squeeze Lovington Paddock with 300 sxs of 2. Drill out cement. 3. Log and perforate Lovington Abo 8100-8200'. 4. Stimulate Abo with 2000 gals 15% nefe acid down 2. 5. Equip well to pump. Spud Date: Rig I hereby certify that the information above is true and complete the proposed of the proposed work). SIGNATURE True Type or print name Make Jove's E-m. For State Use Only APPROVED BY: TITE	ry state all per 7.14 NMAC. class c cemer 2 7/8" tubin g Release lete to the best patricular address:	ertinent details, and For Multiple Cornt. Int.	e and belief. DATE 4-16-2013 WAR LLC GPHONE: 390-4611
13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 19.15.7 proposed completion or recompletion. 1. Cement squeeze Lovington Paddock with 300 sxs of 2. Drill out cement. 3. Log and perforate Lovington Abo 8100-8200'. 4. Stimulate Abo with 2000 gals 15% nefe acid down 2. 5. Equip well to pump. Spud Date: Rig I hereby certify that the information above is true and complete the print name with a superior print name. The state Use Only	ry state all per 7.14 NMAC. class c cemer 2 7/8" tubin g Release lete to the best patricular address:	ertinent details, and For Multiple Cornt. Int.	e and belief. DATE 4-16-2013 WAR LLC GPHONE: 390-4611 MAY 0 1 2012
13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 19.15.7 proposed completion or recompletion. 1. Cement squeeze Lovington Paddock with 300 sxs of 2. Drill out cement. 3. Log and perforate Lovington Abo 8100-8200'. 4. Stimulate Abo with 2000 gals 15% nefe acid down 2. Equip well to pump. Spud Date: Rig I hereby certify that the information above is true and complete the state Use Only APPROVED BY: TITE Type or print name For State Use Only TITE Type OT PROVED BY: TITE Type of Print name TITE Type OT Print name Type O	ry state all per 7.14 NMAC. class c cemer 2 7/8" tubin g Release lete to the best patricular address:	ertinent details, and For Multiple Cornt. Int.	e and belief. DATE 4-16-2013 WAR LLC GPHONE: 390-4611 MAY 0 1 2012