# HOBBS OCD

MAY 0.7 2013

| Submit I Copy To Appropriate District Office State of New Mexic  |  |
|--|--|
| District   RECEIVED Energy, Minerals and Natural   | Resources October 13, 2009 WELL API NO.  |
| 1625 N. French Dr., Hobbs, NM 88240  District II  1301 W. Grand Ave. Artesia NM 88210  OIL CONSERVATION DI | 20.025.40048   |
| 1301 W. Grand Ave., Artesia, NM 88210  District III  1220 South St. Francis                                | 5. Indicate Type of Lease  |
| 1000 Rio Brazos Rd., Aztec, NM 87410   | JIAIE M LEE L  |
| District IV 1220 S. St. Francis Dr., Santa Fe, NM  | 6. State Off & Gas Lease No.   |
| 87505<br>SUNDRY NOTICES AND REPORTS ON WELLS   | 7. Lease Name or Unit Agreement Name   |
| (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG B  | BACK TO A  |
| DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SI PROPOSALS.)                          | UCH Corazon State Unit  8. Well Number   |
| 1. Type of Well: Oil Well Gas Well Other   | 6Н   |
| 2. Name of Operator  | 9. OGRID Number  |
| COG Operating LLC  | 10. Pool name or Wildcat   |
| 3. Address of Operator<br>2208 W. Main Street, Artesia, NM 88210   | Wildcat; Bone Spring   |
| 4. Well Location   |  |
|  | line and 330 feet from the West line   |
| Section 10 Township 21S Rar  |  |
| 11. Elevation (Show whether DR, RK   | (B, RT, GR, etc.)  |
| 3834'  |  |
| TEMPORARILY ABANDON  | tiple Completions: Attach wellbore diagram of proposed   |
| pud Date: Rig Release Date:  |  |
| hereby certify that the information above is true and complete to the best of                              | of my knowledge and belief.  |
| IGNATURE MOLE Regula   | The state of the s |
|  | atory Analyst DATE: 5/6/2013   |
| ype or print name: <u>Mayte Reyes</u> E-mail address: r  | mreyes1@conchoresources.com PHONE: (575) 748-6945  |
|  | leum Engineer DATE MAY 0 7 2   |
| Conditions of Approval (If any):   | DATE TITLE   |

## **Corazon State Unit 6H**

## **Casing and Cement**

| String       | Hole Size | Csg OD  | PPF _   | Depth  | _ Sx Cement | TOC |
|--------------|-----------|---------|---------|--------|-------------|-----|
| Surface      | 17-1/2"   | 13-3/8" | 54.5#   | 1940'  | 1270        | 0'  |
| Intermediate | 12-1/4"   | 9-5/8"  | 36#/40# | 5560'  | 460/1690    | 0'  |
| Production   | 7-7/8"    | 5-1/2"  | 17#     | 16249' | 2385        | 0'  |

#### Well Plan

Drill 17-1/2" hole to ~1940' w/ fresh water spud mud. Run 13-3/8" 54.5# J55 STC casing to TD and cement to surface in one stage. Will use 1" tubing and Class C w/ 2% CaCl<sub>2</sub> to cement to surface, if necessary.

Drill 12-1/4" hole to ~5560' with saturated brine water. If losses occur in the Reef, will switch to fresh water to interval TD. Run 9-5/8" 36# J55 & 40# N80 BTC casing to TD with a DV tool placed ~ 100' above the Reef. Plan to circulate cement on both stages.

Drill 7-7/8" vertical hole, curve and lateral to 16249' with cut brine. Run 5-1/2" 17# P110 LTC casing to TD and cement to surface in one stage.

### **Well Control**

After setting 13-3/8" casing and installing 2000 psi casing head, NU Shaeffer 3000 psi annular BOP. Test annular to 1500 psi and other BOP equipment to 2000 with clear fluid using 3<sup>rd</sup> party testers.

After setting 9-5/8" casing and installing 3000 psi casing spool, NU Shaeffer 3000 psi double ram BOP and Shaeffer 3000 psi annular BOP. Test annular to 1500 psi and other BOP equipment to 3000 with clear fluid using 3<sup>rd</sup> party testers.