State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Dhergy, winierais and reacting bep	Revised 5-27-2004				
FILE IN TRIPLICATE OIL CONSERVATION DIVISIO					
DISTRICT I 1220 South St. Francis Dr. 1625 N. French Dr., Hobbs, NM 88240 HOBBS OCD Santa Fe, NM 87505	WELL API NO. 30-025-29196				
DISTRICT II	5. Indicate Type of Lease				
1301 W. Grand Ave, Artesia, NM 88210 MAY 1 6 2013	STATE FEE X				
Digitider in	6. State Oil & Gas Lease No.				
1000 Rio Brazos Rd, Aztec, NM 87410					
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA) Unit				
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	Section 19				
1. Type of Well:	8. Well No. 422				
Oil Well Gas Well Other Temporarily Abandoned 2. Name of Operator	9. OGRID No. 157984				
Occidental Permian Ltd.	9. OOKID NO. 137984				
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)				
HCR 1 Box 90 Denver City, TX 79323					
4. Well Location					
Unit Letter H 2495 Feet From The North 119	Feet From The Line				
Section 19 Township 18-S Range	38-E NMPM Lea County				
11. Elevation (Show whether DF, RKB, RT GR, etc.) 3653' GL					
Pit or Below-grade Tank Application or Closure					
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water					
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material					
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING				
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI	NG OPNS. PLUG & ABANDONMENT				
PULL OR ALTER CASING Multiple Completion CASING TEST AND C					
OTHER: TA Status extension request / YR. X OTHER:					
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertiner proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of pro 					

Run MI test to gain extension on temporary abandoned status.

Condition of Approval: Notify OCD Hobbs office 24 hours prior to running MIT Test & Chart

I hereby certify that the information above is true and c constructed or	complete to the best of my know	edge and belief. I further certify that any pit	or below-grade tank ha	s been/will be
closed according to NMOCD guidelines	, a general permit	or an (attached) alternative OCD-ap	proved	
Mand. Ad	Jul _	plan		
SIGNATURE IN UNDER CL	PINNON	TITLE Administrative Associate	DATE	05/15/2013
TYPE OR PRINT NAME Mendy A Johnson	E-mail address:	mendy_johnson@oxy.com	TELEPHONE NO.	806-592-6280
For State Use Only		5/20		
APPROVED BY	h	_ TITLE] JIST- MAR	DATE	5-20-2017
CONDITIONS OF APPROVAL IF ANY:		, C		- 7
			MAY 21	2013 1
				and the second
			and the second	