## HOBBS OCD

Form 3160-5

(March 2012)

## **UNITED STATES**

DEPARTMENT OF THE INTERIOR

1625 N. French Drive Bolbs, NM M

New Merico Off Conservation Division, Main

OMB No.	PROVED
OMB No.	1004-0137

ARORM.	APPROVED to 1004-0137		
APPENMR N	Jo 100	04-013	7

September 2017		
OMB No.	1004-01	37
Evnires: Oc	toher 31	201

	expires.	October 31, 2014
5. Lease Serial No. NM-03844		an the same parties of the same of the sam
5 505 II 111	- CO :1	

MAY 1 7 2013 BUR	EAU OF LAND MANAGEMEN	<u> </u>	5. Lease Serial No. NM-03844	The grant transfer any and principles.
REG5 YET use this f	OTICES AND REPORTS ON Norm for proposals to drill or t Use Form 3160-3 (APD) for su	o re-enter an	6. If Indian, Allottee o	r Tribe Name
SUBMIT	FIN TRIPLICATE – Other instructions (	on page 2.	7. If Unit of CA/Agree	ement, Name and/or No.
1. Type of Well	1		0 W-11 N 1 N-	
Oil Well Gas W	Vell X Other		8. Well Name and No. ROCK QUEEN	N UNIT #29
2. Name of Operator Celero Energy II, LP			9. API Well No. 30-005-00883	
3a. Address	3b. Phone No	o. (include area coa	de) 10. Field and Pool or I	Exploratory Area
400 W. Illinois, Ste. 1601 N		)686-1883	CAPROCK; Q	
4. Location of Well (Footage, Sec., T.,) 330' N 330' <b>S</b>	R.,M., or Survey Description)		11. County or Parish,	
UL: A, Sec: 27, T: 13S, R:	31E /		CHAVES	NM
12. CHEC	K THE APPROPRIATE BOX(ES) TO IN	DICATE NATURE	E OF NOTICE, REPORT OR OTH	ER DATA
TYPE OF SUBMISSION		TYI	PE OF ACTION	
X Notice of Intent	_ =	epen	Production (Start/Resume)	Water Shut-Off
		cture Treat	Reclamation	Well Integrity Workover  Nother Convert from
Subsequent Report		w Construction g and Abandon	Recomplete Temporarily Abandon	X Other Convert from monitor to
Final Abandonment Notice	· · · · · · · · · · · · · · · · · · ·	g and Abandon g Back	Water Disposal	producing well
3. PU workstring and RIH t 4. RIH with production pack tubinghead, and NU BOPE 5. Run 2-3/8", 4.7#, J-55, 8 6. Circulate hole with inhibi ND BOPE and install top fla	d ND well head, NU BOPE, and o TD w/ bit, 1-DC, gauge string ker w/plug in place if necessary	mill, 1-DC, an and recover k ion tubing and test casing. S e. e well on prod	nd gauge string mill. Circuitil fluid. POOH, ND BOP 3/8" cap strings. Space out, land tubing, an uction.	E, install CO2 d test cap strings.
		APPR ENDIR	OVED FOR <u>3                                    </u>	NTH PERIOD
•				
4. I hereby certify that the foregoing is to	ue and correct. Name (Printed/Typed)			·
Lisa Hunt		Title Regula	tory Analyst	•
Signature Lisa	Hunt	Date 05/03/2	013	
	THIS SPACE FOR FED	ERAL OR STA	ATE OFFICE USE	
	R. GLASS	PETF	ROLEUM ENGINEER	Date MAY 1 4 2013
	<ul> <li>Approval of this notice does not warrant or tle to those rights in the subject lease which whereon</li> </ul>	certify vould Office R	OSWELL FIELD OFFICE	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements of representation and any makes within its jurisdiction.

entitle the applicant to conduct operations thereon.