Submit 1 Copy To Appropriate District Office	State of New Mexico			Form C-103	
<u>District 1</u> – (575) 393-6161				Revised August 1, 2011 WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283				30-025-40410	
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION			5. Indicate Type of J	
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.			STATE 1	
District IV - (505) 476-3460	Santa Fe, NM 87505			6. State Oil & Gas L	ease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505					
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name or Ur	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				Red Hills West 16 St	ate
PROPOSALS.)				8. Well Number 1F	
1. Type of Well: Oil Well	Gas Well 🗌 Other	H	OBBS OCD		
2. Name of Operator				9. OGRID Number 217817	
ConocoPhillips Company 3. Address of Operator	JUN 2 8 2013			10. Pool name or Wildcat	
P.O. Box 51810 Midland, Tx 797	10			Bone Spring; Shale J	
4. Well Location	<u> </u>		RECEIVED		
Unit Letter D	: 180 feet from the	North		640 feet from the	he West line
Section 16	Township 20	6S Ra	nge 32E		County Lea
1	11. Elevation (Show whe				
3200 GR					
		_			
12. Check	Appropriate Box to Ind	licate Na	ature of Notice,	Report or Other Da	ita
				•	
	NTENTION TO:	_		SEQUENT REPC	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING					
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB					AND A
PULL OR ALTER CASING			CASING/CEWEN		
	J				
OTHER:			OTHER:		
13. Describe proposed or com					
	vork). SEE RULE 19.15.7.1	4 NMAC	C. For Multiple Co	npletions: Attach well	bore diagram of
proposed completion or recompletion. ConocoPhillips Company respectfully request to leave the current top of cement on the above well 5760 after the remediation work that					
was done on 6/13/13-6/20/13. We believe that the annulus is bridged somewhere above 5850 MD and most likely across the interval of					
5440-5560. COP believes that it is very unlikely that circulation from 5880' to a point 200' above the intermediate casing shoe can be					
established. An attempt to remediate the cement above the depths above was done on $6/19/13$ and was unable to establish circulation. The					
cement was pumped with no returns. We do not have any pressure on the annulus between the 7" production casing and the 9 5/8"					
intermediate casing.					
Steve Moore (COP) received verba	I permission from Paul Kau	tz (OCD)	on June 25, 2013 a	t 9.50am CST to leave	the coment as is on the
Steve Moore (COP) received verbal permission from Paul Kautz (OCD) on June 25, 2013 at 9:50am CST to leave the cement as is on the above well without further remediation.					
	<u> </u>		r 		
Spud Date:	Rig Re	elease Da	te.		
			L		
I hereby certify that the information	above is true and complete	to the be	st of my knowledg	e and belief	
		to the se			
SIGNATURE	TITLI	E <u>Sr</u>	. Regulatory		6/26/13
Type or print name Donna-Wi	lliams	loddmass	Donna.J.Wil	liams@	_{E:} 432–688–6943
Type or print name	E-mai	address:	_COP.com	PHON	E: 132-000-0943
- or blate Cot Only		~ -	-/ 100	-	
APPROVED BY:	Jahn TITLE		ST. MAR	DATE	7-1-2013
Conditions of Approval (if any);		Ý		·	