
State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	HÖBBS OOIL CONSERV	ATION DIVISION		,	
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240	1220 South	St. Francis Dr. NM 87505	WELL API NO. 30-025-23277		
<u>DISTRICT II</u>	001 2 2 2010		5. Indicate Type of Lease		
1301 W. Grand Ave, Artesia, NM 88210			STATE	FEE X	
DISTRICT III	RECEIVED		6. State Oil & Gas Lease No.		
1000 Rio Brazos Rd, Aztec, NM 87410					
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agree		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			North Hobbs (G/SA) Uni Section 28	Section 28	
1. Type of Well: Oil Well X	Gas Well Other		8. Well No. 132		
Name of Operator Occidental Permian Ltd.			9. OGRID No. 157984		
3. Address of Operator			10. Pool name or Wildcat	Hobbs (G/SA)	
HCR I Box 90 Denver City, I 4. Well Location	X 79323	A de solution and the second s			
Unit Letter L : 1880	Feet From The South	Line and 750	Feet From The West	_ Line	
Section 28	Township 18-S		8-E NMPM	Lea County	
	11. Elevation (Show whether DF, R 3649' GL	KB, RT GR, etc.)			
Pit or Below-grade Tank Application	or Closure				
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water					
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material					
The Billet Thickness init					
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ADANDON ALTERING CASING					
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT COMMENT COMMENTED TO THE PLUG & ABANDONMENT COMMENT COMMENTED TO THE PLUG & ABANDONMENT COMMENT CO				
PULL OR ALTER CASING	Multiple Completion CASING TEST AND CEMENT JOB				
OTHER:		OTHER: Convert to	ESP from Beam	X	
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. RUPU & RU. Remove pumping unit head. POOH and lay down rods and pump. ND wellhead/NU BOP. RIH w/bit. Tag @4275'. POOH w/bit. RIH w/ESP equipment set on 124 jts of 2-7/8" tubing. Intake set @4022' ND BOP/NU wellhead. RDPU & RU. Clean location and return well to production. 					
RUPU 09/20/2013 RDPU 09/25/2013					
I hereby certify that the information above	is true and complete to the best of my know	vledge and belief. I further cert	tify that any pit or below-grade tank	has been/will be	
constructed or closed according to NMOCD guideling	es , a general permit	or an (attached) alterna	tive OCD-approved	1	
		plan			
SIGNATURE / NUM	y Warmon	TITLE Administrati	ve Associate DAT	E 10/21/2013	
TYPE OR PRINT NAME Mendy A.	Johnson E-mail address:	mendy_johnson@oxy.co	om TELEPHONE NO	806-592-6280	
For State Use Only	9 41	2	/ 100		
APPROVED BY CONDITIONS OF APPROVAL IF ANY	yahr.	_ TITLE	<i>///</i> DA	40-23-2013	
OF MITHOUSE AND					
			OCT 2.3 2	1013	
				•	

Work Plan Report for Well:NHSAU 132-28



Survey Viewer