Office	State of New Mexico	Form C-103
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240	QOO.	WELL API NO. / 30-025-07507
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III - (505) 334-6178	3 2013 ¹ 220 South St. Francis Dr. Santa Fe, NM 87505	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 8741 NOV 1 District IV – (505) 476-3460	3 2013 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		
87505	END REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Section 31
PROPOSALS.)		8. Well Number 231
1. Type of Well: Oil Well Gas Well Other		/·
2. Name of Operator Occidental Permian Ltd.		9. OGRID Number: 157984
3. Address of Operator		10. Pool name or Wildcat Hobbs (G/SA)
2611 State Hwy 214 Denver City, TX 79323		To Foot name of Wilder Hoods (Grove)
4. Well Location	3, 11 19525	1 72 VD / West
Unit Letter K : 28 0	feet from the South line and 21	
Section 31 Township 18S Range 38E NMPM Lea County		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
7.7	644' GR	etc.)
to a such a such a such as a such as a such as a such as a such a such a such a such as a such as a such as a		Same of the same o
12. Check App	ropriate Box to Indicate Nature of Noti	ce, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐		
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐		
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB		
DOWNHOLE COMMINGLE	_	
		<u>_</u>
OTHER:	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
proposed completion of recomp	ietion.	
1) POOH with prod equip.	During t	his procedure we plan to use
2) Clean out to 4180 the closed-		ed-loop system with a steel
3) Acid treat with 1200 gal of 15% PAD acid tank and had		haul contents to the required
4) RIH with prod equipment. disposal per ODC Rule 19.15.17		
5) Return well to production		
Spud Date:	Rig Release Date:	
I hereby certify that the information above	e is true and complete to the best of my knowl	edge and belief.
SIGNATURE		
· · · · · · · · · · · · · · · · · · ·		
Type or print nameSteve Snead E-mail address: steve_snead@oxy.com PHONE: _806-592-6312		
For State Use Only A A		
$\sim 10^{-1}$		
APPROVED BY: 1 GALLES TITLE COMPUTENCE OFFICE DATE 11/14/2013		
Conditions of Approval (if any):		
NOV # 4 1012		
		NOV 1 4 2013