Submit 3 Copies To Appropriate Distric	State of New Mexico		Form C-103
Office <u>District I</u>	Energy, Minerals and Natural Resources		May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	<del></del> -		WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 8821	OIL CONSERVATION DIVISION		30-025-31320 5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE S FEE
District IV	Santa Fe, NM 8	37505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
	OTICES AND REPORTS ON WELLS	S	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PRO DIFFERENT RESERVOIR. USE "APP	POSALS TO DRILL OR TO DEEPEN OR PL PLICATION FOR PERMIT" (FORM C-101) F	LUG BACK TO A	Harry Leonard NCT A
PROPOSALS.)  1. Type of Well: Oil Well	Gas Well ⊠ Other □	HOBBS OCD	8. Well Number 013
2. Name of Operator			9. OGRID Number 217817
	ocoPhillips Company	NOV 1 4 2013	
3. Address of Operator	1 1 C/ 4 O.1 TV 707/2		10. Pool name or Wildcat
	nbrook Street Odessa, TX 79762	RECEIVED	Eumont; Yates 7 Rvrs Qn (Pro Gas)
4. Well Location	1670 6 6 6 0		
Unit Letter J:	1650 feet from the South	line and 2310	
Section 22 Town	<u> </u>		Lea County
. 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3585' GE			
Pit or Below-grade Tank Application or Closure			
Pit typeSteelDepth to GroundwaterDistance from nearest fresh water well Distance from nearest surface waterN/A			
Pit Liner Thickness: Steel mil Below-Grade Tank: Volume 180 bbls; Construction Material Steel			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REMEDIAL WORK □ ALTERING CASING □			
PERFORM REMEDIAL WORK  PLUG AND ABANDON  REMEDIAL WORK  ALTERING CASING  TEMPORARILY ABANDON  CHANGE PLANS  COMMENCE DRILLING OPNS. PAND A			
	MULTIPLE COMPL		
OTHER:			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.			
•			
10/31/13Call OCD to notify of move in.			
11/01/13Set CIBP w/ wireline	@ 3502', tbg @ 3502' circ hole w/ 1	0# MLF & cap CIBP	w/ 35 sxs @ 3502' CAL TOC @ 3352'. Set
CIBP w/ wireline @ 2976', tbg @ 2976' circ hole w/ 10# MLF & cap CIBP w/ 30 sxs "C" cmt @ 2976' CAL TOC @ 2720',			
call Mark w/ OCD ok'd to test csg w/ 500 psi not required to Tag plug @ 2976' csg test ok.			
11/04/13Perf @ 1610' pkr set @ 1037' load hole set pkr pressure to 2000 psi did not get inj. rate, call Mark w/ OCD ok'd to RIH w/			
tbg @ 1660' spot 35 sxs cmt CAL TOC @ 1418' Tag @ 1354'.			
11/05/13Perf @ 800' pkr set @ 387' sqz 40 sxs "C" cmt w/ 2% CaCl CAL TOC @ 700', tbg @ 650'. Perf @ 300' pkr set @ 30' get inj. Rate 2 BPM well did not circ, call Mark w/ OCD ok'd to sqz 40 sxs "C" cmt CAL TOC @ 100' Tag @ 60'.			
inj. Rate 2 BPM Well	and not circ, can Mark W/ OCD ok'd	to sqz 40 sxs "C" cn	nt CAL TOC @ 100' Tag @ 60'.
11/06/13Perf @ 60' load hole pressure to 2000 psi, RIH w/ 2 jts pump 15 sxs "C" cmt from 60' to surface. POOH tbg leave 5½ full of			
cmt. RDMO.		•	
A'd			
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.			
SIGNATURE	TITLE P&A	Tech (Basic Energ	gy Services) DATE <u>11/7/13</u>
Type or print name: Greg Bryan	nt F-mail add	drace:	Tolophono No. 422 562 2255
Walnus Kranze of Marian Color			
APPROVED BY: MILE STEWN TITLE COMPLIANCE SILVEN DATE 11/19/2013.			
	25 Srawn TITLE C	ompliance	-
Conditions of Approval (if any)	Brown TITLE C	ompliance	Officer DATE/19/2013.