

Submit 1 Copy To Appropriate District Office  
District I - (575) 393-6161  
1525 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised August 1, 2011

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-10014
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name H. Corrigan
8. Well Number 9
9. OGRID Number 873
10. Pool name or Wildcat Blinebry (Pro Gas)
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3455' GL

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> HOBBES OCD	
2. Name of Operator Apache Corporation	
3. Address of Operator 303 Veterans Airpark Lane, Ste 3000, Midland TX 79705	
4. Well Location Unit Letter G 1980' feet from the N line and 1880' feet from the E line Section 4 Township 22S Range 37E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3455' GL	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☒  
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 11/18/13 - Notify OCD of MIRU. RIH tag CIBP @ 5455'.
- 11/19/13 - Load well pressure test casing to 1000' psi ok. Circ well w/126 bbls MLF. Spot 40 x class "c" cmt @ 5455' WOC 4 hrs RIH tag TOC @ 4952' POH to 2815' spot 45 x class "c" cmt.
- 11/20/13 - RIH tag TOC @ 2330' POH perf @ 1370' sqz 75 x class "c" cmt displace to 1270' WOC 4 hrs. RIH tag TOC @ 1213' POH perf @ 266' sqz 175 x class "c" cmt to surface. Cmt was circulated behind all casings. Rig down all P&A equipment. Cutoff wellhead, anchors and clean location. Install dry hole marker.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jimmy Bagley TITLE Manager DATE 11/20/13  
Type or print name Jimmy Bagley E-mail address:  PHONE: 432-561-8600  
For State Use Only

APPROVED BY: Maureen Whitman TITLE Compliance Officer DATE 12/9/2013 PM  
Conditions of Approval (if any): Lucian Baker Reclamation Foreman Apache

DEC 10 2013