Submit 3 Copies To Appropriate District HOBBS OCD State of New Mexico	Form C-103		
	May 27, 2004		
District II District II District II District III District District D	30-025-21927 🗸		
1301 W. Grand Ave., Artesia, NM 88210 CONSERVATION DIVISION District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV District IV District IV RECEIVED 1220 South St. Francis Dr. Santa Fe, NM 87505	5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	STATE FEE   6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505	VO-8334		
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	AZTEC		
PROPOSALS.) 1. Type of Well: Oil Well 🛛 / Gas Well 🗌 Other SWD	8. Well Number 1 /		
2. Name of Operator	9. OGRID Number 024010		
V-F PETROLEUM INC.	1		
3. Address of Operator	10. Pool name or Wildcat		
P.O. BOX 1889, MIDLAND, TEXAS 79702 4. Well Location	VADA UPPER PENN		
4. Went Excation Unit Letter $\sqrt{F}$ : <u>2,130</u> feet from the <u>SOUTH</u> line and <u>660</u> feet from the <u>EAST</u> line			
	NMPM LEA County		
11: Elevation (Show whether DR, RKB, RT, GR, e.	tc.)		
Pit or Below-grade Tank Application _ or Closure _			
Pit type Depth to Groundwater Distance from nearest fresh water well Dist	ance from nearest surface water		
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PANDA			
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT JOB     OTHER:   OTHER:   OTHER: RETURN WELL TO PRODUCTION			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of			
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or			
recompletion.			
(SEE BACK)			
· · · · · · · · · · · · · · · · · · ·			
I hereby certify that the information above is true and complete to the best of my knowledge and	belief. I further certify that any pit or below-		
grade tank has been/will be constructed or closed according to NMOCD guidelines $\Box$ , a g OCD-approved plan $\Box_{n}$	eneral permit 🛄 or an (attached) alternative		
SIGNATURE Landy Lawlis TITLE Vice President	DATE <u>12/03/13</u>		
Type or print name Sandra K. Lawlis E-mail address: <u>skl@vfpetro</u>			
(This space for State use)			
APPPROVED BY that white TITLE Compliance officer DATE 12/9/2013			

Conditions	of approval,	if anv.
Conditions	or approval,	n any.

DEC 10 2013

08/13/13 - Building location. 08/18/13 MI Basic WSU. 08/19/13 08/20/13 RU WSU. Drilling cement plugs. 08/21/13 -Drilling cement plugs. 08/30/13 Lower bit to 1,034'. Wash & ream to 1,079' @ 11:59 p.m. Continue to wash & ream 11" hole through midnight. 08/31/13 09/01/13 Wash & ream to 1,081'. Circulate hole clean. 09/02/13-Lower bits to drl TD. 09/03/13 Continue drilling to 1,250'. 09/04/13 -09/13/13 09/14/13 Continue drilling to 1,266'. 09/23/13 09/24/13 RU Rotary WL fish finder tool. Locate top of pipe at 1,041'. RD Rotary WL. TIH with impression block. Multiple times unable to get inside 8 5/8" csg. 09/25/13 -09/26/13 09/27/13 RD rel WSU. 10/14/13 -MIRU WSU. Drilling to 1,294'. RD & rel WSU. 10/19/13 MIRU WSU. Nipple up WH. Run 8 5/8" csg. Set slips on 8 5/8" csg. Cut off 8 5/8". SDFN. 11/04/13 -11/05/13 11/06/13 - RU reverse unit. Washing and milling. Circ hole clean. 11/07/13 Nipple down 8 5/8" WH. Cut off 11" WH. Weld on to 8 5/8" csg. PU on csg. Install adapter. SWI. SDFN. 11/08/13 11/12/13 RU csg crew & lay down machine. TOH w/8 5/8" csg. LD all 8 5/8" csg. RD csg crew. RD lay down machine. RD WSU.

11/13/13 Well to be plugged and abandoned. No further work to be performed until P&A.