



# United States Department of the Interior

## BUREAU OF LAND MANAGEMENT

Carlsbad Field Office  
620 E. Greene  
Carlsbad, New Mexico 88220-6292  
www.nm.blm.gov



In Reply Refer to  
3162.4 (P0220)

HOBBS OCD

DECEMBER 18, 2013

RESACA OPERATING CO.  
1331 LAMAR  
STE: 1450  
HOUSTON, TX. 77010-3039

DEC 23 2013

RECEIVED

RE-ENTRY  
30-025-11166

Gentlemen:

Your Application for Permit to Drill (APD) for the well listed below has expired because drilling has not commenced per Onshore Order #1:

<u>LEASE</u>	<u>WELL NAME AND LOCATION</u>	<u>EXPIRATION</u>
NM12612	COOPER JAL UNIT -147 2313' FNL & 326' FWL, SWNW, sec.19 - T. 24 S.- R. 37 E.	DECEMBER 6, 2013

If the well has not been spud, but site construction activities have occurred please contact Jim Amos at (575) 234-5909 for surface reclamation instructions. If drilling operations have commenced send all necessary reports (spud, casing/cementing, etc., 1 original and 3 copies) to the BLM so we may correct our records.

If you wish to drill this wells at a later date, please submit a complete application (1 original and 3 copies) to this office. Since the original APD has expired, the resubmitted APD will be subject to all processing requirements including the \$6,500 application fee and the 30-day posting period. Please note on the resubmitted APD that it was previously approved and we will review the expired file for information which will help expedite the processing.

If you have any questions, please contact Johnny Dickerson at (575) 234-5914.

Sincerely,

Stephen J. Caffey  
Assistant Field Manager, Lands & Minerals

cc: NMOCD

DEC 30 2013