## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Hobbs

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

	Expires.	Jι
Lease	Serial No.	
	M3622	

SUNDRY N	OTICES AND REPORTS ON WELLS	
Do not use this	form for proposals to drill or to re-enter an	
abandanad wall	Hen form 2160-2 (APD) for such proposals	

HORRE

Do not use thi abandoned we	s form for proposals to drill ii. Use form 3160-3 (APD) fo	or to re-enter an re- r such proposals.	9093 OC 36. If India	n, Allottee or Tribe Name					
SUBMIT IN TRI	PLICATE - Other instruction	s on reverse side. AU		or CA/Agreement, Name and/or 124020	No.				
I. Type of Well		R		ame and No. INE DEEP UNIT 17 FEDERA	L 02/				
Oil Well ☑ Gas Well ☐ Oth  Name of Operator CIMAREX ENERGY COMPAI	Contact: TFR	RISTATHEM	9. API W	ell No. 5-37194-00-S1	/				
3a. Address 600 NORTH MARIENFELD S MIDLAND, TX 79701	3b.	Phone No. (include area code) 918-295-1763	10. Field	10. Field and Pool, or Exploratory QUAIL RIDGE Bone Spring					
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)		11. Count	y or Parish, and State	77				
Sec 17 T19S R34E SWNW 14	150FNL 1200FWL 🗸		LEA C	COUNTY, NM					
12. CHECK APPI	ROPRIATE BOX(ES) TO INI	DICATE NATURE OF N	NOTICE, REPORT, C	OR OTHER DATA					
TYPE OF SUBMISSION		TYPE OF	ACTION						
Notice of Intent     ■	☐ Acidize	☐ Deepen	☐ Production (Start/F	Resume) 🔲 Water Shut-	Off				
_	☐ Alter Casing	☐ Fracture Treat	■ Reclamation	□ Well Integri	ty				
☐ Subsequent Report	☐ Casing Repair	■ New Construction	□ Recomplete	□ Other					
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	☐ Temporarily Abane	don					
	☐ Convert to Injection	☑ Plug Back	■ Water Disposal						
determined that the site is ready for final inspection.)  Cimarex Energy Co. respectfully reugests approval to plugback the Pipeline Deep Unit 17 Federal #2 according to the following procedure:  5 (OM)  1. MIRU. Abandon Morrow perfs (13228-13235). RIH w/ CIBP & set @ 13178'. 2. Mix & pump-35-of cmt on top of plug.									
<ol> <li>Pressure test casing.</li> <li>RIH &amp; perf Bone Spring @</li> <li>Acidize Bone Spring w/ 500</li> <li>Return well to production.</li> </ol>	9430-10002'. 00 gals 15% NEFE acid.		SUBJECT TO LIKE APPROVAL BY STATE						
	de currents prop	rosed well bi	re diagram	S					
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #21141 For CIMAREX ENERG' mitted to AFMSS for processin	17 verified by the BLM Wel Y COMPANY OF CO, sent g by KURT SIMMONS on C	Information System to the Hobbs 01107/12/2013 (13kMs2407	ITACHED FOR	OVAL				
Name (Printed/Typed) TERRI ST	ATHEM	Title COORD	INATOR REGULATO	ORY COMPLIA					
Signature (Electronic S	ubmission)	Date 06/24/20	)13 <b>AP</b>	PROVED					
	THIS SPACE FOR F	EDERAL OR STATE	OFFICE USE						
Approved By		Title	AU	G 1 2 2013					
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to condu	itable title to those rights in the subje		BURNALO	FLAND MANAGEMENT PAD EVELD OFFICE	LON				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a crime tatements or representations as to any	for any person knowingly and matter within its jur	willfully make to any de	epartment or agency of the Unite	d				

\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED

<u>CONDITION OF APPROVAL</u>: Approval for Drilling ONLY. CANNOT produce without the OCD Santa Fe approval for Non-Standard Location.

## **Conditions of Approval**

Cimarex Energy Company
Pipeline Deep Unit 17 Federal 2
API 30-025-37194
T19S-R34E, Sec 17
August 12, 2013

Notify BLM at 575-393-3612 a minimum of 24 hours prior to commencing work.

Work to be completed by November 12, 2013.

- 1. Operator shall place a CIBP at 13,178' and place a minimum of 25 sx of Class H cement on top. Tag at approximately 12,972' required. Tag to be witnessed by BLM.
- 2. Operator shall place a balanced Class H cement plug from 12,853'-12,625' to isolate the top of the Morrow formation.
- 3. Operator shall place a balanced Class H cement plug from 11,211'-11,000' to isolate the top of the Wolfcamp formation.
- **4.** Subject to like approval by the New Mexico Oil Conservation Division.
- 5. Surface disturbance beyond the existing pad must have prior approval.
- **6.** A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 7. Functional H<sub>2</sub>S monitoring equipment shall be on location.
- 8. A minimum of 5000 (5M) BOPE shall be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (5M) Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.

- 9. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- **10.** Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 11. Operator shall submit a sundry to remove "unit" from the name. This is to remove wellbore from unit.
- 12. See attached for general requirements.
- 13. Submit subsequent sundry required detailing work done and completion report for the new formation. Operator to include well bore schematic of current well condition when work is complete.
- 14. Operator shall file a non-standard location for Bone Springs and the BLM will require a Communitization agreement when well spacing is established.

JAM 081213

## **BUREAU OF LAND MANAGEMENT**

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## **General Requirements**

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from this approval.

If you are unable to plug back the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat Class** "C", for up to 7,500 feet of depth or **Neat Class** "H", for deeper than 7,500 feet plugs.

- 6. <u>Subsequent Plug back Reporting:</u> Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date work was completed.**
- 7. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.