Office District 1		Form C-103	3.
	State of New Mexico Energy, Minerals and Natural F		
1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural F	WELL API NO.	$\overline{}$
District II		2. Ar - 2NUNI	
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIV	5 Indicate Type of Lease	\dashv
District III	1220 South St. Francis	Dr. STATE FEE	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	6. State Oil & Gas Lease No.	\dashv
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	54114 1 0, 1 111 0 1 5 0 5	6. State Off & das Lease No.	
87505			
SUNDRY NOTICE	ES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSA			
DIFFERENT RESERVOIR. USE "APPLICA"	TION FOR PERMIT" (FORM C-101) FOR SU	MONUMENT 14 STATE	1
PROPOSALS.) 1. Type of Well: Goil Well G	as Well [Other , the state of	8. Well Number	1
		9. OGRID Number	\dashv
	196.	4323 H1333	-
Cheuron Mines 3. Address of Operator	Nt. NENT		
· _	-	10. Pool name or Wildcat	ļ
15 Smith ROAD	MINIAND IX 79	705 ABO, North	
4. Well Location	· · · · · · · · · · · · · · · · · · ·	/	
Unit Letter Z : 1740	feet from the 5 line and feet	fro m the E line	
	195 Range 365 NMPM	County LEA	
1	11. Elevation (Show whether DR, RKE		
	3732	, Mr, Orc etc.)	
12. Check Appropriate Box to In		t or Other Date	
2. Check Appropriate box to in	ndicate Nature of Notice, Kepor	t of Other Data	
NOTICE OF INTI	ENTION TO:	SUBSEQUENT REPORT OF:	1
		MEDIAL WORK ALTERING CASING	, 1
•		1	
		MMENCE DRILLING OPNS. P AND A	
PULL OR ALTER CASING I	MULTIPLE COMPL CA	SING/CEMENT JOB	
OTUED.		Latin COD in an after DRA	
OTHER:		Location is ready for OCD inspection after P&A	
		ms of the Operator's pit permit and closure plan.	
A steel marker at least 4" in diame	ter and at least 4' above ground level	has been set in concrete. It shows the	
A steel marker at least 4" in diame OPERATOR NAME, LEAS	ter and at least 4' above ground level E NAME, WELL NUMBER, API N	has been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR	
A steel marker at least 4" in diame OPERATOR NAME, LEAS UNIT LETTER, SECTION,	ter and at least 4' above ground level E NAME, WELL NUMBER, API N TOWNSHIP, AND RANGE. All II	has been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR	
A steel marker at least 4" in diame OPERATOR NAME, LEAS UNIT LETTER, SECTION,	ter and at least 4' above ground level E NAME, WELL NUMBER, API N	has been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR	
A steel marker at least 4" in diame OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE	ter and at least 4' above ground level E NAME, WELL NUMBER, API N TOWNSHIP, AND RANGE. All II D ON THE MARKER'S SURFAC	has been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR VEORMATION HAS BEEN WELDED OR 3.	
A steel marker at least 4" in diame OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as no	ter and at least 4' above ground level E NAME, WELL NUMBER, API N TOWNSHIP, AND RANGE. All II D ON THE MARKER'S SURFAC	has been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR	l
A steel marker at least 4" in diame OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as nether production equipment.	ter and at least 4' above ground level E NAME, WELL NUMBER, API N TOWNSHIP, AND RANGE. All II D ON THE MARKER'S SURFAC early as possible to original ground co	has been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR 3. Intour and has been cleared of all junk, trash, flow lines and	1
A steel marker at least 4" in diame OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as nother production equipment. Anchors, dead men, tie downs and	ter and at least 4' above ground level E NAME, WELL NUMBER, API N TOWNSHIP, AND RANGE. All II D ON THE MARKER'S SURFACE early as possible to original ground contribute to the state of	has been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR 3. Intour and has been cleared of all junk, trash, flow lines and set below ground level.	1
OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as nother production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last respectively.	ter and at least 4' above ground level E NAME, WELL NUMBER, API N TOWNSHIP, AND RANGE. All II D ON THE MARKER'S SURFACE early as possible to original ground continuous prisers have been cut off at least two formaining well on lease, the battery and	has been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR E. Intour and has been cleared of all junk, trash, flow lines and set below ground level. pit location(s) have been remediated in compliance with	
OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as nother production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last resorted in the operator.	ter and at least 4' above ground level E NAME, WELL NUMBER, API N TOWNSHIP, AND RANGE. All II D ON THE MARKER'S SURFACE early as possible to original ground continuous prisers have been cut off at least two formaining well on lease, the battery and	has been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR 3. Intour and has been cleared of all junk, trash, flow lines and set below ground level.	
OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as nother production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last recomplease and the terms of the Operator om lease and well location.	ter and at least 4' above ground level E NAME, WELL NUMBER, API N TOWNSHIP, AND RANGE. All II D ON THE MARKER'S SURFACE early as possible to original ground continuous prisers have been cut off at least two formations well on lease, the battery and pr's pit permit and closure plan. All floors	thas been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR E. Intour and has been cleared of all junk, trash, flow lines and set below ground level. pit location(s) have been remediated in compliance with ow lines, production equipment and junk have been remove	ed
OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as nother production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last recompless and the terms of the Operator om lease and well location. All metal bolts and other materials	ter and at least 4' above ground level E NAME, WELL NUMBER, API N TOWNSHIP, AND RANGE. All II D ON THE MARKER'S SURFACE early as possible to original ground continuous prisers have been cut off at least two formations well on lease, the battery and pr's pit permit and closure plan. All floors	has been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR E. Intour and has been cleared of all junk, trash, flow lines and set below ground level. pit location(s) have been remediated in compliance with	ed
OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as menter production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last recommended in the terms of the Operator of the Operator lease and well location. All metal bolts and other materials be removed.)	ter and at least 4' above ground level E NAME, WELL NUMBER, API N TOWNSHIP, AND RANGE. All II DON THE MARKER'S SURFACE early as possible to original ground corrisers have been cut off at least two femaining well on lease, the battery and or's pit permit and closure plan. All flower been removed. Portable bases have	thas been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR E. Intour and has been cleared of all junk, trash, flow lines and set below ground level. pit location(s) have been remediated in compliance with low lines, production equipment and junk have been removed.	ed
OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as not her production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last rescont lease and the terms of the Operator lease and well location. All metal bolts and other materials be removed.) All other environmental concerns lease.	ter and at least 4' above ground level E NAME, WELL NUMBER, API N TOWNSHIP, AND RANGE. All II DON THE MARKER'S SURFACT early as possible to original ground corrisers have been cut off at least two formaining well on lease, the battery and or's pit permit and closure plan. All flower been removed. Portable bases have been addressed as per OCD rules have been addressed as per OCD rules.	has been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR 3. Intour and has been cleared of all junk, trash, flow lines and set below ground level. pit location(s) have been remediated in compliance with low lines, production equipment and junk have been removed twe been removed. (Poured onsite concrete bases do not have	ed
OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as neather production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last real CD rules and the terms of the Operato om lease and well location. All metal bolts and other materials as the removed.) All other environmental concerns and Pipelines and flow lines have been	ter and at least 4' above ground level E NAME, WELL NUMBER, API N TOWNSHIP, AND RANGE. All II DON THE MARKER'S SURFACT early as possible to original ground corrisers have been cut off at least two formaining well on lease, the battery and or's pit permit and closure plan. All flower been removed. Portable bases have been addressed as per OCD rules have been addressed as per OCD rules.	thas been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR E. Intour and has been cleared of all junk, trash, flow lines and set below ground level. pit location(s) have been remediated in compliance with low lines, production equipment and junk have been removed.	ed
OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as nether production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last recomplease and the terms of the Operate om lease and well location. All metal bolts and other materials be removed.) All other environmental concerns a pipelines and flow lines have been trieved flow lines and pipelines.	ter and at least 4' above ground level E NAME, WELL NUMBER, API NOTOWNSHIP, AND RANGE. All III DON THE MARKER'S SURFACT risers have been cut off at least two formaining well on lease, the battery and pr's pit permit and closure plan. All flower been removed. Portable bases have been addressed as per OCD rules abandoned in accordance with 19.15.	has been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR Let below ground level. pit location(s) have been remediated in compliance with ow lines, production equipment and junk have been removed we been removed. (Poured onsite concrete bases do not have been removed.) 35.10 NMAC. All fluids have been removed from non-	ed ve
OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as nother production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last resident of the Operator on lease and well location. All metal bolts and other materials to be removed.) All other environmental concerns the Pipelines and flow lines have been strieved flow lines and pipelines.	ter and at least 4' above ground level E NAME, WELL NUMBER, API NOTOWNSHIP, AND RANGE. All III DON THE MARKER'S SURFACT risers have been cut off at least two formaining well on lease, the battery and pr's pit permit and closure plan. All flower been removed. Portable bases have been addressed as per OCD rules abandoned in accordance with 19.15.	has been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR Let below ground level. pit location(s) have been remediated in compliance with ow lines, production equipment and junk have been removed we been removed. (Poured onsite concrete bases do not have been removed.) 35.10 NMAC. All fluids have been removed from non-	ed ve
OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as never production equipment. Anchors, dead men, tie downs and lifthis is a one-well lease or last recommended and the terms of the Operator lease and well location. All metal bolts and other materials be removed.) All other environmental concerns a Pipelines and flow lines have been trieved flow lines and pipelines. If this is a one-well lease or last recommended to the second seco	ter and at least 4' above ground level E NAME, WELL NUMBER, API N TOWNSHIP, AND RANGE. All II D ON THE MARKER'S SURFAC early as possible to original ground corrisers have been cut off at least two formaining well on lease, the battery and or's pit permit and closure plan. All flow have been removed. Portable bases have been addressed as per OCD rules abandoned in accordance with 19.15. maining well on lease: all electrical se	has been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR 3. Intour and has been cleared of all junk, trash, flow lines and set below ground level. pit location(s) have been remediated in compliance with low lines, production equipment and junk have been removed twe been removed. (Poured onsite concrete bases do not have	ed ve
OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as never production equipment. Anchors, dead men, tie downs and lifthis is a one-well lease or last recommended and the terms of the Operator lease and well location. All metal bolts and other materials be removed.) All other environmental concerns a Pipelines and flow lines have been trieved flow lines and pipelines. If this is a one-well lease or last recommended to the second seco	ter and at least 4' above ground level E NAME, WELL NUMBER, API N TOWNSHIP, AND RANGE. All II D ON THE MARKER'S SURFAC early as possible to original ground corrisers have been cut off at least two formaining well on lease, the battery and or's pit permit and closure plan. All flow have been removed. Portable bases have been addressed as per OCD rules abandoned in accordance with 19.15. maining well on lease: all electrical se	has been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR Let below ground level. pit location(s) have been remediated in compliance with ow lines, production equipment and junk have been removed we been removed. (Poured onsite concrete bases do not have been removed.) 35.10 NMAC. All fluids have been removed from non-	ed ve
OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as menter production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last recommended by the comment of the Operator of the Operator lease and well location. All metal bolts and other materials be removed.) All other environmental concerns the Pipelines and flow lines have been brieved flow lines and pipelines. If this is a one-well lease or last recoation, except for utility's distribution	E NAME, WELL NUMBER, APIN TOWNSHIP, AND RANGE. All II DON THE MARKER'S SURFACE early as possible to original ground corrisers have been cut off at least two femaining well on lease, the battery and or's pit permit and closure plan. All floware been removed. Portable bases have been addressed as per OCD rules abandoned in accordance with 19.15. maining well on lease: all electrical seminfrastructure.	thas been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR E. Intour and has been cleared of all junk, trash, flow lines and set below ground level. pit location(s) have been remediated in compliance with low lines, production equipment and junk have been removed live been removed. (Poured onsite concrete bases do not have been removed. All fluids have been removed from non- rvice poles and lines have been removed from lease and we	ed ve
OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as nother production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last ref CD rules and the terms of the Operato om lease and well location. All metal bolts and other materials be removed.) All other environmental concerns to be removed. Pipelines and flow lines have been trieved flow lines and pipelines. If this is a one-well lease or last ref cation, except for utility's distribution	E NAME, WELL NUMBER, APIN TOWNSHIP, AND RANGE. All II DON THE MARKER'S SURFACE early as possible to original ground corrisers have been cut off at least two femaining well on lease, the battery and or's pit permit and closure plan. All floware been removed. Portable bases have been addressed as per OCD rules abandoned in accordance with 19.15. maining well on lease: all electrical seminfrastructure.	thas been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR E. Intour and has been cleared of all junk, trash, flow lines and set below ground level. pit location(s) have been remediated in compliance with low lines, production equipment and junk have been removed live been removed. (Poured onsite concrete bases do not have been removed. All fluids have been removed from non- rvice poles and lines have been removed from lease and we	ed ve
OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as me her production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last recomplese and the terms of the Operator on lease and well location. All metal bolts and other materials be removed.) All other environmental concerns leaved flow lines and pipelines. If this is a one-well lease or last recoation, except for utility's distribution then all work has been completed, return the second of the complete	ter and at least 4' above ground level E NAME, WELL NUMBER, API N TOWNSHIP, AND RANGE. All II D ON THE MARKER'S SURFAC early as possible to original ground corrisers have been cut off at least two formaining well on lease, the battery and or's pit permit and closure plan. All flow have been removed. Portable bases have been addressed as per OCD rules abandoned in accordance with 19.15. maining well on lease: all electrical search infrastructure. The properties of the propriate Distriction of the properties of the propertie	has been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR L. Intour and has been cleared of all junk, trash, flow lines and set below ground level. pit location(s) have been remediated in compliance with low lines, production equipment and junk have been removed are been removed. (Poured onsite concrete bases do not have been removed.) 35.10 NMAC. All fluids have been removed from non- rvice poles and lines have been removed from lease and we at office to schedule an inspection.	ed ve
OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as me her production equipment. Anchors, dead men, tie downs and lf this is a one-well lease or last reconcerns and the terms of the Operator lease and well location. All metal bolts and other materials be removed.) All other environmental concerns lease and flow lines have been trieved flow lines and pipelines. If this is a one-well lease or last reconcerns, except for utility's distribution then all work has been completed, return the second completed, return the second completed of the second complete of the second com	ter and at least 4' above ground level E NAME, WELL NUMBER, API N TOWNSHIP, AND RANGE. All II D ON THE MARKER'S SURFAC early as possible to original ground corrisers have been cut off at least two formaining well on lease, the battery and or's pit permit and closure plan. All flow have been removed. Portable bases have been addressed as per OCD rules abandoned in accordance with 19.15. maining well on lease: all electrical search infrastructure. The properties of the propriate Distriction of the properties of the propertie	has been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR L. Intour and has been cleared of all junk, trash, flow lines and set below ground level. pit location(s) have been remediated in compliance with low lines, production equipment and junk have been removed are been removed. (Poured onsite concrete bases do not have been removed.) 35.10 NMAC. All fluids have been removed from non- rvice poles and lines have been removed from lease and we at office to schedule an inspection.	ed ve
OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as nother production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last report of the Operator of the	E NAME, WELL NUMBER, API N. TOWNSHIP, AND RANGE. All II DON THE MARKER'S SURFACT early as possible to original ground corrisers have been cut off at least two formaining well on lease, the battery and pr's pit permit and closure plan. All flower been removed. Portable bases have been addressed as per OCD rules abandoned in accordance with 19.15. maining well on lease: all electrical search infrastructure.	has been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR 3. Intour and has been cleared of all junk, trash, flow lines and set below ground level. pit location(s) have been remediated in compliance with ow lines, production equipment and junk have been removed are been removed. (Poured onsite concrete bases do not have been removed from non- rvice poles and lines have been removed from lease and we at office to schedule an inspection. Coustruction Rep. DATE 10-15-13	ed ve
OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as nother production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last report of the Operator of the	E NAME, WELL NUMBER, API N. TOWNSHIP, AND RANGE. All II DON THE MARKER'S SURFACT early as possible to original ground corrisers have been cut off at least two formaining well on lease, the battery and pr's pit permit and closure plan. All flower been removed. Portable bases have been addressed as per OCD rules abandoned in accordance with 19.15. maining well on lease: all electrical search infrastructure.	has been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR 3. Intour and has been cleared of all junk, trash, flow lines and set below ground level. pit location(s) have been remediated in compliance with ow lines, production equipment and junk have been removed are been removed. (Poured onsite concrete bases do not have been removed from non- rvice poles and lines have been removed from lease and we at office to schedule an inspection. Coustruction Rep. DATE 10-15-13	ed ve
OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as nother production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last reform lease and the terms of the Operator om lease and well location. All metal bolts and other materials be removed. All other environmental concerns of Pipelines and flow lines have been trieved flow lines and pipelines. If this is a one-well lease or last reform the cation, except for utility's distribution then all work has been completed, return the control of the complete	E NAME, WELL NUMBER, API N. TOWNSHIP, AND RANGE. All II DON THE MARKER'S SURFACT early as possible to original ground corrisers have been cut off at least two formaining well on lease, the battery and pr's pit permit and closure plan. All flower been removed. Portable bases have been addressed as per OCD rules abandoned in accordance with 19.15. maining well on lease: all electrical search infrastructure.	has been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR L. Intour and has been cleared of all junk, trash, flow lines and set below ground level. pit location(s) have been remediated in compliance with low lines, production equipment and junk have been removed are been removed. (Poured onsite concrete bases do not have been removed.) 35.10 NMAC. All fluids have been removed from non- rvice poles and lines have been removed from lease and we at office to schedule an inspection.	ed ve
OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as mer production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last rest on the compact of the Operator of the Oper	E NAME, WELL NUMBER, API N. TOWNSHIP, AND RANGE. All II DON THE MARKER'S SURFACT early as possible to original ground corrisers have been cut off at least two formaining well on lease, the battery and pr's pit permit and closure plan. All flower been removed. Portable bases have been addressed as per OCD rules abandoned in accordance with 19.15. maining well on lease: all electrical search infrastructure.	has been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR Let below ground level. pit location(s) have been remediated in compliance with own lines, production equipment and junk have been removed are been removed. (Poured onsite concrete bases do not have been removed. (Poured onsite concrete bases do not have been removed from non-cruice poles and lines have been removed from lease and we to office to schedule an inspection. Construction Rep. DATE 10-15-13	ed ve
OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as nother production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last refunction lease and the terms of the Operator om lease and well location. All metal bolts and other materials be removed. All other environmental concerns leaved flow lines and pipelines. If this is a one-well lease or last refunction, except for utility's distribution then all work has been completed, return the GNATURE OPE OR PRINT NAME OPE OR PRINT NAME OPE OR PRINT NAME OPE OR PRINT NAME	E NAME, WELL NUMBER, API N. TOWNSHIP, AND RANGE. All II DON THE MARKER'S SURFACT early as possible to original ground corrisers have been cut off at least two formaining well on lease, the battery and pr's pit permit and closure plan. All flower been removed. Portable bases have been addressed as per OCD rules abandoned in accordance with 19.15. maining well on lease: all electrical search infrastructure.	has been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR Let below ground level. pit location(s) have been remediated in compliance with own lines, production equipment and junk have been removed are been removed. (Poured onsite concrete bases do not have been removed. (Poured onsite concrete bases do not have been removed from non-cruice poles and lines have been removed from lease and we to office to schedule an inspection. Construction Rep. DATE 10-15-13	ed ve
UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as nother production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last report rom lease and well location. All metal bolts and other materials to be removed.) All other environmental concerns and Pipelines and flow lines have been etrieved flow lines and pipelines.	E NAME, WELL NUMBER, API N. TOWNSHIP, AND RANGE. All II DON THE MARKER'S SURFACT early as possible to original ground corrisers have been cut off at least two formaining well on lease, the battery and pr's pit permit and closure plan. All flower been removed. Portable bases have been addressed as per OCD rules abandoned in accordance with 19.15. maining well on lease: all electrical search infrastructure.	has been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR Let below ground level. pit location(s) have been remediated in compliance with own lines, production equipment and junk have been removed are been removed. (Poured onsite concrete bases do not have been removed. (Poured onsite concrete bases do not have been removed from non-cruice poles and lines have been removed from lease and we to office to schedule an inspection. Construction Rep. DATE 10-15-13	ed ve
OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as nother production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last report room lease and the terms of the Operator room lease and well location. All metal bolts and other materials to be removed.) All other environmental concerns of the Operator room lease and flow lines have been entireved flow lines and pipelines. If this is a one-well lease or last report room, except for utility's distribution when all work has been completed, return the room of the Operator room lease or last report room lease room lease or last report room lease roo	E NAME, WELL NUMBER, API N. TOWNSHIP, AND RANGE. All II DON THE MARKER'S SURFACT early as possible to original ground corrisers have been cut off at least two formaining well on lease, the battery and pr's pit permit and closure plan. All flower been removed. Portable bases have been addressed as per OCD rules abandoned in accordance with 19.15. maining well on lease: all electrical search infrastructure.	has been set in concrete. It shows the UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR 3. Intour and has been cleared of all junk, trash, flow lines and set below ground level. pit location(s) have been remediated in compliance with ow lines, production equipment and junk have been removed are been removed. (Poured onsite concrete bases do not have been removed from non- rvice poles and lines have been removed from lease and we at office to schedule an inspection. Coustruction Rep. DATE 10-15-13	ed ve ell