Submit 1 Copy To Appropriate District Office <u>District 1</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	State of New Mexico Energy, Minerals and Natural Resources		Form C-103 Revised August 1, 2011 WELL API NO.						
$\frac{\text{District II}}{\text{District III}} = (575) 748-1283$ 811 S. First St., Artesia, NM 88210 $\frac{\text{District III}}{\text{District III}} = (505) 334-6178$ 1000 Rio Brazos Rd., Aztec, NM 87410 $\frac{\text{District IV}}{\text{District IV}} = (505) 476-3460$ 1220 S. St. Francis Dr., Santa Fe, NM 87505	OIL CONSERVA 1220 South S Santa Fe, I	t. Francis Dr.	30-005-10531 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No. OG-1062						
	CATION FOR PERMIT" (FORM C	NOR PLUG BACK TO A C-101) FOR SUCH HOBBS OCD er Injection Well	 7. Lease Name or Unit Agreement Name KM Chaveroo SA Unit 8. Well Number 113 						
2. Name of Operator Dugan Production Corp.	/	DEC 03 2014	9. OGRID Number 006515						
3. Address of Operator P O Box 420, Farmington, NM 874	499-0420	RECEIVED	10. Pool name or Wildcat						
4. Well Location Unit Letter P : 990 feet from the _South _ line and _990 _ feet from the _East _ line Section 2 Township 8S Range 33E NMPM Chaves _ County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4347' GL									
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data									
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE	PLUG AND ABANDON [CHANGE PLANS [REMEDIAL WO COMMENCE DR	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. P AND A CASING/CEMENT JOB						
OTHER:			Irn to Injection						
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of									

proposed completion or recompletion.


¥.

On July 17, 2012, the packer in the subject injection well was found to have failed. The tubing was pulled and the packer was replaced with a Model AD-1 style tension packer. The packer was set at 4153'. A wellbore schematic is attached. The casing was pressure tested with no leaks on November 12, 2014. The test was witnessed by the NMOCD. This well is returned to injection. A previous sundry incorrectly reported this well as temporarily abandoned.

Spud Date:		F	Rig Release Date:				
I hereby certify that	t the information ab	ove is true and con	nplete to the best	of my knowledge and be	elief.		
SIGNATURE	hn/llo	for the	TITLE <u>Vice-Pr</u>	esident			
Type or print name	John Alexander	E-mail address:	johncalexander(duganproduction.com	PHONE: <u>505-3</u>	325-1821	
For State Use Onl APPROVED BY:	Y O			A Manager			L
Conditions of App	oval (if any):			•			
					DEC	17 2014'	SM

<u>Wellbore Schematic</u> K M Chaveroo SA 113, San Anders 300-05-10531 990' FSL & 990' FEL, S2 T8S R33E

ł



8 5/8" J-55 24# casing @ 401.

Packer set @ 4153'

San Anders Perforated @ 4241'-4275' & 4292'-4336'

2-3/8" tubing. End of Tubing @ 4323'

5 1/2" 14 # casing @ 4340'. PBTD @ 4338'

(