	2 A	2014
Submit One Copy To Appropriate District	State of New Mexico NOV 2 4	Form C-103
Office District I	Energy, Minerals and Natural Resources	Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240	RECE!	REVISED 140VEIDE 3, 2011
<u>District II</u> 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III	1220 South St. Francis Dr.	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
	ES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(ALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	JR Phillips
PROPOSALS.)	ATION FOR PERMIT" (FORM C-101) FOR SUCH	
1. Type of Well: Soil Well	Gas Well Other: Injection	8. Well Number 005
2. Name of Operator		9. OGRID Number
Chevron, USA INC		4323
3. Address of Operator		10. Pool name or Wildcat
15 Smith Road, Midland, TX 79705		Monument; ABO (Oil & Gas)
4. Well Location		
Unit Letter: <u>D</u> 660 feet from the <u>No</u>	rth line and 660 feet from the West line Section 06 T	ownship 20S Range 37E NMPM
County <u>Lea</u>		
	11. Elevation (Show whether DR, RKB, RT, GR, etc.,	
		The state of the s
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO:		
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REMEDIAL WORK □ ALTERING CASING □		
TEMPORARILY ABANDON DIVIDOR NATIONAL DIVIDING	<u> </u>	
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEMEN	T JOB 🛛 🏑
		and the OOD increasion of the DOA
OTHER:		eady for OCD inspection after P&A
	compliance with OCD rules and the terms of the Ope	rator's pit permit and closure plan.
✓ All pits have been remediated in✓ Rat hole and cellar have been fill	compliance with OCD rules and the terms of the Ope ed and leveled. Cathodic protection holes have been	rator's pit permit and closure plan. properly abandoned.
✓ All pits have been remediated in✓ Rat hole and cellar have been fill	compliance with OCD rules and the terms of the Ope	rator's pit permit and closure plan. properly abandoned.
 ✓ All pits have been remediated in ✓ Rat hole and cellar have been fill ✓ A steel marker at least 4" in diam 	compliance with OCD rules and the terms of the Ope ed and leveled. Cathodic protection holes have been leter and at least 4' above ground level has been set in	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the
 ✓ All pits have been remediated in ✓ Rat hole and cellar have been fill ✓ A steel marker at least 4" in diam OPERATOR NAME, LEA	compliance with OCD rules and the terms of the Ope ed and leveled. Cathodic protection holes have been eter and at least 4' above ground level has been set in SE NAME, WELL NUMBER, API NUMBER, QU	rator's pit permit and closure plan. properly abandoned. a concrete. It shows the JARTER/QUARTER LOCATION OR
 ✓ All pits have been remediated in ✓ Rat hole and cellar have been fill ✓ A steel marker at least 4" in diam OPERATOR NAME, LEAUNIT LETTER, SECTION 	compliance with OCD rules and the terms of the Ope ed and leveled. Cathodic protection holes have been eter and at least 4' above ground level has been set in SE NAME, WELL NUMBER, API NUMBER, QUI, TOWNSHIP, AND RANGE. All INFORMATION.	rator's pit permit and closure plan. properly abandoned. a concrete. It shows the JARTER/QUARTER LOCATION OR
 ✓ All pits have been remediated in ✓ Rat hole and cellar have been fill ✓ A steel marker at least 4" in diam OPERATOR NAME, LEAUNIT LETTER, SECTION 	compliance with OCD rules and the terms of the Ope ed and leveled. Cathodic protection holes have been eter and at least 4' above ground level has been set in SE NAME, WELL NUMBER, API NUMBER, QU	rator's pit permit and closure plan. properly abandoned. a concrete. It shows the JARTER/QUARTER LOCATION OR
 ✓ All pits have been remediated in ✓ Rat hole and cellar have been fill ✓ A steel marker at least 4" in diam OPERATOR NAME, LEA UNIT LETTER, SECTION PERMANENTLY STAMP 	compliance with OCD rules and the terms of the Ope ed and leveled. Cathodic protection holes have been eter and at least 4' above ground level has been set in SE NAME, WELL NUMBER, API NUMBER, QUI, TOWNSHIP, AND RANGE. All INFORMATION.	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the JARTER/QUARTER LOCATION OR DN HAS BEEN WELDED OR
All pits have been remediated in Rat hole and cellar have been fill A steel marker at least 4" in diam OPERATOR NAME, LEA UNIT LETTER, SECTION PERMANENTLY STAMP The location has been leveled as other production equipment.	compliance with OCD rules and the terms of the Ope ed and leveled. Cathodic protection holes have been leter and at least 4' above ground level has been set in SE NAME, WELL NUMBER, API NUMBER, QUI, TOWNSHIP, AND RANGE. All INFORMATION ED ON THE MARKER'S SURFACE. The property of the content of the content of the complex of the content of the conten	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the JARTER/QUARTER LOCATION OR DN HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and
All pits have been remediated in Rat hole and cellar have been fill A steel marker at least 4" in diam OPERATOR NAME, LEA UNIT LETTER, SECTION PERMANENTLY STAMP The location has been leveled as other production equipment. Anchors, dead men, tie downs an	compliance with OCD rules and the terms of the Ope ed and leveled. Cathodic protection holes have been leter and at least 4' above ground level has been set in SE NAME, WELL NUMBER, API NUMBER, QUI, TOWNSHIP, AND RANGE. All INFORMATION ED ON THE MARKER'S SURFACE. Inearly as possible to original ground contour and has drisers have been cut off at least two feet below ground.	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the JARTER/QUARTER LOCATION OR DN HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level.
All pits have been remediated in Rat hole and cellar have been fill A steel marker at least 4" in diam OPERATOR NAME, LEA UNIT LETTER, SECTION PERMANENTLY STAMP The location has been leveled as other production equipment. Anchors, dead men, tie downs an If this is a one-well lease or last r	compliance with OCD rules and the terms of the Ope ed and leveled. Cathodic protection holes have been eter and at least 4' above ground level has been set in SE NAME, WELL NUMBER, API NUMBER, QUI, TOWNSHIP, AND RANGE. All INFORMATION ED ON THE MARKER'S SURFACE. Inearly as possible to original ground contour and has drisers have been cut off at least two feet below ground emaining well on lease, the battery and pit location(s)	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the JARTER/QUARTER LOCATION OR DN HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with
All pits have been remediated in Rat hole and cellar have been fill A steel marker at least 4" in diam OPERATOR NAME, LEA UNIT LETTER, SECTION PERMANENTLY STAMP The location has been leveled as other production equipment. Anchors, dead men, tie downs an If this is a one-well lease or last r OCD rules and the terms of the Opera	compliance with OCD rules and the terms of the Ope ed and leveled. Cathodic protection holes have been leter and at least 4' above ground level has been set in SE NAME, WELL NUMBER, API NUMBER, QUI, TOWNSHIP, AND RANGE. All INFORMATION ED ON THE MARKER'S SURFACE. Inearly as possible to original ground contour and has drisers have been cut off at least two feet below ground.	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the JARTER/QUARTER LOCATION OR DN HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with
All pits have been remediated in Rat hole and cellar have been fill A steel marker at least 4" in diam OPERATOR NAME, LEA UNIT LETTER, SECTION PERMANENTLY STAMP The location has been leveled as other production equipment. Anchors, dead men, tie downs an If this is a one-well lease or last r OCD rules and the terms of the Opera from lease and well location.	compliance with OCD rules and the terms of the Ope ed and leveled. Cathodic protection holes have been eter and at least 4' above ground level has been set in SE NAME, WELL NUMBER, API NUMBER, QUI, TOWNSHIP, AND RANGE. All INFORMATION ED ON THE MARKER'S SURFACE. Inearly as possible to original ground contour and has drisers have been cut off at least two feet below ground emaining well on lease, the battery and pit location(s) tor's pit permit and closure plan. All flow lines, products	rator's pit permit and closure plan. properly abandoned. a concrete. It shows the JARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with fluction equipment and junk have been removed
All pits have been remediated in Rat hole and cellar have been fill A steel marker at least 4" in diam OPERATOR NAME, LEAUNIT LETTER, SECTION PERMANENTLY STAMP The location has been leveled as other production equipment. Anchors, dead men, tie downs an If this is a one-well lease or last r OCD rules and the terms of the Opera from lease and well location. All metal bolts and other materials.	compliance with OCD rules and the terms of the Ope ed and leveled. Cathodic protection holes have been eter and at least 4' above ground level has been set in SE NAME, WELL NUMBER, API NUMBER, QUI, TOWNSHIP, AND RANGE. All INFORMATION ED ON THE MARKER'S SURFACE. Inearly as possible to original ground contour and has drisers have been cut off at least two feet below ground emaining well on lease, the battery and pit location(s)	rator's pit permit and closure plan. properly abandoned. a concrete. It shows the JARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with fluction equipment and junk have been removed
All pits have been remediated in Rat hole and cellar have been fill A steel marker at least 4" in diam OPERATOR NAME, LEA UNIT LETTER, SECTION PERMANENTLY STAMP The location has been leveled as other production equipment. Anchors, dead men, tie downs an If this is a one-well lease or last r OCD rules and the terms of the Opera from lease and well location. All metal bolts and other materials to be removed.)	compliance with OCD rules and the terms of the Ope ed and leveled. Cathodic protection holes have been eter and at least 4' above ground level has been set in SE NAME, WELL NUMBER, API NUMBER, QUI, TOWNSHIP, AND RANGE. All INFORMATION ED ON THE MARKER'S SURFACE. Inearly as possible to original ground contour and has drisers have been cut off at least two feet below ground emaining well on lease, the battery and pit location(s) tor's pit permit and closure plan. All flow lines, products have been removed. Portable bases have been removed.	rator's pit permit and closure plan. properly abandoned. a concrete. It shows the JARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with fluction equipment and junk have been removed
All pits have been remediated in Rat hole and cellar have been fill A steel marker at least 4" in diam OPERATOR NAME, LEA UNIT LETTER, SECTION PERMANENTLY STAMP The location has been leveled as other production equipment. Anchors, dead men, tie downs an If this is a one-well lease or last r OCD rules and the terms of the Opera from lease and well location. All metal bolts and other material to be removed.) All other environmental concerns	compliance with OCD rules and the terms of the Ope ed and leveled. Cathodic protection holes have been eter and at least 4' above ground level has been set in SE NAME, WELL NUMBER, API NUMBER, QUI, TOWNSHIP, AND RANGE. All INFORMATION ED ON THE MARKER'S SURFACE. Inearly as possible to original ground contour and has drisers have been cut off at least two feet below ground emaining well on lease, the battery and pit location(s) tor's pit permit and closure plan. All flow lines, product that the product of the p	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the JARTER/QUARTER LOCATION OR DN HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with fluction equipment and junk have been removed oved. (Poured onsite concrete bases do not have
All pits have been remediated in Rat hole and cellar have been fill A steel marker at least 4" in diam OPERATOR NAME, LEA UNIT LETTER, SECTION PERMANENTLY STAMP The location has been leveled as other production equipment. Anchors, dead men, tie downs an If this is a one-well lease or last r OCD rules and the terms of the Opera from lease and well location. All metal bolts and other materials to be removed.) All other environmental concerns Pipelines and flow lines have been	compliance with OCD rules and the terms of the Ope ed and leveled. Cathodic protection holes have been eter and at least 4' above ground level has been set in SE NAME, WELL NUMBER, API NUMBER, QUI, TOWNSHIP, AND RANGE. All INFORMATION ED ON THE MARKER'S SURFACE. Inearly as possible to original ground contour and has drisers have been cut off at least two feet below ground emaining well on lease, the battery and pit location(s) tor's pit permit and closure plan. All flow lines, products have been removed. Portable bases have been removed.	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the JARTER/QUARTER LOCATION OR DN HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with fluction equipment and junk have been removed oved. (Poured onsite concrete bases do not have
All pits have been remediated in Rat hole and cellar have been fill A steel marker at least 4" in diam OPERATOR NAME, LEAUNIT LETTER, SECTION PERMANENTLY STAMP The location has been leveled as other production equipment. Anchors, dead men, tie downs an If this is a one-well lease or last roccord rules and the terms of the Opera from lease and well location. All metal bolts and other materials to be removed.) All other environmental concerns. Pipelines and flow lines have beer retrieved flow lines and pipelines.	compliance with OCD rules and the terms of the Ope ed and leveled. Cathodic protection holes have been eter and at least 4' above ground level has been set in SE NAME, WELL NUMBER, API NUMBER, QUI, TOWNSHIP, AND RANGE. All INFORMATION ED ON THE MARKER'S SURFACE. Inearly as possible to original ground contour and has derisers have been cut off at least two feet below ground emaining well on lease, the battery and pit location(s) tor's pit permit and closure plan. All flow lines, products have been removed. Portable bases have been removed as have been addressed as per OCD rules. In abandoned in accordance with 19.15.35.10 NMAC	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the JARTER/QUARTER LOCATION OR DN HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with fluction equipment and junk have been removed oved. (Poured onsite concrete bases do not have
All pits have been remediated in Rat hole and cellar have been fill A steel marker at least 4" in diam OPERATOR NAME, LEAUNIT LETTER, SECTION PERMANENTLY STAMP The location has been leveled as other production equipment. Anchors, dead men, tie downs an If this is a one-well lease or last r OCD rules and the terms of the Opera from lease and well location. All metal bolts and other materials to be removed.) All other environmental concerns Pipelines and flow lines have bee retrieved flow lines and pipelines. If this is a one-well lease or last reference of the operation of the	compliance with OCD rules and the terms of the Ope ed and leveled. Cathodic protection holes have been eter and at least 4' above ground level has been set in SE NAME, WELL NUMBER, API NUMBER, QUI, TOWNSHIP, AND RANGE. All INFORMATION ED ON THE MARKER'S SURFACE. Inearly as possible to original ground contour and has derisers have been cut off at least two feet below ground emaining well on lease, the battery and pit location(s) tor's pit permit and closure plan. All flow lines, products have been removed. Portable bases have been removed as have been addressed as per OCD rules. In abandoned in accordance with 19.15.35.10 NMAC emaining well on lease: all electrical service poles and	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the JARTER/QUARTER LOCATION OR DN HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with fluction equipment and junk have been removed oved. (Poured onsite concrete bases do not have
All pits have been remediated in Rat hole and cellar have been fill A steel marker at least 4" in diam OPERATOR NAME, LEAUNIT LETTER, SECTION PERMANENTLY STAMP The location has been leveled as other production equipment. Anchors, dead men, tie downs an If this is a one-well lease or last roccord rules and the terms of the Opera from lease and well location. All metal bolts and other materials to be removed.) All other environmental concerns. Pipelines and flow lines have beer retrieved flow lines and pipelines.	compliance with OCD rules and the terms of the Ope ed and leveled. Cathodic protection holes have been eter and at least 4' above ground level has been set in SE NAME, WELL NUMBER, API NUMBER, QUI, TOWNSHIP, AND RANGE. All INFORMATION ED ON THE MARKER'S SURFACE. Inearly as possible to original ground contour and has derisers have been cut off at least two feet below ground emaining well on lease, the battery and pit location(s) tor's pit permit and closure plan. All flow lines, products have been removed. Portable bases have been removed as have been addressed as per OCD rules. In abandoned in accordance with 19.15.35.10 NMAC emaining well on lease: all electrical service poles and	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the JARTER/QUARTER LOCATION OR DN HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with fluction equipment and junk have been removed oved. (Poured onsite concrete bases do not have
All pits have been remediated in Rat hole and cellar have been fill A steel marker at least 4" in diam OPERATOR NAME, LEA UNIT LETTER, SECTION PERMANENTLY STAMP The location has been leveled as other production equipment. Anchors, dead men, tie downs an If this is a one-well lease or last r OCD rules and the terms of the Opera from lease and well location. All metal bolts and other materials to be removed.) All other environmental concerns Pipelines and flow lines have been retrieved flow lines and pipelines. If this is a one-well lease or last relocation, except for utility's distribution	compliance with OCD rules and the terms of the Ope ed and leveled. Cathodic protection holes have been eter and at least 4' above ground level has been set in SE NAME, WELL NUMBER, API NUMBER, QUIL TOWNSHIP, AND RANGE. All INFORMATION ED ON THE MARKER'S SURFACE. Inearly as possible to original ground contour and has derisers have been cut off at least two feet below ground emaining well on lease, the battery and pit location(s) tor's pit permit and closure plan. All flow lines, products have been removed. Portable bases have been removed as have been addressed as per OCD rules. In abandoned in accordance with 19.15.35.10 NMAC emaining well on lease: all electrical service poles and infrastructure.	rator's pit permit and closure plan. properly abandoned. a concrete. It shows the JARTER/QUARTER LOCATION OR DN HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with fluction equipment and junk have been removed eved. (Poured onsite concrete bases do not have) All fluids have been removed from non- d lines have been removed from lease and well
All pits have been remediated in Rat hole and cellar have been fill A steel marker at least 4" in diam OPERATOR NAME, LEA UNIT LETTER, SECTION PERMANENTLY STAMP The location has been leveled as other production equipment. Anchors, dead men, tie downs an If this is a one-well lease or last r OCD rules and the terms of the Opera from lease and well location. All metal bolts and other material to be removed.) All other environmental concerns Pipelines and flow lines have been retrieved flow lines and pipelines. If this is a one-well lease or last r location, except for utility's distribution.	compliance with OCD rules and the terms of the Ope ed and leveled. Cathodic protection holes have been eter and at least 4' above ground level has been set in SE NAME, WELL NUMBER, API NUMBER, QUIL TOWNSHIP, AND RANGE. All INFORMATION ED ON THE MARKER'S SURFACE. Inearly as possible to original ground contour and has derisers have been cut off at least two feet below ground emaining well on lease, the battery and pit location(s) tor's pit permit and closure plan. All flow lines, products have been removed. Portable bases have been removed as have been addressed as per OCD rules. In abandoned in accordance with 19.15.35.10 NMAC emaining well on lease: all electrical service poles and infrastructure.	rator's pit permit and closure plan. properly abandoned. a concrete. It shows the JARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with fluction equipment and junk have been removed eved. (Poured onsite concrete bases do not have eved. All fluids have been removed from non-d lines have been removed from lease and well evedule an inspection.
All pits have been remediated in Rat hole and cellar have been fill A steel marker at least 4" in diam OPERATOR NAME, LEA UNIT LETTER, SECTION PERMANENTLY STAMP The location has been leveled as other production equipment. Anchors, dead men, tie downs an If this is a one-well lease or last r OCD rules and the terms of the Opera from lease and well location. All metal bolts and other materials to be removed.) All other environmental concerns Pipelines and flow lines have been retrieved flow lines and pipelines. If this is a one-well lease or last relocation, except for utility's distribution	compliance with OCD rules and the terms of the Ope ed and leveled. Cathodic protection holes have been eter and at least 4' above ground level has been set in SE NAME, WELL NUMBER, API NUMBER, QUIL TOWNSHIP, AND RANGE. All INFORMATION ED ON THE MARKER'S SURFACE. Inearly as possible to original ground contour and has derisers have been cut off at least two feet below ground emaining well on lease, the battery and pit location(s) tor's pit permit and closure plan. All flow lines, products have been removed. Portable bases have been removed as have been addressed as per OCD rules. In abandoned in accordance with 19.15.35.10 NMAC emaining well on lease: all electrical service poles and infrastructure.	rator's pit permit and closure plan. properly abandoned. a concrete. It shows the JARTER/QUARTER LOCATION OR DN HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with fluction equipment and junk have been removed eved. (Poured onsite concrete bases do not have a concrete bases do not have been removed from non-dulines have been removed from lease and well sedule an inspection.
All pits have been remediated in Rat hole and cellar have been fill A steel marker at least 4" in diam OPERATOR NAME, LEA UNIT LETTER, SECTION PERMANENTLY STAMP The location has been leveled as other production equipment. Anchors, dead men, tie downs an If this is a one-well lease or last r OCD rules and the terms of the Opera from lease and well location. All metal bolts and other materials to be removed.) All other environmental concerns Pipelines and flow lines have bee retrieved flow lines and pipelines. If this is a one-well lease or last r location, except for utility's distribution. When all work has been completed, resident sides of the completed of the of the complete of the completed of the completed of the completed of the completed of the complete of the complet	compliance with OCD rules and the terms of the Ope ed and leveled. Cathodic protection holes have been eter and at least 4' above ground level has been set in SE NAME, WELL NUMBER, API NUMBER, QUI, TOWNSHIP, AND RANGE. All INFORMATION ED ON THE MARKER'S SURFACE. Inearly as possible to original ground contour and has drisers have been cut off at least two feet below ground emaining well on lease, the battery and pit location(s) tor's pit permit and closure plan. All flow lines, product in abandoned in accordance with 19.15.35.10 NMAC emaining well on lease: all electrical service poles and infrastructure. Esturn this form to the appropriate District office to scheme the content of the properties of the content of the properties. TITLE:	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the JARTER/QUARTER LOCATION OR DN HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with fluction equipment and junk have been removed oved. (Poured onsite concrete bases do not have a lines have been removed from non-d lines have been removed from lease and well needule an inspection. DATE: 10/14/14 1/24/14
All pits have been remediated in Rat hole and cellar have been fill A steel marker at least 4" in diam OPERATOR NAME, LEA UNIT LETTER, SECTION PERMANENTLY STAMP The location has been leveled as other production equipment. Anchors, dead men, tie downs an If this is a one-well lease or last r OCD rules and the terms of the Opera from lease and well location. All metal bolts and other materials to be removed.) All other environmental concerns Pipelines and flow lines have bee retrieved flow lines and pipelines. If this is a one-well lease or last r location, except for utility's distribution. When all work has been completed, resident and the second pipelines. TYPE OR PRINT NAME: Jon Ru	compliance with OCD rules and the terms of the Ope ed and leveled. Cathodic protection holes have been eter and at least 4' above ground level has been set in SE NAME, WELL NUMBER, API NUMBER, QUI, TOWNSHIP, AND RANGE. All INFORMATION ED ON THE MARKER'S SURFACE. Inearly as possible to original ground contour and has drisers have been cut off at least two feet below ground emaining well on lease, the battery and pit location(s) tor's pit permit and closure plan. All flow lines, product in abandoned in accordance with 19.15.35.10 NMAC emaining well on lease: all electrical service poles and infrastructure. Extern this form to the appropriate District office to scheme the content of the properties of the content of the properties. TITLE:	rator's pit permit and closure plan. properly abandoned. a concrete. It shows the JARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with fluction equipment and junk have been removed eved. (Poured onsite concrete bases do not have eved. All fluids have been removed from non-d lines have been removed from lease and well evedule an inspection.
All pits have been remediated in Rat hole and cellar have been fill A steel marker at least 4" in diam OPERATOR NAME, LEA UNIT LETTER, SECTION PERMANENTLY STAMP The location has been leveled as other production equipment. Anchors, dead men, tie downs an If this is a one-well lease or last r OCD rules and the terms of the Opera from lease and well location. All metal bolts and other materials to be removed.) All other environmental concerns Pipelines and flow lines have bee retrieved flow lines and pipelines. If this is a one-well lease or last r location, except for utility's distribution. When all work has been completed, resident sides of the completed of the of the complete of the completed of the completed of the completed of the completed of the complete of the complet	compliance with OCD rules and the terms of the Ope ed and leveled. Cathodic protection holes have been eter and at least 4' above ground level has been set in SE NAME, WELL NUMBER, API NUMBER, QUI, TOWNSHIP, AND RANGE. All INFORMATION ED ON THE MARKER'S SURFACE. Inearly as possible to original ground contour and has drisers have been cut off at least two feet below ground emaining well on lease, the battery and pit location(s) tor's pit permit and closure plan. All flow lines, product in abandoned in accordance with 19.15.35.10 NMAC emaining well on lease: all electrical service poles and infrastructure. Esturn this form to the appropriate District office to scheme the content of the properties of the content of the properties. TITLE:	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the JARTER/QUARTER LOCATION OR DN HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with fluction equipment and junk have been removed oved. (Poured onsite concrete bases do not have a lines have been removed from non-d lines have been removed from lease and well needule an inspection. DATE: 10/14/14 1/24/14
All pits have been remediated in Rat hole and cellar have been fill A steel marker at least 4" in diam OPERATOR NAME, LEA UNIT LETTER, SECTION PERMANENTLY STAMP The location has been leveled as other production equipment. Anchors, dead men, tie downs an If this is a one-well lease or last r OCD rules and the terms of the Opera from lease and well location. All metal bolts and other materials to be removed.) All other environmental concerns Pipelines and flow lines have bee retrieved flow lines and pipelines. If this is a one-well lease or last r location, except for utility's distribution. When all work has been completed, resident and the second pipelines. TYPE OR PRINT NAME: Jon Ru	compliance with OCD rules and the terms of the Ope ed and leveled. Cathodic protection holes have been eter and at least 4' above ground level has been set in SE NAME, WELL NUMBER, API NUMBER, QUI, TOWNSHIP, AND RANGE. All INFORMATION ED ON THE MARKER'S SURFACE. Inearly as possible to original ground contour and has drisers have been cut off at least two feet below ground emaining well on lease, the battery and pit location(s) tor's pit permit and closure plan. All flow lines, product in abandoned in accordance with 19.15.35.10 NMAC emaining well on lease: all electrical service poles and infrastructure. Esturn this form to the appropriate District office to scheme the content of the properties of the content of the properties. TITLE:	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the JARTER/QUARTER LOCATION OR DN HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with fluction equipment and junk have been removed oved. (Poured onsite concrete bases do not have a lines have been removed from non-d lines have been removed from lease and well needule an inspection. DATE: 10/14/14 1/24/14
All pits have been remediated in Rat hole and cellar have been fill A steel marker at least 4" in diam OPERATOR NAME, LEA UNIT LETTER, SECTION PERMANENTLY STAMP The location has been leveled as other production equipment. Anchors, dead men, tie downs an If this is a one-well lease or last r OCD rules and the terms of the Opera from lease and well location. All metal bolts and other materials to be removed.) All other environmental concerns Pipelines and flow lines have bee retrieved flow lines and pipelines. If this is a one-well lease or last r location, except for utility's distribution. When all work has been completed, resident and the second pipelines. TYPE OR PRINT NAME: Jon Ru	compliance with OCD rules and the terms of the Ope ed and leveled. Cathodic protection holes have been eter and at least 4' above ground level has been set in SE NAME, WELL NUMBER, API NUMBER, QUI, TOWNSHIP, AND RANGE. All INFORMATION ED ON THE MARKER'S SURFACE. Inearly as possible to original ground contour and has drisers have been cut off at least two feet below ground emaining well on lease, the battery and pit location(s) tor's pit permit and closure plan. All flow lines, product in abandoned in accordance with 19.15.35.10 NMAC emaining well on lease: all electrical service poles and infrastructure. Esturn this form to the appropriate District office to scheme the content of the properties of the content of the properties. TITLE:	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the JARTER/QUARTER LOCATION OR DN HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with fluction equipment and junk have been removed oved. (Poured onsite concrete bases do not have a lines have been removed from non-d lines have been removed from lease and well needule an inspection. DATE: 10/14/14 1/24/14

DEC 0 5 2015 M