Susana Martinez Governor

David Martin Cabinet Secretary-Designate

Brett F. Woods, Ph.D. Deputy Cabinet Secretary

January 8, 2015

Armstrong Energy Corp ATT: Regulatory P O Box 1973 Roswell, NM 88022 David Catanach Division Director Oil Conservation Division



RE: Hard Days Night #1-N, 10-6s-33e, API # 30-041-20963 Whiskey River #10, 15-6s-33e, API # 30-041-20964

Dear Operator:

The following inspection(s) of the well files indicate that the well(s) have been drilled, but the operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail attachments. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situations brought into compliance.

Rule 19.15.16 states that completion forms must be filed within 20 days after completion of the well. Per each attachment is a list of what is required for each well.

Please Note: Delay in processing of regulatory forms may result in operator receiving production and dispositions error messages generated by C-115 reporting.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due" by January 30, 2015, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon these wells.

Sincerely,

Donna Mull

Line Manager Hobbs OCD District Office

API # 3()=041=20963»	OPERATOR ARMSTRONG ENERGY CORP	WELL NAME HARD DAY	WELL #

We have received your completion paperwork on the well listed above. However, before we can approve it, we need the following submitted: (Marked by XXXXX)

	Need C-103 or BLM 3160-5 Subsequent Report on all strings of Casing & Cement		
XXXXX Need C-103 or BLM 3160-5 Subsequent Report on how well was completed			
XXXXX	Need Deviation Survey		
	Need Directional Drill Survey		
	Need C-102 with correct Bottomhole Location (Directional or Horizontal wells only)		
XXXXX Need to submit logs run on well			
XXXXX	Need C-104		
XXXXX	Need C-105 or BLM 3160-4		

Missing info on C-103	
Missing info on C-104	
Missing info on C-105	
Need logs run on well	······

 OTHERS	 	 			

With <u>the exception of logs</u>, these can be submitted by e-mail. Please notify me by email when sending information requested

PLEASE NOTE: Delay in processing of regulatory forms may result in operator receiving production and dispositions error messages generated by C-115 reporting.

	API # 30:041:20964 >	OPERATOR ARMSTRONG ENERGY CORP	WELL NAME_ WHISKEY_RIVER	WELL # _ 001 >
1				

We have received your completion paperwork on the well listed above. However, before we can approve it, we need the following submitted: (Marked by XXXXX)

	Need C-103 or BLM 3160-5 Subsequent Report on all strings of Casing & Cement		
XXXXX Need C-103 or BLM 3160-5 Subsequent Report on how well was completed			
XXXXX	Need Deviation Survey		
	Need Directional Drill Survey		
	Need C-102 with correct Bottomhole Location (Directional or Horizontal wells only)		
XXXXX	Need to submit logs run on well		
XXXXX	Need C-104		
XXXXX	Need C-105 or BLM 3160-4		

Missing info on C-103	
Missing info on C-104	
Missing info on C-105	
Need logs run on well	

 OTHERS

With <u>the exception of logs</u>, these can be submitted by e-mail. Please notify me by email when sending information requested

PLEASE NOTE: Delay in processing of regulatory forms may result in operator receiving production and dispositions error messages generated by C-115 reporting.