State of New Mexico DISTRICT I

1825 N. PRINCE DR. HOBBS. NH. 85240
Franci (876) 363-6161 Fam (876) 363-6172

Energy, Minerals & Natural Resources Department

DISTRICT II 611 S. FIRST ST., ARTESIA, NM 68210 Phone: (675) 748-1283 Fazz (675) 748-9726


CONSERVATION DIVISION 1220 SOUTH ST. FRANCIS DR.

Form C-102 Revised August 1, 2011 Submit one copy to appropriate District Office

DISTRICT III 1000 RIO BRAZOS RD., AZTEC, NM 87410 Phone: (808) 334-8178 Fax: (808) 334-8170 DISTRICT IV 1220 S. ST. FRANCIS DE., SANTA FZ, NW 57605 Phone: (505) 478-3460 Fax: (505) 478-3462 Santa Fe, New Mexico 87505

O AMENDED REPORT

API Number 30-025-42-52-3			Pool Code 98110 WC-025 G-09 5253509D; 1			3509D.B	NE GA		
714771		Property Name SKULL CAP STATE COM					Well Number 2H		
OGRID No. 229137			COG OPERATING, LLC				glevation 3286.0		
					Surface Loc	ation			
UL or lot No.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County
J	32	24-S	35-E		2590	SOUTH	1980	EAST	LEA
			Bottom	Hole Loc	ation If Diffe	erent From Sur	face		
UL or lot No.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Fest from the	East/West line	County
J	5	25-S	35-E		1650	SOUTH	1980	EAŞT	LEA .
Dedicated Acres	Joint o	r Infill Co	nsolidation	Code Ore	ier No.	**************************************		1	
200.72	1			1					
NO ALLO	WABLE V					ONTIL ALL INTER APPROVED BY		EEN CONSOLIDA	TED
				[OPERAT	OR CERTIFICA	TION



CONDITIONS OF APPROVAL

API#	Operator	Well name & Number
30-025-42523	COG OPERATING LLC	SKULL CAP STATE COM # 002H
Applicable cond	itions of approval marked with)	XXXXXX

Administra	tive Orders Required	
XXXXXX	Will require administrative order for non-standard location prior to placing the well on production	
XXXXXXX	Will require administrative order for non-standard spacing unit	
Other wells		
Drilling		
XXXXXXX	Once the well is spud, to prevent ground water contamination through whole or partial conduits from the surface, the operator shall drill without interruption through the fresh water zone or zones and shall immediately set in cement the water protection string	
Casing	<u></u>	
XXXXXXX	SURFACE & INTERNEMIATE(1) CASING - Cement must circulate to surface	
XXXXXX	PRODUCTION CASING - Cement must tie back into intermediate casing	
XXXXXX	LINER - Cement must tie back into production casing	
XXXXXX	If cement does not circulate to surface, must run temperature survey or other log to determine top of cement	

Pits

XXXXXXX

XXXXXX	If using a pit for drilling and completions, must have an approved pit form prior to spudding the well
	·
	·

Surface casing must be set 25' below top of Rustler Anhydrite in order to seal off protectable water

Completion & Production

South Area

XXXXXXX	Will require a directional survey with the C-104

Potash Area

 Not Applicable