
Submit 3 Copie Office	s To Appropriate District	г .	Form C-103							
District 1	D. Hakka NM 97240	Energy, N	Iinerals and Nat	urai Resou	rces	WELL A	PLNO		June 19, 2	2008
1625 N. French Dr., Hobbs, NM 87240  District II  OIL CONSERVATION DIVISION						WEELA	30- <u>0</u> 25-	12783		
1301 W. Grand Ave., Artesia, NM 88210 District III  1220 South St. Francis Dr.						5. Indicate Type of Lease				
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505						STATE X FEE				
District IV. 1220 S. St. Francis Dr., Santa Fe, NM						6. State Oil & Gas Lease No.				
87505										
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  1. Type of Well:  Oil Well:  Oil Well:  Other WIW  2. Name of Operator						7. Lease Name or Unit Agreement Name:  North Hobbs G/SA Unit  8. Well Number  411  9. OGRID Number				
	ntal Permian Ltd.						15798			
3. Address of Operator P.O. Box 4294, Houston, TX 77210-4294						10. Pool name or Wildcat  Hobbs: Grayburg-San Andres				
4. Well Loca		X //210-42	294	<u> </u>		HODD	<u>s: Graybu</u>	<u>rg-San An</u>	<u>iares</u>	
Unit Le		_330 fee	t from the No	rth li	ne and	330	_ feet from	the E	ast	line
Section	23	To	wnship 18-S	Range	37-E	NMPM		County	Lea	
Section	25		on (Show whether				el e	County	Lea	
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			86' DF						2
	12 Check A	nnronriate I	Box to Indicate	Nature of	f Notice J	Penart a	· Other D			_
	12. Check 11	ppropriater	Jox to indicate	ivature or	r rouce, r	ceport, or	Outer D	ata		
	NATIOE OF INT	-NITION T	<b>^</b>	1	0110	0501151	UT DED	0DT 0E		
NOTICE OF INTENTION TO: SUB						SEQUENT REPORT OF:				
ERFORM RE	EMEDIAL WORK 🔲 🗀	PLUG AND	ABANDON 🔲	REMEDIA	AL WORK		X	ALTERIN	G CASING	; 🗀
EMPORARILY ABANDON						NG OPNS.		P AND A		
'ULL OR ALT	FR CASING	MULTIPLE	COMPL	CASING/	CEMENT JO	ОВ				
	COMMINGLE						<u>—</u>			
OWINHOLE	COMMININGLE L									
THER:				OTHER:						
	proposed or complete g any proposed work). pletion.									
						Cancl Well Create Pool				
See Attached						Cor	np f	G New P&A Loc Chng_	TA	ās JA
Spud Date:	RU - 3/30/1	5	Rig Rele	ase Date:	RE	) - 4/6/1	5			
hereby certif	y that the information:	above is true a	nd complete to the	e best of my	knowledge	and belief	f.			_
SIGNATURE	110.1.51		TI7	_	_			DATE5	5/18/15	
.01.11.0182						ephens@ox	y.com			<u>515</u> 8
-		l				٠.				
or State Use	/5 an X		1	<	L CC -		_		10,10 -	–
APPROVED I	_ ,	mama	<u>h</u> TI	TLE	iart M)	anage	<u> </u>	ATE	196/30	<u>/</u>
onditions of	Approval (if any):								Å	/ 、



North Hobbs G/SA Unit No. 411 API No. 30-025-12783 UL A, Sec. 23, T-18-S, R-38-E Lea Co.. NM

3/30/15 - 4/6/15:

MI x RU pulling unit. Pressure test tubing to 2000 psi x lost 80 psi in 10 minutes; casing held good at 600 psi. ND WH x NU BOP. Circulate well with 120 bbls FW. Latch on to packer x retest tubing and was still leaking. POOH w/128 jts injection tubing. RBIH with on/off tool x 128 jts new duoline injection tubing. Test tubing to 2000 psi x leaked 100 psi in 15 minutes. RU Archer WL x POOH w/tubing,  $4 \cdot 1/2$ " KTC hydraulic packer, &  $4 \cdot 1/2$ " injection packer. RBIH with exchange KTC x injection packers on 127 jts. duoline 20 injection tubing  $(4 \cdot 1/2$ " Arrowset 1-X injection packer set at 4131'). Test packer to 600 psi and tubing to 1200 psi (held). Circulate well w/125 bbls 10# packer fluid. ND BOP x NU WH. Run MIT for the NMOCD - initial pressure 500 psi, final pressure 500 psi. Hook up injection line x RD pulling unit x clean location.

Note: This was a continuation of the work done on 3/12/15 - 3/17/15 (copy of approved subsequent report C-103 is attached).

BS 5/24/2015