Submit I Copy To Office	Appropriate District	State of New Mexico		Form C-103	
	trict 1 – (575) 393-6161 Energy, Minerals and Natural Resources		tural Resources	Revised August 1, 2011 WELL API NO.	
	625 N. French Dr., Hobbs, NM 88240 Pistrict II – (575) 748-1283			30-015-24759	
811 S. First St., Ar	811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 Sente Fe NIM 87505			30 013 24737	
1000 Rio Brazos R				5. Indicate Type of Lease STATE X FEE	
District IV = (505) 476-3460 Salita Fe, INIVI 873US 1220 S. St. Francis Dr., Santa Fe, NM			6. State Oil & Gas Lease No.		
87505			o. State on & Gas Lease No.		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other				7. Lease Name or Unit Agreement Name	
				-	
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-10 1770 R SUCH PROPOSALS)				Diamond State	
1. Type of Well: Oil Well X Gas Well Other				8. Well Number 001	
2. Name of Operator				9. OGRID Number	
State of New Mexico formerly Marks and Garner				14070	
3. Address of Operator			10. Pool name or Wildcat		
3. Address of Operator 811 S First St Artesia, NM 88210 4. Well Location			Cave GB/SA		
4. Well Location					
Unit LetterO:330feet from theSouth line and2310feet from theEastline					
Section 4 Township 17S Range 29E NMPM Eddy County					
11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
E-PERMITTING <swdinjection> SUBSEQUENT REPORT OF:</swdinjection>					
CONVERSION RBDMS REMEDIAL WORK				_	
RETURN TO TA COMMENCE DRILL					
CSNG CHG LOC CASING/CEMENT JOB					
INT TO PAP&A R_P&A R					
OTHER:			OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date					
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of					
proposed completion or recompletion.					
Groupoto A. A. C. C. A.					
3/28/2013	Moved in rigged up. Attempted to blow down. Well started kicking fluid. SION. Will kill well in the morning and proceed.				
2/20/2012	VOOCOOLO VIII I II I I II I DOD Marala L'ar Constant Constant A DIII with talking and constant DOOL and DIII with				
3/29/2013	Killed well. Installed BOP. Moved tubing from the Cave St. #4. RIH with tubing and scrapper. POOH and RIH w 5 ½" CIBP and set at 2441. Circulated with mud and spotted 25 sx class c cement on top of CIBP. POOH to 1818				
	and spotted 25 sx class c cement. POOH with setting tool and SION.				
and spotted 25 sx class c cement. I oon with setting tool and orox.					
4/1/2013	RIH to 407' and circulated cement to surface. Laid down tubing and filled 5 ½" casing to surface. Rigged down, cut				
	off wellhead and installed dry hole marker. Cut off anchors.				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
Thereby certify that the information above is true and complete to the best of my knowledge and benefit					
SIGNATURE_		TITLE		DATE	
Toma an antick :	ma 0	الدادة المسالة		PHONE:	
For State Use Only					
M 1 KK					
APPROVED BY: Maley Stawn TITLE Dest. Supervisor DATE 6/9/2015					
Conditions of Approval (if any):					
	l <i>J</i>			•-	

JU" 0 9 2015