

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised July 18, 2013

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr. **HOBBS OCD**
 Santa Fe, NM 87505

WELL API NO.	30-025-29474 ✓
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	302601
7. Lease Name or Unit Agreement Name	NM BG STATE NCT 1 ✓
8. Well Number	008 ✓
9. OGRID Number	213190
10. Pool name or Wildcat	SAUNDERS PERMO UPPER PENN
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	GL 4193

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other

2. Name of Operator: CROWNQUEST OPERATING LLC ✓

3. Address of Operator: P.O. BOX 53310, MIDLAND, TX 79710

4. Well Location
 Unit Letter A : 660 feet from the NORTH line and 455 feet from the EAST line
 Section 14 Township 14S Range 33E NMPM County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
 GL 4193

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

E-PERMITTING <SWD INJECTION> F CONVERSION _____ RBDMS _____ T RETURN TO _____ TA _____ F CSNG _____ ENVIRO _____ CHG LOC _____ E INT TO PA _____ P&A NR _____ P&A R _____ C _____ OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input checked="" type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>
--	--

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 7/14/15: MIRU AND FOUND STUCK TUBING
- 7/15/15: WL FREEPOINT @ 7755', OCD APPROVED CUT @ 7745'
- 7/20/15: PUMPED 50 SXS CLASS C @ 7745' OCD APPROVED. RIH W 4.5" GAUGE RING AND TAGGED OBSTRUCTION @ 6138'
- 7/21/15: RIH W BIT AND SCRAPER TO 7730'. POOH W TBG AND SCRAPER. RIH W CIBP AND TAG FISH @ 7745'. POOH TO 7730' AND SET CIBP. RIH W TUBING AND TAGGED PLUG. CIRCULATED HOLE WITH MLF AND PRESSURED UP CASING TO 540 PSI. PRESSURE HELD FOR 15 MINUTES; GOOD TEST.
- 7/22/15: PUMPED 30 SXS CLASS C TO CAP CIBP. WOC 4 HRS AND TAG TOC AT 7580'. OCD APPROVED. POOH TO 7100' AND PUMPED 35 SXS CLASS C.
- 7/23/15: TUBING STUCK. RIH W K-BARS ON SANLINE AND TAG TOC @ 6600'. WIRLINE FREEPOINT AT 5300'. OCD APPROVED CUT @ 5296'.
- 7/24/15: RIH W TUBING TO 5275'. PUMPED 25 SXS CLASS C.
- 7/27/15: TAGGED PLUG @ 4825'. OCD APPROVED. POOH TO 4285' AND PUMPED 35 SXS OF CLASS C.
- 7/28/15: TAGGED PLUG @ 4089'. OCD APPROVED. POOH TO 1858' AND PUMPED 35 SXS OF CLASS C. TAGGED PLUG @ 1479'. OCD APPROVED. POOH TO 350' AND PUMPED 20 SXS CLASS C BEFORE RUNNING OUT. FINISH SURFACE PLUG IN AM.
- 7/29/15: TAGGED TOC @ 144'. PUMPED 14 SXS OF CLASS C AND BROKE CIRCULATION WITH CEMENT. DUG OUT CELLAR 5 FT.
- 7/30/15: CUT AND CAPPED WELLHEAD WITH SURFACE MARKER. CUT ANCHORS OFF 3' BELOW SURFACE.

Spud Date: 7/14/2015 ✓ Rig Release Date: 7/30/2015 ✓

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Zachariah Jones TITLE LEASE MANAGER III DATE 9/16/15

Type or print name ZACHARIAH JONES E-mail address: zjones@crowquest.com PHONE: 432-288-4726

For State Use Only

APPROVED BY: Marys Brown TITLE Dist. Supervisor DATE 9/21/2015

Conditions of Approval (if any):

SEP 23 2015 *jm*