

Submit 1 Copy To Appropriate District  
Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised August 1, 2011

|   |  |  |
|---|--|--|
| <b>SUNDRY NOTICES AND REPORTS ON WELLS</b><br>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) |  | WELL API NO.<br>30-025-34946   |
| 1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other: Injector   |  | 5. Indicate Type of Lease<br>STATE <input checked="" type="checkbox"/> FEE <input checked="" type="checkbox"/> |
| 2. Name of Operator<br>Occidental Permian Ltd.  |  | 6. State Oil & Gas Lease No.<br>19552  |
| 3. Address of Operator<br>HCR 1 Box 90 Denver City, TX 79323  |  | 7. Lease Name or Unit Agreement Name<br>South Hobbs (G/SA) Unit  |
| 4. Well Location<br>Unit Letter <u>I</u> : <u>1984</u> feet from the <u>South</u> line and <u>370</u> feet from the <u>East</u> line<br>Section <u>5</u> Township <u>19S</u> Range <u>38E</u> NMPM Lea County |  | 8. Well Number: 239  |
| 11. Elevation (Show whether DR, RKB, RT, GR, etc.)<br>3624' KB  |  | 9. OGRID Number: 157984  |
|   |  | 10. Pool name or Wildcat Hobbs (G/SA)  |

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. MIRU Pulling Unit
2. POOH with injection assembly
3. Set CIBP above current open pay to shutoff injection (top perf @ 4085')
4. Selectively perforate interval 4030'-4060'
5. RIH with injection equipment. CHART TEST
6. Return well to injection.
- 7.
- 8.
- 9.
- 10.

During this procedure we plan to use  
the closed-loop system with a steel  
tank and haul contents to the required  
disposal per ODC Rule 19.15.17

Condition of Approval: notify

OCD Hobbs office 24 hours

prior of running MIT Test & Chart

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Production Eng

DATE 03/15/16

Type or print name

E-mail address

PHONE:

For State Use Only

APPROVED BY:

TITLE Dist Supervisor

DATE 3/16/2016

Conditions of Approval (if any):

MAR 16 2016