

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-40813
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other SWD		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator MESQUITE SWD, INC.		6. State Oil & Gas Lease No. SWD-1324 LC063200
3. Address of Operator PO BOX 1479, CARLSBAD NM 88221		7. Lease Name or Unit Agreement Name PADUCA
4. Well Location Unit Letter _____ : 500 _____ feet from the _____ S _____ line and _____ 2000 _____ feet from the _____ E _____ line Section 22 Township T25S Range 32E NMPM County LEA		8. Well Number 2
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 161968
		10. Pool name or Wildcat

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
CLOSED-LOOP SYSTEM <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.


REMEDIAL WORK TO CLEAN OUT WELL BORE, AND PERFORATIONS.

MOVE IN AND RIG UP PULLING UNIT, KILL WELL, NIPPLE UP BOP, UNSEAT PACKER AND LAY DOWN 4.5" PRODUCTION TUBING. RIH WITH 7" SCRAPER AND BIT TO TD. CLEAN OUT WELL BORE, LAY DOWN WORK STRING, RIH WITH PRODUCTION PACKER AND PRODUCTION TUBING, SET PACKER, CIRCULATE PACKER FLUID, NIPPLE UP WELL HEAD, TEST BACK SIDE, RIG DOWN PULLING UNIT.

WORK TO BE STARTED AS SOON AS APPROVAL IS RECEIVED. ESTIMATED TIME OF WORK IS 4 DAYS

Spud Date:

Rig Release Date:



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Riley G Neatherline TITLE Production Foreman DATE 3/18/16
Type or print name Riley G Neatherline E-mail address: Rgneatherline@gmail.com PHONE: 575 706 7288
For State Use Only

APPROVED BY: [Signature] TITLE Petroleum Engineer DATE 03/18/16
Conditions of Approval (if any):

MAR 21 2016