Submit I Copy To Appropriate District State of New Me Office District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	exico Form C-103
District 1 – (575) 393-6161 Pracryy, Minerals and Natu	ral Resources Revised August 1, 2011 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	30-025-43026
	5. Indicate Type of Lease
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 District III - (503) 334-6178 District III - (503) 334-6178 1000 Rio Brezzo Rd. Artes NM 8710	ncis Dr. STATE S FEE
District IV - (505) 476-3460 Santa Fe, NM 8	
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PL DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FO PROPOSALS.)	OR SUCH
1. Type of Well: Oil Well Gas Well Other	8. Well Number 24-663
2. Name of Operator	9. OGRID Number: 157984
Occidental Permian Ltd.	
3. Address of Operator	10. Pool name or Wildcat: Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	
4. Well Location Unit LetterB_:_ 99_feet from the _North line a	
Section 24 Township 18S	
11. Elevation (Show whether DR	, RKB, RT, GR, etc.)
3674.2' (GL)	
10 (1) 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	CAVIT D O.I. D.
12. Check Appropriate Box to Indicate N	ature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐	
PULL OR ALTER CASING MULTIPLE COMPL	CASING/CEMENT JOB
DOWNHOLE COMMINGLE	_
_	
OTHER: Initial Completion	OTHER:
 Describe proposed or completed operations. (Clearly state all of starting any proposed work). SEE RULE 19.15.7.14 NMAG 	
proposed completion or recompletion.	c. For Multiple Completions. Attach wellbore diagram of
proposed completion of recompletion.	
1) Drill Out DV tool to Float Collar	
RU wireline & run CNL/GR/CBL/CCL per prog	During this procedure we plan to use
3) Perforate and acid treat San Andres formation the closed-loop system with a steel	
4) RIH w/ ESP production equipment 5) Turn well to production tank and haul contents to the requir	
disposal per ODC Rule 19.15.17	
Spud Date: Rig Release Da	ate:
I hereby certify that the information above is true and complete to the b	est of my knowledge and belief.
111	
SIGNATURE SIGNATURE Produ	action Engineer DATE 3/29/2016
SIGNATURE TOOL	Ction Engineer DATE 3/29/2010
Type or print name Jacob S. Cox E-mail address: Jacob C	ox@oxy.com PHONE: _713-497-2053
For State Use Only 11	
Wal Man 1	16. 000/4/20 2/20/2011
APPROVED BY: / CALLY CTITLE DU	1 SUPRIMICO DATE 3/29/2014
Conditions of Approval (if any):	