| Submit 1 Copy To Appropriate District Office | State of New Mexico Energy, Minerals and Natural Resources | | Form C-103 October 13, 2009 |
|---|--|---|---|
| District I 1625 N. French Dr., Hobbs, NM 88240 | Energy, witherars and tvatur | ai Resources | WELL API NO. |
| District II | OIL CONSERVATION | DIVISION | 30-025-04168 |
| 1301 W. Grand Ave., Artesia, NM 88210 District III | 1220 South St. Francis Dr. | | 5. Indicate Type of Lease |
| 1000 Rio Brazos Rd., Aztec, NM 87410 | Santa Fe, NM 875 | | STATE FEE |
| District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 | Santa Pe, Nivi 67. | 303 | 6. State Oil & Gas Lease No. |
| | CES AND REPORTS ON WELLS | | 7. Lease Name or Unit Agreement Name |
| (DO NOT USE THIS FORM FOR PROPOSE DIFFERENT RESERVOIR. USE "APPLICE" | ALS TO DRILL OR TO DEEPEN OR PLU ATION FOR PERMIT" (FORM C-101) FOR | | North Monument G/SA Unit Blk. 18 |
| PROPOSALS.) | Cas Wall Other Injection well | | 8. Well Number 07 |
| | Gas Well Other Injection well | BBS OCD | 9. OGRID Number 873 |
| 2. Name of Operator Apache Corp. | 110. | | 9. OGRID Number 8/3 |
| 3. Address of Operator | MA. | AR 31 2016 | 10. Pool name or Wildcat |
| P O box Drawer D Monument NM | 88265 | 411 0 1 2010 | North Monument G/SA |
| 4. Well Location | | CEIVED | |
| Unit LetterG: | 1980feet from theN | ECEIVED line and _ | 1980feet from the |
| Eline | | | |
| Section 2 | Township 20S | Range 36E | NMPM Lea County |
| | 11. Elevation (Show whether DR, | RKB, RT , GR , $etc.$) | |
| | | | |
| 12 Charles | manamista Day to Indicate No | tuna of Nation | Demont on Other Date |
| 12. Check A | ppropriate Box to Indicate Na | iture of Notice, | Report of Other Data |
| NOTICE OF IN | TENTION TO: | SUB | SEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK | | REMEDIAL WORK | |
| TEMPORARILY ABANDON | CHANGE PLANS | COMMENCE DRI | LLING OPNS. P AND A |
| PULL OR ALTER CASING | MULTIPLE COMPL | CASING/CEMENT | JOB 🗆 |
| DOWNHOLE COMMINGLE | | | |
| | | | |
| OTHER: | | OTHER: | 5 year pressure test |
| | | | 5 year pressure test |
| 13. Describe proposed or complete | eted operations. (Clearly state all pe | ertinent details, and | d give pertinent dates, including estimated date |
| 13. Describe proposed or complete of starting any proposed wo | eted operations. (Clearly state all peck). SEE RULE 19.15.7.14 NMAC. | ertinent details, and | |
| 13. Describe proposed or complete | eted operations. (Clearly state all peck). SEE RULE 19.15.7.14 NMAC. | ertinent details, and | d give pertinent dates, including estimated date |
| 13. Describe proposed or complete of starting any proposed wo | eted operations. (Clearly state all peck). SEE RULE 19.15.7.14 NMAC. | ertinent details, and | d give pertinent dates, including estimated date |
| 13. Describe proposed or complete of starting any proposed wo proposed completion or reco | eted operations. (Clearly state all periods). SEE RULE 19.15.7.14 NMAC. ompletion. | ertinent details, and For Multiple Con | d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of |
| 13. Describe proposed or complete of starting any proposed wo proposed completion or reco | eted operations. (Clearly state all periods). SEE RULE 19.15.7.14 NMAC. ompletion. | ertinent details, and For Multiple Con | d give pertinent dates, including estimated date |
| Describe proposed or complete of starting any proposed we proposed completion or recommendation. Move in Maclaskey pump truck to perform the proposed complete or recommendation. | eted operations. (Clearly state all periods). SEE RULE 19.15.7.14 NMAC. ompletion. | ertinent details, and For Multiple Con | d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of |
| Describe proposed or complete of starting any proposed we proposed completion or recommendation. Move in Maclaskey pump truck to perform the proposed complete or recommendation. | eted operations. (Clearly state all periods). SEE RULE 19.15.7.14 NMAC. ompletion. | ertinent details, and For Multiple Con | d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of |
| Describe proposed or complete of starting any proposed we proposed completion or recommendation. Move in Maclaskey pump truck to perform the proposed complete or recommendation. | eted operations. (Clearly state all periods). SEE RULE 19.15.7.14 NMAC. ompletion. | ertinent details, and For Multiple Con | d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of |
| Describe proposed or complete of starting any proposed we proposed completion or recommendation. Move in Maclaskey pump truck to perform the proposed complete or recommendation. | eted operations. (Clearly state all periods). SEE RULE 19.15.7.14 NMAC. ompletion. | ertinent details, and For Multiple Con | d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of |
| Describe proposed or complete of starting any proposed we proposed completion or recommendation. Move in Maclaskey pump truck to perform the proposed complete or recommendation. | eted operations. (Clearly state all periods). SEE RULE 19.15.7.14 NMAC. ompletion. | ertinent details, and For Multiple Con | d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of |
| Describe proposed or complete of starting any proposed we proposed completion or recommendation. Move in Maclaskey pump truck to perform the proposed complete or recommendation. | eted operations. (Clearly state all periods). SEE RULE 19.15.7.14 NMAC. ompletion. | ertinent details, and For Multiple Con | d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of |
| Describe proposed or complete of starting any proposed we proposed completion or recommendation. Move in Maclaskey pump truck to perform the proposed complete or recommendation. | eted operations. (Clearly state all periods). SEE RULE 19.15.7.14 NMAC. ompletion. | ertinent details, and For Multiple Con | d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of |
| Describe proposed or complete of starting any proposed we proposed completion or recommendation. Move in Maclaskey pump truck to perform the proposed complete or recommendation. | eted operations. (Clearly state all periods). SEE RULE 19.15.7.14 NMAC. ompletion. | ertinent details, and For Multiple Con | d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of |
| Describe proposed or complete of starting any proposed we proposed completion or recommendation. Move in Maclaskey pump truck to perform the proposed complete or recommendation. | eted operations. (Clearly state all periods). SEE RULE 19.15.7.14 NMAC. ompletion. | ertinent details, and For Multiple Con | d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of |
| 13. Describe proposed or complete of starting any proposed wo proposed completion or recommon Move in Maclaskey pump truck to perminutes with a 10 lb. loss to 530 psi. | eted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC. ompletion. rform pressure test on casing. Pressure test on casing. | ertinent details, and For Multiple Con | d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of |
| Describe proposed or complete of starting any proposed we proposed completion or recommendation. Move in Maclaskey pump truck to perform the proposed complete or recommendation. | eted operations. (Clearly state all periods). SEE RULE 19.15.7.14 NMAC. ompletion. | ertinent details, and For Multiple Con | d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of |
| 13. Describe proposed or complete of starting any proposed wo proposed completion or recommon Move in Maclaskey pump truck to perminutes with a 10 lb. loss to 530 psi. | eted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC. ompletion. rform pressure test on casing. Pressure test on casing. | ertinent details, and For Multiple Con | d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of |
| 13. Describe proposed or complete of starting any proposed we proposed completion or recommon Move in Maclaskey pump truck to perminutes with a 10 lb. loss to 530 psi. | eted operations. (Clearly state all perick). SEE RULE 19.15.7.14 NMAC. ompletion. rform pressure test on casing. Pressure Rig Release Date | ertinent details, and For Multiple Conduction with the casing to see: | d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of 540 psi & recorded the test on a chart for 32 |
| 13. Describe proposed or complete of starting any proposed wo proposed completion or recommon Move in Maclaskey pump truck to perminutes with a 10 lb. loss to 530 psi. | eted operations. (Clearly state all perick). SEE RULE 19.15.7.14 NMAC. ompletion. rform pressure test on casing. Pressure Rig Release Date | ertinent details, and For Multiple Conduction with the casing to see: | d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of 540 psi & recorded the test on a chart for 32 |
| 13. Describe proposed or complete of starting any proposed we proposed completion or recommon Move in Maclaskey pump truck to perminutes with a 10 lb. loss to 530 psi. | eted operations. (Clearly state all perick). SEE RULE 19.15.7.14 NMAC. ompletion. rform pressure test on casing. Pressure Rig Release Date | ertinent details, and For Multiple Conduction with the casing to see: | d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of 540 psi & recorded the test on a chart for 32 |
| 13. Describe proposed or complete of starting any proposed wo proposed completion or recommendate. Move in Maclaskey pump truck to perminutes with a 10 lb. loss to 530 psi. Spud Date: | Rig Release Date bove is true and complete to the besite of the besite of the box is true and complete to the besite of the box is true and the box is tr | ertinent details, and For Multiple Con ured the casing to see: | d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of 540 psi & recorded the test on a chart for 32 e and belief. |
| 13. Describe proposed or complete of starting any proposed we proposed completion or recommon Move in Maclaskey pump truck to perminutes with a 10 lb. loss to 530 psi. | Rig Release Date bove is true and complete to the besite of the besite of the box is true and complete to the besite of the box is true and the box is tr | ertinent details, and For Multiple Con ured the casing to see: | d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of 540 psi & recorded the test on a chart for 32 |
| 13. Describe proposed or complete of starting any proposed wo proposed completion or recommendate. Move in Maclaskey pump truck to perminutes with a 10 lb. loss to 530 psi. Spud Date: | Rig Release Date bove is true and complete to the bese and address: E-mail address: | ertinent details, and For Multiple Con ured the casing to set of my knowledge rument TechJD.Ellison@apa | and belief. DATE3/21/16 checcorp.com_PHONE: _575-441-7734 |
| 13. Describe proposed or complete of starting any proposed we proposed completion or recommendate. Move in Maclaskey pump truck to perminutes with a 10 lb. loss to 530 psi. Spud Date: I hereby certify that the information a SIGNATURE | Rig Release Date bove is true and complete to the bese and address: E-mail address: | ertinent details, and For Multiple Con ured the casing to set of my knowledge rument TechJD.Ellison@apa | and belief. DATE3/21/16 checcorp.com_PHONE: _575-441-7734 |
| 13. Describe proposed or complete of starting any proposed we proposed completion or recommendate. Move in Maclaskey pump truck to perminutes with a 10 lb. loss to 530 psi. Spud Date: I hereby certify that the information a SIGNATURE Type or print name Jim Ellison | Rig Release Date bove is true and complete to the bese and address: E-mail address: | ertinent details, and For Multiple Con ured the casing to set of my knowledge rument Tech | and belief. DATE3/21/16 checcorp.com_PHONE: _575-441-7734 |

