

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
June 19, 2008

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-22704
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name UNA
8. Well Number 1
9. OGRID Number 247692
10. Pool name or Wildcat BAGLEY PERMO PENN NORTH

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator JAY MANAGEMENT COMPANY, LLC

3. Address of Operator  
2425 WEST LOOP SOUTH, SUITE 810 HOUSTON, TX 77027

4. Well Location  
Unit Letter G : 1980 feet from the NORTH line and 1980 feet from the EAST line  
Section 32 Township 11S Range 33E NMPM County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
4287' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Plan to enter well, remove down hole production equipment.
2. TD the well and check for fill.
3. Run a retrievable bridge plug or packer to within 100 feet of uppermost perforations.
4. Pressure test to 500 psi for 30 minute.

Condition of Approval: notify  
OCD Hobbs office 24 hours  
prior of running MIT Test & Chart

C.O.A.  
SUBMIT CURRENT WELLBORE  
DIAGRAM WITH  
SUBSEQUENT C-103

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Operations Manager

DATE 04/18/2016

Type or print name Amir Sanker

E-mail address: asanker@isramco-jay.com

PHONE: 713-417-6530

For State Use Only

APPROVED BY:

TITLE

DATE

Conditions of Approval (if any):

NO PROD. REPORTED - 69 MONTHS

APR 22 2016