Office Energy, Minerals and Nati	xico	/ Form C-103
LOCAL DE LES MAIL MAL DOBIO	ral Resources	Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240 District II	WELL API NO. 30-025-03205	
811 S. First St., Artesia, NM 88210 OIL CONSERVATION	DIVISION 5 Indicate Type	of Lease
District III 1000 Rio Brazos Rd , Aztec, NM 87410 1220 South St. Fra	CIS Dr. STATE	FEE
District IV Santa Fe, NM 8	505 6. State Oil & G	as Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTICES AND REPORTS ON WELLS		or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PL DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) F	D SUCH	LIE MATTIX UNIT
PROPOSALS.)	8. well Number	
1. Type of Well: Oil Well Gas Well Other	144	
2. Name of Operator OXY USA WTP LP JUN 2	9. OGRID Num 192463	ber
3. Address of Operator	10. Pool name o	r Wildcat
PO BOX 4294; HOUSTON, TX 77210	I ANOT IT MAT	
4. Well Location		
Unit Letter_G : 1966 feet from the NORTH line and 1980	feet from the EAST line	
Section 5 Township 24S Range 37E NMPM	County LEA	and the second second
11. Elevation (Show whether DR		
32		
12. Check Appropriate Box to Indicate Nature of Notice, F	eport or Other Data	
NOTICE OF INTENTION TO:		POPT OF
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
PULL OR ALTER CASING MULTIPLE COMPL	CASING/CEMENT JOB	
		pm
OTHER: Constant of the section of t		
All pits have been remediated in compliance with OCD rules and Rat hole and cellar have been filled and leveled. Cathodic protect	te terms of the Operator's pit permit a	nd closure plan.
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the 		
OPERATOR NAME, LEASE NAME, WELL NUMBER,		
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE, All INFORMATION HAS BEEN WELDED OR		
PERMANENTLY STAMPED ON THE MARKER'S SUP		ELDED OR
	FACE.	ELDED OR
The location has been leveled as nearly as possible to original group	Contraction of the second	
other production equipment.	nd contour and has been cleared of all	
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least	nd contour and has been cleared of all wo feet below ground level.	junk, trash, flow lines and
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least If this is a one-well lease or last remaining well on lease, the batter	nd contour and has been cleared of all wo feet below ground level. y and pit location(s) have been remedi	junk, trash, flow lines and ated in compliance with
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least If this is a one-well lease or last remaining well on lease, the batter OCD rules and the terms of the Operator's pit permit and closure plan.	nd contour and has been cleared of all wo feet below ground level. y and pit location(s) have been remedi	junk, trash, flow lines and ated in compliance with
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least If this is a one-well lease or last remaining well on lease, the batter OCD rules and the terms of the Operator's pit permit and closure plan. from lease and well location.	nd contour and has been cleared of all wo feet below ground level. y and pit location(s) have been remedi All flow lines, production equipment	junk, trash, flow lines and ated in compliance with and junk have been removed
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least If this is a one-well lease or last remaining well on lease, the batter OCD rules and the terms of the Operator's pit permit and closure plan. from lease and well location. All metal bolts and other materials have been removed. Portable b	nd contour and has been cleared of all wo feet below ground level. y and pit location(s) have been remedi All flow lines, production equipment	junk, trash, flow lines and ated in compliance with and junk have been removed
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least If this is a one-well lease or last remaining well on lease, the batter OCD rules and the terms of the Operator's pit permit and closure plan. from lease and well location.	nd contour and has been cleared of all wo feet below ground level. y and pit location(s) have been remedi All flow lines, production equipment a ses have been removed. (Poured onsit	junk, trash, flow lines and ated in compliance with and junk have been removed
 other production equipment. Anchors, dead men, tie downs and risers have been cut off at least If this is a one-well lease or last remaining well on lease, the batter OCD rules and the terms of the Operator's pit permit and closure plan. from lease and well location. All metal bolts and other materials have been removed. Portable b to be removed.) All other environmental concerns have been addressed as per OCI Pipelines and flow lines have been abandoned in accordance with 	nd contour and has been cleared of all wo feet below ground level. y and pit location(s) have been remedi All flow lines, production equipment a ses have been removed. (Poured onsit rules.	junk, trash, flow lines and ated in compliance with and junk have been removed e concrete bases do not have
 other production equipment. Anchors, dead men, tie downs and risers have been cut off at least If this is a one-well lease or last remaining well on lease, the batter OCD rules and the terms of the Operator's pit permit and closure plan. from lease and well location. All metal bolts and other materials have been removed. Portable b to be removed.) All other environmental concerns have been addressed as per OCI Pipelines and flow lines have been abandoned in accordance with retrieved flow lines and pipelines. 	nd contour and has been cleared of all wo feet below ground level. y and pit location(s) have been remedi All flow lines, production equipment ses have been removed. (Poured onsit rules. 9.15.35.10 NMAC. All fluids have b	junk, trash, flow lines and ated in compliance with and junk have been removed e concrete bases do not have een removed from non-
 other production equipment. Anchors, dead men, tie downs and risers have been cut off at least If this is a one-well lease or last remaining well on lease, the batter OCD rules and the terms of the Operator's pit permit and closure plan. from lease and well location. All metal bolts and other materials have been removed. Portable b to be removed.) All other environmental concerns have been addressed as per OCI Pipelines and flow lines have been abandoned in accordance with retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electric 	nd contour and has been cleared of all wo feet below ground level. y and pit location(s) have been remedi All flow lines, production equipment ses have been removed. (Poured onsit rules. 9.15.35.10 NMAC. All fluids have b	junk, trash, flow lines and ated in compliance with and junk have been removed e concrete bases do not have een removed from non-
 other production equipment. Anchors, dead men, tie downs and risers have been cut off at least If this is a one-well lease or last remaining well on lease, the batter OCD rules and the terms of the Operator's pit permit and closure plan. from lease and well location. All metal bolts and other materials have been removed. Portable b to be removed.) All other environmental concerns have been addressed as per OCI Pipelines and flow lines have been abandoned in accordance with retrieved flow lines and pipelines. 	nd contour and has been cleared of all wo feet below ground level. y and pit location(s) have been remedi All flow lines, production equipment ses have been removed. (Poured onsit rules. 9.15.35.10 NMAC. All fluids have b	junk, trash, flow lines and ated in compliance with and junk have been removed e concrete bases do not have een removed from non-
 other production equipment. Anchors, dead men, tie downs and risers have been cut off at least If this is a one-well lease or last remaining well on lease, the batter OCD rules and the terms of the Operator's pit permit and closure plan. from lease and well location. All metal bolts and other materials have been removed. Portable b to be removed.) All other environmental concerns have been addressed as per OCI Pipelines and flow lines have been abandoned in accordance with retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electric 	nd contour and has been cleared of all wo feet below ground level. y and pit location(s) have been remedi All flow lines, production equipment ses have been removed. (Poured onsit rules. 9.15.35.10 NMAC. All fluids have b cal service poles and lines have been r	junk, trash, flow lines and ated in compliance with and junk have been removed e concrete bases do not have een removed from non- emoved from lease and well
 other production equipment. Anchors, dead men, tie downs and risers have been cut off at least If this is a one-well lease or last remaining well on lease, the batter OCD rules and the terms of the Operator's pit permit and closure plan. from lease and well location. All metal bolts and other materials have been removed. Portable b to be removed.) All other environmental concerns have been addressed as per OCI Pipelines and flow lines have been abandoned in accordance with retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electric location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate 	nd contour and has been cleared of all wo feet below ground level. y and pit location(s) have been remedi All flow lines, production equipment a ses have been removed. (Poured onsit rules. 9.15.35.10 NMAC. All fluids have b cal service poles and lines have been r	junk, trash, flow lines and ated in compliance with and junk have been removed e concrete bases do not have een removed from non- emoved from lease and well n.
 other production equipment. Anchors, dead men, tie downs and risers have been cut off at least If this is a one-well lease or last remaining well on lease, the batter OCD rules and the terms of the Operator's pit permit and closure plan. from lease and well location. All metal bolts and other materials have been removed. Portable b to be removed.) All other environmental concerns have been addressed as per OCI Pipelines and flow lines have been abandoned in accordance with retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electric location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate 	nd contour and has been cleared of all wo feet below ground level. y and pit location(s) have been remedi All flow lines, production equipment a ses have been removed. (Poured onsit rules. 9.15.35.10 NMAC. All fluids have b cal service poles and lines have been r	junk, trash, flow lines and ated in compliance with and junk have been removed e concrete bases do not have een removed from non- emoved from lease and well n.
other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least X If this is a one-well lease or last remaining well on lease, the batter OCD rules and the terms of the Operator's pit permit and closure plan. from lease and well location. X All metal bolts and other materials have been removed. Portable b to be removed.) X All other environmental concerns have been addressed as per OCI X Pipelines and flow lines have been abandoned in accordance with retrieved flow lines and pipelines. X X If this is a one-well lease or last remaining well on lease: all electr location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate SIGNATURE	nd contour and has been cleared of all wo feet below ground level. y and pit location(s) have been remedi All flow lines, production equipment a ses have been removed. (Poured onsit rules. 9.15.35.10 NMAC. All fluids have b cal service poles and lines have been r District office to schedule an inspectio	junk, trash, flow lines and ated in compliance with and junk have been removed the concrete bases do not have een removed from non- emoved from lease and well n. $MTE - \frac{G - 27 - 16}{16}$
 other production equipment. Anchors, dead men, tie downs and risers have been cut off at least If this is a one-well lease or last remaining well on lease, the batter OCD rules and the terms of the Operator's pit permit and closure plan. from lease and well location. All metal bolts and other materials have been removed. Portable b to be removed.) All other environmental concerns have been addressed as per OCI Pipelines and flow lines have been abandoned in accordance with retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electric location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate SIGNATURE	nd contour and has been cleared of all wo feet below ground level. y and pit location(s) have been remedi All flow lines, production equipment a ses have been removed. (Poured onsit rules. 9.15.35.10 NMAC. All fluids have b cal service poles and lines have been r District office to schedule an inspectio	junk, trash, flow lines and ated in compliance with and junk have been removed the concrete bases do not have een removed from non- emoved from lease and well n. $MTE - \frac{G - 27 - 16}{16}$
other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least X If this is a one-well lease or last remaining well on lease, the batter OCD rules and the terms of the Operator's pit permit and closure plan. from lease and well location. X All metal bolts and other materials have been removed. Portable b to be removed.) X All other environmental concerns have been addressed as per OCI X Pipelines and flow lines have been abandoned in accordance with retrieved flow lines and pipelines. X X If this is a one-well lease or last remaining well on lease: all electr location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate SIGNATURE	nd contour and has been cleared of all wo feet below ground level. y and pit location(s) have been remedi All flow lines, production equipment a ses have been removed. (Poured onsit rules. 9.15.35.10 NMAC. All fluids have b cal service poles and lines have been r District office to schedule an inspectio ENVIRONMENTAL ADVISOR_DA y_summers@oxy.com PHONE:	junk, trash, flow lines and ated in compliance with and junk have been removed e concrete bases do not have een removed from non- emoved from lease and well n. $x_{TE} = \frac{6 \cdot 27 \cdot 16}{575 \cdot 513 \cdot 8289}$
 other production equipment. Anchors, dead men, tie downs and risers have been cut off at least If this is a one-well lease or last remaining well on lease, the batter OCD rules and the terms of the Operator's pit permit and closure plan. from lease and well location. All metal bolts and other materials have been removed. Portable b to be removed.) All other environmental concerns have been addressed as per OCI Pipelines and flow lines have been abandoned in accordance with retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electric location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate SIGNATURE	nd contour and has been cleared of all wo feet below ground level. y and pit location(s) have been remedi All flow lines, production equipment a ses have been removed. (Poured onsit rules. 9.15.35.10 NMAC. All fluids have b cal service poles and lines have been r District office to schedule an inspectio	junk, trash, flow lines and ated in compliance with and junk have been removed the concrete bases do not have een removed from non- emoved from lease and well n. $MTE - \frac{G - 27 - 16}{16}$