

State of New Mexico  
Energy, Minerals and Natural Resources Department

Susana Martinez  
Governor

Tony Delfin  
Acting Cabinet Secretary

David Catanach, Director  
Oil Conservation Division



**\*Response Required - Deadline Enclosed\***

*Field Inspection Program*  
*"Preserving the Integrity of Our Environment"*

**HOBBS OCD**

**SEP 08 2016**

**RECEIVED**

08-Sep-16

**MATADOR PRODUCTION COMPANY**

One Lincoln Centre 5400 LBJ Freeway, Ste 1500  
Dallas TX 75240-5240

**LETTER OF VIOLATION - Inspection**

Dear Operator:


The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

**INSPECTION DETAIL SECTION**

<b>ATLANTIC 32 STATE</b>		<b>No.002</b>	<b>E-32-18S-33E</b>	<b>30-025-31222-00-00</b>		
<b>Inspection Date</b>	<b>Type Inspection</b>	<b>Inspector</b>	<b>Violation?</b>	<b>*Significant Non-Compliance?</b>	<b>Corrective Action Due By:</b>	<b>Inspection No.</b>
09/08/2016	Routine/Periodic	Mark Whitaker	Yes	No	10/21/2016	iMAW1625235658
<b>Violations</b>						
<b>Surface Damage/Restoration</b>						
<b>Comments on Inspection:</b>		DO NOT RELEASE BONDS. Need to flush flowline to battery and disconnect at production header. Need to install new well sign at battery. Need to remove pumping unit, anchors, wellhead, concrete, guard rails and other debris on north side of location, well sign, and power disconnect and conduit off power pole on northeast corner of location.				

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,   
Petroleum Engr. Specialist

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.  
\*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD  
OIL CONSERVATION DIVISION  
1625 N FRENCH DRIVE  
HOBBS NM 88240

MATADOR PRODUCTION COMPANY  
ONE LINCOLN CENTRE  
5400 LBJ FREEWAY, STE 1500  
DALLAS, TX 75240



HASLER

FIRST-CLASS MAIL

**\$000.67<sup>5</sup>**

09/08/2016 ZIP 88240  
012E14642224

US POSTAGE