Submit One Copy To Appropriate District Office District I State of New Mexico Energy, Minerals and Natural Resources	Form C-103 Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240	WELL API NO. 30-025-02719
811 S. First St., Artesia, NM 88210 DIVISION District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410  District IV 1220 S. St. Francis Dr., Santa Fe, NM ECEIVED  87505  Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name STATE TB
PROPOSALS.)  1. Type of Well:  Gas Well  Other	8. Well Number 1
Name of Operator     DEVON ENERGY PRODUCTION CO LP	9. OGRID Number 6137
3. Address of Operator PO BOX 250, ARTESIA, NM 88211	10. Pool name or Wildcat TOWNSEND; PERMO UPPER PENN
4. Well Location	
Unit Letter:_N, 660feet from the SOUTH line and 1980 feet from the WEST line	
Section 2 Township 16S Range 35E NMPM County LEA  11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3998' KB; 3987' GL	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING   PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT JOB   PAND A   CASING/CEMENT JOB   PAND A   P	
	ready for OCD inspection after P&A
<ul> <li>All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.</li> <li>Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.</li> <li>A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the         OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.     </li> </ul>	
<ul> <li>☑ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.</li> <li>☑ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.</li> </ul>	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.  All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	
<ul> <li>✓ All other environmental concerns have been addressed as per OCD rules.</li> <li>✓ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-</li> </ul>	
retrieved flow lines and pipelines.  If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE Level Beroud TITLE ADMIN FIELD SU	JPPORTDATE8/29/2016
TYPE OR PRINT NAMEDenise Menoud	
APPROVED BY: Mal With TITLE P.E.S.  Conditions of Approval (if any):	DATE 9/29/2016