NMOCD: HOBBS OCD Form 3160-5 FORM APPROVED UNITED STATES (June 2015) Hobbs OMB NO. 1004-0137 DEPARTMENT OF THE INTERIOR Expires: January 31, 2018 **BUREAU OF LAND MANAGEMENT** 5 Lease Serial No. Do not use this form for proposals to drill or to re-enter an **NSUNDRY NOTICES AND REPORTS ON WELLS** NMNM0558018 abandoned well. Use form 3160-3 (APD) for such proposals. 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2 1. Type of Well 8. Well Name and No. UNION SI FEDERAL 4 ☑ Oil Well ☐ Gas Well ☐ Other **ROSS PEARSON** API Well No. Name of Operator Contact: CROSS BORDER RESOURCES, INCE-Mail: ROSS@REDMOUNTAINRESOURCES.COM 30-005-20867-00-S1 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area 14282 GILLIS ROAD Ph: 214-871-0400 Ext: 1019 TOMAHAWK-SAN ANDRES FARMERS BRANCH, TX 75244 Fx: 214-871-0406 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State Sec 1 T8S R31E NENE 330FNL 330FEL CHAVES COUNTY, NM 33.655213 N Lat, 103.719434 W Lon 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION ☐ Acidize □ Deepen ☐ Production (Start/Resume) ■ Water Shut-Off Notice of Intent ☐ Alter Casing ☐ Hydraulic Fracturing □ Reclamation ■ Well Integrity ☐ Subsequent Report Casing Repair □ New Construction Other ☐ Recomplete Production Start-up ☐ Final Abandonment Notice ☐ Change Plans ☐ Plug and Abandon ☐ Temporarily Abandon ☐ Convert to Injection ☐ Plug Back ☐ Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. MONTH PERIOD ACCEPTED FOR MIRU pulling unit. MAY 1 4 7017 POOH with rods and pump. POOH with production tubing. Check fluid level. Acidize well if it is carrying a fluid level (800 to 1000' above the perfs). Hydrotest tubing back into the hole. Accepted For Record Only! Approval Subject Run pump and rods. To Putting Well On Continuous Production And Keeping Well On Continuous Production Return well to production. Or Plugging Well With An Approved Plugging Program! 14. I hereby certify that the foregoing is true and correct Electronic Submission #367051 verified by the BLM Well Information System For CROSS BORDER RESOURCES, INC., sent to the Roswell Committed to AFMSS for processing by DAVID GLASS on 02/14/2017 (17DRG0100SE) Name (Printed/Typed) **ROSS PEARSON** Title VP OPERATION (Electronic Submission) Date 02/14/2017 Signature THIS SPACE FOR FEDERAL OR STATE OFFICE USE ACCEPTED FOR RECORD Date Approved By Approv Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or a qualificative to those rights in the subject lease

Title 18 U.S.C. Section 1001 and 1016 42 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

which would entitle the applicant to conduct operations thereon.

Office