Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NMOCD SUNDRY NOTICES AND REPORTS ON WELLS RECOVER

FORM APPROVED OMB NO. 1004-0137

NMNM0558018

Expires: January	31,	201
Lease Serial No.		

Do not use the abandoned we	proposals.	OCD	6. If Indian, Allottee or Tribe Name							
SUBMIT IN	TRIPLICATE - Other inst	page 2	017	7. If Unit or CA/Agreement, Name and/or No.						
Type of Well	ner ,	RECEIV	ED	8. Well Name and No. UNION SI FEDERAL 2						
Name of Operator CROSS BORDER RESOURCE	Contact: CES, INCE-Mail: ROSS@RI	RSON RESOURCES.CO	М	9. API Well No. 30-005-20866-00-S1						
3a. Address 14282 GILLIS ROAD FARMERS BRANCH, TX 752	244	o. (include area code) 71-0400 Ext: 1019 1-0406		10. Field and Pool or Exploratory Area TOMAHAWK-SAN ANDRES						
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description			11. County or Parish, State						
Sec 1 T8S R31E NENW 660F 33.654299 N Lat, 103.729273				CHAVES COUNTY, NM						
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	ER DA	.TA			
TYPE OF SUBMISSION		TYPE OF ACTION								
☐ Notice of Intent	☐ Acidize	☐ Dee	pen	☐ Product	ion (Start/Resume)	■ Water Shut-Off				
	☐ Alter Casing	☐ Hydraulic Fracturing ☐ Recl		☐ Reclam	ation	☐ Well Integrity				
Subsequent Report ∴	☐ Casing Repair	☐ New Construction ☐ Recomp		☐ Recomp	iplete 🖸 Other		ier			
☐ Final Abandonment Notice	☐ Change Plans		g and Abandon	-	orarily Abandon					
	☐ Convert to Injection	☐ Plug Back ☐ Water			Disposal proposed work and approximate duration thereof.					
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Rebuilding Tank Battery (12/20/2016 - 12/23/2016) Removed the remaining fluids in the four 210 bbl oil tanks, 400 bbl gun-barrel, 4' by 20' steel gun-barrel, a 10" by 30" 3 phase separator, and two 210 bbl F.G. water tanks. Remove any process of the tanks and haul solid BS&W to the Gandy Land Farm located in Roswell, New Mexico										
(1/13/2017 - 1/20/2017) Remove catwalk from oil tanks. Set tanks and separating equipment on the west side of the pad location. Remove piping and dispose of properly. Cut-off 210 bbl tank sumps (corroded). Weld on flat plate. Patch and repair small gun barrel. 400 bbl gun barrel is junk (plan to haul off). Re-build firewalls utilizing the original battery footprint. Approximately 30' by 130'.										
14. I hereby certify that the foregoing is true and correct. Electronic Submission #367818 verified by the BLM Well Information System For CROSS BORDER RESOURCES, INC., sent to the Roswell Committed to AFMSS for processing by JENNIFER SANCHEZ on 02/22/2017 (17JS0042SE)										
Name (Printed/Typed) ROSS PE	ARSON	Title VP OPERATION								
Signature (Electronic S	Submission)		Date 02/22/20	017			:			
,	THIS SPACE FO	R FEDERA	AL OR STATE	OFFICE U	SE		8			
Approved By			Title			D	ate			
Conditions of approval, if any, are attache certify that the applicant holds legal or equivinch would entitle the applicant to conduct the applicant the applicant to conduct the applicant the app	uitable title to those rights in the	Office								
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent				willfully to ma	ike to any department or a	gency of	the United			

(Instructions on page 2) ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

Additional data for EC transaction #367818 that would not fit on the form

32. Additional remarks, continued

(1/21/2017 - 1/25/2017)
Line new firewalls and 30' by 120' area with 30 mil HDPE plastic. Prepare new tank pad and level inside plastic lined area. Set tanks and separation equipment inside new fire wall area. All tanks shall have closed tops. Tie-in load lines. Tanks and equipment set as per attached diagram. Tanks are set in the original tank battery footprint. Tie-in separation equipment with poly and victualic couplings. Cement in corner posts and string new barb wire fencing around the battery. Painted all tanks and separation equipment in approved APD "sand" scheme.



Union SI Federal (API - 30-005-20866) 660' FNL & 1980'FWL Section 1, Twp. 8-S, Rge. 31-E Chaves County, New Mexico

