Form 3160-5 (June 2015)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Honn	FORM APPROVED OMB NO. 1004-0137		
.OUBS (	Expires: January 31, 20		
	5 Tease Serial No.		

NMNM90161	

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			NMNM90161  6. If Indian, Allottee or Tribe Name				
SUBMIT IN TRIPLICATE - Other instructions on page 2			7. If Unit or CA/Agreement, Name and/or No. NMNM120042X				
1. Type of Well				Well Name and No.     WEST BLINEBRY DRINKARD UNIT 45			
☑ Oil Well ☐ Gas Well ☐ Oth      Name of Operator     APACHE CORPORATION	9. API Well No. 30-025-36344						
	/ E-Mail: REESA.FISHER@						
3a. Address 303 VETERANS AIRPARK LANE SUITE 1000 MIDLAND, TX 79705  3b. Phone No. (include area code) Ph: 432-818-1000 Ext: 1062				<ol> <li>Field and Pool or Exploratory Area EUNICE; B-T-D, NORTH</li> </ol>			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, State			
Sec 9 T21S R37E SESE 1040	LEA COUNTY COUNTY, NM						
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
TYPE OF SUBMISSION		TYPE OF ACTION					
☐ Notice of Intent	☐ Acidize	□ Deepen	☐ Product	ion (Start/Resume)	☐ Water Shut-Off		
	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclama	ation	■ Well Integrity		
Subsequent Report	☐ Casing Repair	☐ New Construction	Recomp	olete	☑ Other Workover Operations		
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon ☐ Tempo		rarily Abandon workover Operations			
	☐ Convert to Injection	☐ Plug Back	☐ Water D	Disposal			
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.							
Apache performed the following:							
3/29/2017 MIRUSU POOH w/rods. SD due to high wind. 3/30/2017 POOH w/rods. Scan tbg out. 3/31/2017 RIH w/bit & scraper; tag fill @ 6776'. 4/03/2017 Perf Drinkard @ 6530'-6643' w/1 SPF, 100 shots. Set RBP @ 6660'. 4/04/2017 Acidize BTD w/12,736 gal 15% HCL NEFE acid & 14,400# rock salt. 4/05/2017 Wash salt; rel RBP. TTIH w/2-7/8" J-55 tbg. 4/06/2017 RIH w/pump & rods. Test to 500#; test good. SN @ 6701' & TAC @ 5536'. RTP							
14. I hereby certify that the foregoing is true and correct.  Electronic Submission #375083 verified by the BLM Well Information System  For APACHE CORPORATION, sent to the Hobbs							
Name (Printed/Typed) REESA FISHER		Title SR STA	Title SR STAFF REG ANALYST				
Signature (Electronic S	Date 05/04/20	)17					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved By		Title			Date		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.							

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

