| Submit 3 Copies To Appropriate District Office <u>District I</u> | 1220 South St. Francis Dr. | | WELL ADIAGO | Form C-103 June 19, 2008 |
|--|--|----------------------------|------------------------------|-----------------------------|
| 1625 N. French Dr., Hobbs, NM 88240 District II | | | WELL API NO. 30-025-21603 | |
| 1301 W. Grand Ave., Artesia, NM 88210 | | | 5. Indicate Type of Lease | |
| District III 1000 Rio Brazos Rd., Aztec, NM 87410 | | | STATE 🗸 F | EE 🗆 🖊 |
| Santa Fe, NM 87505 Strangis Dr., Santa Fe, NM | | 6. State Oil & Gas Lease ? | No. | |
| 87505 | | | E-1311 | |
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A | | | 7. Lease Name or Unit Ag | reement Name |
| DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH | | | New Mexico "X" Stat | e ′ |
| PROPOSALS.) 1. Type of Well: Oil Well Gas Well □ Other Other | | | 8. Well Number 1 | / |
| 2 Name of Operator | | | 9. OGRID Number | |
| JAY MANAGEMENT COMPANY, LLC | | | 2476 | 592 |
| 3. Address of Operator | | | 10. Pool name or Wildcat | |
| 2425 WEST LOOP SOUTH, SUITE 810 HOUSTON,TX 77027 | | | Mescalero San Andre | S |
| 4. Well Location Unit Letter P | 400 feet from the EAST | 11 2 | 330 feet from the S0 | OUTH 15 |
| Cint Better | rect nom the | | | |
| Section 10 | Township 10S Ra 11. Elevation (Show whether DR, | | NMPM County | LEA |
| 4324' GL | | | | |
| | | | | |
| 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data | | | | |
| NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ TEMPORARILY ABANDON ☑ CHANGE PLANS □ COMMENCE DRILLING OPNS.□ P AND A PULL OR ALTER CASING □ MULTIPLE COMPL □ CASING/CEMENT JOB □ | | | | |
| DOWNHOLE COMMINGLE | MOETH EE GOME | O/ (OII VO/ OEIVIEI VI | | |
| OTHER: | | OTHER: | | |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. | | | | |
| | | | | |
| Plan to enter well, remove down hole production equipment. | | | | |
| 2. TD the well and check for fill. | | | | |
| Run a retrievable bridge plug or packer to within 100 feet of uppermost perforations. | | | | |
| 4. Pressure test to 500 psi for 30 minute. | | | | |
| | | | | |
| Condition of Approval: notify | | | | |
| OCD Hobbs office 24 hours | | | | |
| | | | | |
| | | prior of runnin | g MIT Test & Chart | \$ |
| | n: n: n** | 1, | * 5 | |
| Spud Date: | Rig Release Da | ite: | | |
| | | | | |
| I hereby certify that the information above is true and complete to the best of my knowledge and belief. | | | | |
| Thereby certify that the information | | or or my michiga | | |
| SIGNATURE | TITLE Opera | ations Manager | DATE05/ | 30/2017 |
| Tune or print name Amir Contrar | E mail address | acankar@israr | aco-jay com PHONE. | 713_417_6530 |
| Type or print name Amir Sanker E-mail address: asanker@isramco-jay.com PHONE: 713-417-6530 | | | | |
| APPROVED BY: Valey S Drown TITLE AO/II DATE 4/5/2017 | | | | |
| Conditions of Approval (if any): | , | 6 | | / |

NOPROD REPORTED - 200 MONTHS