Form 3160-5

OCD Hobbs **UNITED STATES**

FORM APPROVED

(March 2012)	DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to require an					OMB No. 1004-0137 Expires: October 31, 2014			
,						. Lease Serial No.			
SUNDRY NOTICES AND REPORTS ON WELLS				NM-004609					
Do not us	se this form for	proposals to drill or to	re-enter an	6. If Indian, A	llottee or Tri	ibe Name			
abandone	d well. Ose Forti	1 3 100-3 (APD) 101 Spe	proposais	7 1611-4 -60	A / A	-4 Nome d/ N	VI-		
Do not use this form for proposals to drill or to abandoned well. Use Form 3160-3 (APD) for SUBMIT IN TRIPLICATE – Other instructions on page 2			SEP	7. If Unit of CA/Agreement, Name and/or No. NMNM-91005X					
1. Type of Well			CEIV	8. Well Name and No.					
Oil Well Gas Well Other			RECEIV	QPQASU #24					
2. Name of Operator Mewbourne Oil Company		100		9. API Well No. 30-025-25618					
3a. Address	3b. Phone No. (include area cod		10. Field and Pool, or Exploratory Area						
PO Box 5270, Hobbs, NM 88241		575-393-5905		Querecho Plains Queen					
4. Location of Well (Footage, Sec., T., R., M., or Survey Descrip. 2310 FNL & 1980 FWL, Sec 27, T-18-S, R				11. County or Parish, State					
	TI IDE OF NOTICE	Lea County, New Mexico							
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION									
THE OF SUBMISSION									
Notice of Intent	Acidize	Deepen	Production (Start/R	lesume)	Water	INT TO I	DΛ		
Notice of Intent	Alter Casing	Fracture Treat	Reclamantion		Well Ir	P&A NR			
Subsequent Report	Casing Repair	New Construction	Recomplete		Other	P&A R	D ~		
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily Aband	ion		FOAK	+m ~		
	Convert to Injectio	n Plug Back	Water Disposal						
following completion of the involvesting has been completed. Final determined that the site is ready for f 06/29/16 MIRU plugging ed fluid. Spotted 125 sx cemen Perf'd csg @ 1350. Establis @ 1262'. Perf'd csg @ 1201 @ 890'. Perf'd csg @ 100'. circulated to surface. WOC welder and backhoe. Dug of Removed deadmen. Cleaned	Abandonment Notices final inspection. quipment. Dug of t @ 3882-1910. hed injection rand. Establised injection pumped water of the control o	pout cellar. ND wellhead POH w/ tbg. Perf'd 4 te at 500 psi. Spotted 2 ection pressure 500 psi down csg and circulate fied cement @ 3' from f wellhead. Welded on	d. NU BOP. 06/30 1/2 csg @ 1415'. I 5 sx cement @ 16 i. Spotted 25 sx ce d around 8 5/8. 0	/16 Circu Established 55-1277'. ment @ 1 7/05/16 So down mov Dry Hole	llated we d injection WOC. 0 250-873. qz'd 50 s ved off. Marker'	ell with much on rate at 5 07/01/16 Ta . WOC. Ta sx cement (6 07/11/16 M	the operator has d laden 500 psi. agged plug gged plug 20 100' and Moved in d cellar.		
14. I hereby certify that the foregoing is	true and correct. Name (Printed/Typed)							
Cade Cate Title Prod				Eng.	ner				
Signature 2	7/18/17								
Accepted for Record THIS SPACE FOR FEDERAL OR STATE OFFICE USE									
Approved by Conditions of approval, it any, are attache	a Q. G		tle SPET	-	Date	8-31	-17		

that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 8 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, frictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

FOR RECORD ONLY MW/000 09/12/2017