Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

OCD Hobbs SUNDRY NOTICES AND REPORTS ON WELLS OBBS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

Lease Serial No. NMLC061873B

6. If Indian, Allottee or Tribe Name

	m occioni oroco (Ar	SEP 1	1 2017				
SUBMIT IN	7. If Unit or CA/Agree 891005247X	ement, Name and/or No.					
1. Type of Well	Well Name and No. COTTON DRAW	LINIT 509H					
☑ Oil Well ☐ Gas Well ☐ Ott							
Name of Operator DEVON ENERGY PRODUCT	9. API Well No. 30.025-43916						
3a. Address 333 WEST SHERIDAN AVEN OKLAHOMA CITY, OK 7310	3b. Phone No. (include area code) Ph: 405.552.6558		10. Field and Pool or Exploratory Area PADUCA				
4. Location of Well (Footage, Sec., T	11. County or Parish, State						
Sec 18 T25S R32E SESE 540 32.124561 N Lat, 103.707733	LEA COUNTY, NM						
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
TYPE OF SUBMISSION	TYPE OF ACTION						
■ Notice of Intent	☐ Acidize	□ Deepen	☐ Production (Start/Resume)		☐ Water Shut-Off		
	☐ Alter Casing	☐ Hydraulic Fracturing	□ Reclamation		■ Well Integrity		
☐ Subsequent Report	☐ Casing Repair	■ New Construction	Temporarily Abandon Char		⊠ Other		
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon			Change to Original A		
	☐ Convert to Injection	□ Plug Back	☐ Water I	Disposal			
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.							
plan: 1. Utilize a spudder rig to pre- 2. Description of Operations 1. Spudder rig contractor Trar section and pre-set surface ca a. After drilling the surface hol applicable rules and regulation b. Rig will utilize fresh water b handled entirely on a closed le	set surface casing. Insend Drilling will move in the cotton Draw asing on the Cotton Draw are section, the rig will run ns (OnShore Order 2, all ased mud to drill 17?" su toop basis. No earth pits were seen the constant of the constant o	casing and cement following all COAs and NMOCD regulations rface hole to TD. Solids control	e Il of the s). will be				

14. I hereby certify that the foregoing is true and correct. Electronic Submission #386390 verified by the BLM Well Information System For DEVON ENERGY PRODUCTION COMPAN, sent to the Carlsbad Committed to AFMSS for processing by CHRISTOPHER WALLS on 09/01/2017 (17CRW0048SE)								
Name (Printed/Type	ed) LINDA GOOD	Title	REGULATORY SPECIALIST					
Signature	(Electronic Submission)	Date	08/28/2017					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved By CHRISTOPHER WALLS		TitleF	ETROLEUM ENGINEER	Date 09/01/2017				
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Carlshad					

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)
** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **



Additional data for EC transaction #386390 that would not fit on the form

32. Additional remarks, continued

time has been reached.

3. A blind flange with the same pressure rating as the wellhead will be installed to seal the wellbore. Pressure will be monitored with needle valves installed on two wingvalves.

a. A means for intervention will be maintained while the drilling rig is not over the well.

4. Spudder rig operations is expected to take 8-10 days on a multi well pad

5. The BLM will be contacted and notified 24 hours prior to commencing spudder rig operations.
6. Drilling operation will be performed with the big rig. At that time an approved BOP stack will be nippled up and tested on the wellhead before drilling operations commences on each well.
a. The BLM will be contacted / notified 24 hours before the big rig moves back on to the pad with the pre-set surface casing.

7. Devon Energy will have supervision on the rig to ensure compliance with all BLM and NMOCD

regulations and to oversee operations.

8. Once the rig is removed, Devon Energy will secure the wellhead area by placing a guard rail around the cellar area.

The big rig must be moved in within 90 days of spudder rig completion