

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-26974
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 19552
7. Lease Name or Unit Agreement Name North Hobbs (G/SA) Unit
8. Well Number: 432
9. OGRID Number: 157984
10. Pool name or Wildcat Hobbs (G/SA)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other: Injector

2. Name of Operator
Occidental Permian Ltd.

3. Address of Operator
P.O. Box 4294, Houston, TX, 77210

4. Well Location
Unit Letter I : 1400 feet from the South line and 1300 feet from the East line
Section 32 Township 18S Range 38E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3629' (GL)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. MIRU PU x NDWD - NUBOP
2. POOH with injection equipment
3. RIH with 4-3/4" bit clean out to 4220', drill out CIBP @ 4220'
4. CO wellbore to original PBTD @ 4338', POOH with bit
5. RU WL run CBL/CIL from PBTD to Surface
6. RIH and set CIBP @ 4135', capped with pea gravel and 15' cement to 4085'.
RIH with CICR set @ 3889'
7. Squeezed Zn1B with aprox 600 sxs of cement (Volume will be adjusted once perms are isolated)
8. RIH with 4-3/4" bit and DO CICR, Cement. Test squeeze, continue DO to CIBP @ 4135'. Circulate clean,
9. DO CIBP and CO to PBTD
10. Perforate casing as following: 4275'-4285', 4260'-4268', 4248'-4252', 4227'-4240', 4206'-4210', 4192'-4202', 4245'-4255',
4133', 4137', 4074'-4079'.
11. RIH with PPI tool and acidized new and existing perms with 4000 gals of 15% HCL, POOH with PPI Tool
12. RIH with Injection equipment (injection packer to be set @ 3890', same place as before)
13. NDBOP - NUWH. Run H-5 test
14. RDMO PU

During this procedure we plan to use the closed-loop system with a steel tank and haul contents to the required disposal per ODC Rule 19.15.17

Condition of Approval: notify

OCD Hobbs office 24 hours

prior of running MIT Test & Chart

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Production Engineer DATE 11/15/2017

Type or print name Carlos Restrepo E-mail address carlos_restrepo@oxy.com PHONE: 713-838-5772

For State Use Only

APPROVED BY: [Signature] TITLE AO/II DATE 11/21/2017

Conditions of Approval (if any):

MB