

Submit 1 Copy To Appropriate District Office
District I – (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II – (575) 748-1283
811 S. First St., Artesia, NM 88210
District III – (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV – (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-06423
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Eumont Hardy Unit
8. Well Number 028
9. OGRID Number 151228
10. Pool name or Wildcat Eumont; Yates, 7 Rivers, Queen

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>
2. Name of Operator Mar Oil and Gas Corporation
3. Address of Operator PO Box 5155 Santa Fe, NM 87502
4. Well Location Unit Letter B : 660 feet from the North line and 1980 feet from the East line Section 6 Township 21S Range 37E NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input checked="" type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPL <input type="checkbox"/> DOWNHOLE COMMINGLE <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT -- REMEDIAL WORK COMMENCE DRILLING OPNS. INT TO PA CASING/CEMENT JOB P&A NR P&A R OTHER: <input type="checkbox"/>
--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Mar Oil purposes to PA Eumont Hardy Unit # 028 as follows.

10 3/4" CSA 177', cmt w/ 150 sx....Cement circulated

7" CSA 3515', cmt w/ 500 sx ...TOC estimated at 100'

Top of Salt 1385' Base of Salt 2585'

Open hole 3515'=3820'

Please see attached PA procedure and wellbore diagram.

**NOTIFY OCD 24 HOURS PRIOR TO
BEGINNING PLUGGING OPERATIONS**

Spud Date:

C103 INTENT TO P&A EXPIRES

03-05-2019

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Billy E. Prichard Title Foreman

DATE 2/27/18

Type or print name Billy(Bill)E. Prichard

E-mail address: billy@pwlle.net

PHONE: 432-934-7680

For State Use Only

APPROVED BY: Manuel Whitaker TITLE Petroleum Engr. Specialist DATE 03/05/2018

Conditions of Approval (if any):

Mar Oil & Gas Corporation
Eumont Hardy Unit # 28
API 30-025-06423
UL "B", Sec 6, T21S, R37E
660 FNL x 1980 FEL

Plugging Procedure

MIRUSU

Pull rods and pump

NU BOP

Pull tubing x packer

Run and set CIBP at 3475'

Tag CIBP

Hole in casing at unknown depth

Hole in casing 743'-900' squeezed in 1969

Pressure test casing

Spot 35 sx cmt

Displace casing with gelled brine

Perf at 2635'

Squeeze w/ 40 sx cmt x WOC

Tag cmt plug at 2510' or above

Perf at ~~1435'~~ 1350'

Squeeze w/ 40 sx cmt x WOC

Tag cmt plug ~~1335'~~ or above 1250'

Spot 40 sx cmt across 1969 hole 743'-900'

WOC and tag plug

Perf 350'

Squeeze w/ 35sx cmt x WOC

Tag cmt plug x Circulate cement to surface

Cut of well head

Insure casing is full of cement

Cut off Su anchors and install PA marker

Clean location

Prepare for release

Mar Oil & Gas Corporation

Eumont Hardy Unit # 28


API # 3002506423

Unit Letter "B", Section 6, T21S, R37E

Lea County, New Mexico

660 FNL x 1980 FEL

Current Well Diagram



Mar Oil & Gas Corporation

Eumont Hardy Unit # 28

API # 3002506423

Unit Letter "B", Section 6, T21S, R37E

Lea County, New Mexico

660 FNL x 1980 FEL

