Submit 1 Copy To Appropriate District State of New Mexico Office Energy Minerals and Natural Resources	Form C-103 Revised July 18, 2013
Submit 1 Copy To Appropriate District       State of New Mexico         Office       District I – (575) 393-6161         1625 N. French Dr., Hobbs       District II – (575) 748-124         District II – (575) 748-124       OBDE         811 S. First St., Artesia, NM 88210       OIL CONSERVATION DIVISION	WELL API NO. 30-025-34374
811 S. First St., Artesia, NM 88210         OIL CONSERVATION DIVISION         District III – (505) 334-6178         1000 Rio Brazos Rd., Aztec, NM 476 3460       0 2018         District III – (505) 476-3460    OIL CONSERVATION DIVISION	5. Indicate Type of Lease STATE X FEE
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM, FIVED Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	North Hobbs G/SA Unit     -       8. Well Number 531     -
1. Type of Well: Oil Well   Image: Gas Well   Other     2. Name of Operator	9. OGRID Number
Occidental Permian LTD	157984
3. Address of Operator PO Box 4294 Houston, TX 77210	10. Pool name or Wildcat Hobbs; Grayburg - San Andres
4. Well Location	Hobbs, Grayburg - San Andres
Unit Letter J : 2120 feet from the S line and	1550 feet from the <u>E</u> line
Section 32 Township 18S Range 38E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc., 3635' GL	
3033 GL	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WOR         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DR	—
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	
	_
CLOSED-LOOP SYSTEM	П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
MIRU x NDWH x NUBOP.	
POOH 124 jts tbg x ESP equipment.	
RIH 4 3/4" bit x tagged PBTD @ 4345'.	
Water washed perfs 4058'-4248' w/ 120 bbls FW x acid washed perfs w/ 3000 gals 15% acid x flushed tbg.	
Shot new perfs @ 4255' to 4290' w/ total of 84 holes.	
Ran acid job w/ 1000 gal 15% acid.	
RIH w/ 124 jts tbg @ 3944' ESP @ 3988'.	
RD x NDBOP x NUWH.	
[]	
Spud Date:         05/15/2018         Rig Release Date:         05/18/20	18
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
and that	
SIGNATURE COMPUTED TITLE Regulatory Specialist	DATE06/14/2018
Type or print name April Hood E-mail address: April_Hood@O; For State Use Only AA	ry.com PHONE: 713-366-5771
APPROVED BY: Malur Brownine A0/I DATE 6/21/2018	
Conditions of Approval (if any)!	

C

/