Form 3160-5 (June 2015)

## UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB NO. 1004-0137

Expires: January 31, 2018

BUREAU OF LAND MANAGEMENT 5 Lease Serial No. SUNDRY NOTICES AND REPORTS OF THE COMNM57730 Do not use this form for proposals to drill or to re abandoned well. Use form 3160-3 (APD) for such pro 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2 8. Well Name and No. LOWE FEDERAL 01 1. Type of Well ☑ Oil Well ☐ Gas Well ☐ Other 2. Name of Operator Contact: **AGGIE ALEXIEV** 9. API Well No. PENROC OIL CORPORATION 30-025-29647-00-S1 E-Mail: aggie@penrocoil.com 10. Field and Pool or Exploratory Area 3b. Phone No. (include area code) 3a. Address 1515 WEST CALLE SUR STREET Ph: 575-492-1236 UNDESIGNATED HOBBS, NM 88241 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State Sec 7 T13S R38E NWNW 330FNL 330FWL LEA COUNTY, NM 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION ☐ Acidize □ Deepen □ Production (Start/Resume) ■ Water Shut-Off Notice of Intent ☐ Alter Casing ☐ Hydraulic Fracturing □ Reclamation ☐ Well Integrity ☐ Subsequent Report Casing Repair □ New Construction □ Other Recomplete ☐ Change Plans ☐ Plug and Abandon ☐ Final Abandonment Notice ☐ Temporarily Abandon ☐ Plug Back ☐ Convert to Injection ■ Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Intent to recomplete in the Wolfcamp: RU WSU. NU BOP & POH w/ ESP. Lay same down. RU wireline. Run 4.5" gauge ring to 11,100'. Run 4.5" CIBP and set same @ 11,100'. With bailer runs set 35' of Class "H" cement on top of CIBP. Tag same. Perf 2 spf 9670'-9695' TIH w/ packer. Set same 9600'. Swab test, If necessary acidize w/3000 gal of 15% NEFE & ball sealerss Test well for production. 14. I hereby certify that the foregoing is true and correct Electronic Submission #428898 verified by the BLM Well Information System For PENROC OIL CORPORATION, sent to the Hobbs Committed to AFMSS for processing by PRISCILLA PEREZ on 07/27/2018 (18PP1559SE) Name (Printed/Typed) AGGIE ALEXIEV Title CONTROLLER (Electronic Submission) Date 07/26/2018 Signature THIS SPACE FOR FEDERAL OR STATE OFFICE USE /s/ Jonathon Shepard AUG 0 8 2018 Approved By Petroleum Engineer Conditions of approval, if any, are attached. Approval of this notice does not warrant or

certify that the applicant holds legal or equitable title to those rights in the subject lease

which would entitle the applicant to conduct operations thereon.

Carlsbad Field Office

Form 3160-5 (June 2015)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

#### FORM APPROVED OMB No. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

5. Lease Serial No.
NM-57730
6. If Indian, Allottee or Tribe Name

	Use Form 3160-3 (APD) for s		,			
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit of CA/Agreement, Name and/or No.		
I. Type of Well						
✓ Oil Well Gas Well Other				8. Well Name and No. Lowe Federal #1		
2. Name of Operator Pogo Oil & Gas Operating, Inc				9. API Well No. 30-025-29647		
3a. Address 1515 W Calle Sur, Suite 174, Hobbs, NM 88240 3b. Phone No. (include area code) (575) 942-2004 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) D-07-13S-38E, 330 FNL 330 FWL			10. Field and Pool or Exploratory Area			
				Wolfcamp		
				11. Country or Parish, State		
			Lea County, New Mexico			
12. CHE	CK THE APPROPRIATE BOX(ES) TO	INDICATE NATURE	OF NOTIO	CE, REPORT OR OTH	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
✓ Notice of Intent		eepen		uction (Start/Resume)	Water Shut-Off	
		ydraulic Fracturing	=	imation	Well Integrity	
Subsequent Report		ew Construction		mplete	Other	
Final Abandonment Nation		ug and Abandon	= '	orarily Abandon	•	
Final Abandonment Notice	Convert to Injection Pl	ug Back		ater Disposal		
With bailer runs set 35' of Class Perf 2 spf 9670'-9695'		ne.	E & ball s	ealers.		
, , , , ,	true and correct. Name (Printed/Typed)	Agent				
M. Y. Merchant		Title		·		
Signature Char	Shap Cet	Date 07/26/2018				
	THE SPACE FOR FE	DERAL OR STA	ATE OF	ICE USE	····	
Approved by		Title		D	ale	
Conditions of approval, if any, are attact pertify that the applicant holds legal or e which would entitle the applicant to con	ned. Approval of this notice does not warn equitable title to those rights in the subject duct operations thereon.	rant or t lease Office				
	B U.S.C Section 1212, make it a crime for ents or representations as to any matter w		y and will	fully to make to any dep	partment or agency of the United Sta	ites

#### **BUREAU OF LAND MANAGEMENT**

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

### Permanent Abandonment of Production Zone Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

- 1. Plug back operations shall commence within <u>ninety (90)</u> days from this approval. If you are unable to plug back the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.
- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822. For wells in Lea County, call 575-393-3612
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours. In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. **Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.** Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat Class "C"**, for up to 7,500 feet of depth or **Neat Class "H"**, for deeper than 7,500 feet plugs.
- 6. <u>Subsequent Plug back Reporting:</u> Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date work was completed.** If plugging back to a new zone submit a Completion Report, form 3160-4 with the Subsequent Report.
- 7. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.
- 8. <u>If well location is within the Timing Limitation Stipulation Area for Lesser Prairie-Chicken:</u> From March 1<sup>st</sup> through June 15<sup>th</sup> annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted