Submit 1 Copy To Appropriate District Office	State of New Me	xico	Form C-103	
District 1 - (575) 393-6161	Energy, Minerals and Natu	ral Resources	Revised July 18, 2013 WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283				
811 S. First St., Artesia, NM 88210	OIL CONSERVATION		3002544207	
District III (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fran		5. Indicate Type of Lease	
District IV - (505) 476-3460	Santa Fe, NM 87	/505	STATE FEE	
1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name	
DIFFERENT RESERVOIR LISE "APPLICATION FOR REPMIT" (FORM C-101) FOR SUCH			WEST EUMONT UNIT	
Diricher RASERVOR. USE AFFECTION ON TERMIN (FORM CONTON ON SOCH PROPOSALS.) 1. Type of Well: Oil Well [] Gas Well [] Other INJECTOR 2. Name of Operator FORTY ACRES ENERGY, LLC 3. Address of Operator 11777B Katy Freeway, Suite #305, Houston, TX 77079 4. Well Location			8. Well Number 211	
2. Name of Operator		0.0	9. OGRID Number	
FORTY ACRES ENERGY, LLC	OB ^B	18	371416	
3. Address of Operator			10. Pool name or Wildcat	
11777B Katy Freeway, Suite #305, H	Houston, TX 77079	· ~ 0	EUMONT; Yates-Seven Rivers-Queen (Oil)	
4. Well Location				
Unit Letter B : 1185 feet from the North line and 1345 feet from the East line				
Section 2	Township 21S Ran	Q	PM LEA County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3575' GR				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INT	ENTION TO:	SUBS	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI		
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	ЈОВ 🔲	
DOWNHOLE COMMINGLE				
		OTHER	Π	
UIDER SIEPRAIE IESI				

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

The well is injecting approximately 275 bpd at 760 psi on the surface. Following results of the step rate test, it is expected these wells will inject 500-700 bpd.

- 1. Shut wells in 48 hours prior to conducting the step rate test.
- 2. Using a pump truck equipped with a chart recorder, begin injecting at a gradient of 0.05 psi/ft.
- 3. Increase the gradient to 0.1, 0.2, 0.3, 0.4 and 0.5 psi/ft or until Formation Parting Pressure is reached.
- 4. A surface pressure vs. rate and bottom hole pressure vs. rate charts will be supplied to the OCD following the tests.

Spud Date: PROVIDE S.R.T. RESULTS TO SANTA FE OCD FOR	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE for	
Type or print name Jessica LaMarro E-mail address: jessica @faenergyus.com PHONE: 832-706-0041	
For State Use Only APPROVED BY:	
Conditions of Approval (if any): WBrown 9/18/2018	