Submit I Copy To Appropriate District State of New Mexico Form C-103 Office Revised July 18, 2013 Energy, Minerals and Natural Resources District 1 - (575) 393-6161 WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283 **OIL CONSERVATION DIVISION** 3002544208 811 S. First St., Artesia, NM 88210 District III - (505) 334-6178 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 5. Indicate Type of Lease Santa Fe, NM 87505 District IV - (505) 476-3460 STATE FEE 1220 S. St. Francis Dr., Santa Fe, NM 6. State Oil & Gas Lease No. 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH **WEST EUMONT UNIT** PROPOSALS.) 8. Well Number 212 1. Type of Well: Oil Well Gas Well Other INJECTOR 2. Name of Operator 9. OGRID Number FORTY ACRES ENERGY, LLC 371416 10. Pool name or Wildcat 3. Address of Operator 11777B Katy Freeway, Suite #305, Houston, TX 77079 EUMONT; Yates-Seven Rivers-Queen (Oil) 4. Well Location Unit Letter B: 1185 feet from the North line and 2580 feet from the East line Township 21S Range 35E **NMPM** Section LEA County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3567' GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING □ **TEMPORARILY ABANDON** \Box CHANGE PLANS COMMENCE DRILLING OPNS. P AND A **PULL OR ALTER CASING** П MULTIPLE COMPL П CASING/CEMENT JOB **DOWNHOLE COMMINGLE** CLOSED-LOOP SYSTEM OTHER: STEP RATE TEST \boxtimes OTHER: П 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. The well is injecting approximately 275 bpd at 760 psi on the surface. Following results of the step rate test, it is expected these wells will inject 500-700 bpd. 1. Shut wells in 48 hours prior to conducting the step rate test. Using a pump truck equipped with a chart recorder, begin injecting at a gradient of 0.05 psi/ft. 2. 3. Increase the gradient to 0.1, 0.2, 0.3, 0.4 and 0.5 psi/ft or until Formation Parting Pressure is reached. 4. A surface pressure vs. rate and bottom hole pressure vs. rate charts will be supplied to the OCD following the tests PROVIDE S.R.T. RESULTS TO SANTA FE OCD FOR Spud Date: APPROVAL I hereby certify that the information above is true and complete to the best of my knowledge and belief. **SIGNATURE** TITLE Geologist DATE 09/13/2018 Type or print name <u>Jessica LaMarro</u> E-mail address: <u>jessica@faenergvus.com</u> PHONE: 832-706-0041 For State Use Only

Conditions of Approval (if any):

Whoever 9/18/2018

DATE

Accepted for Record Only LE

APPROVED BY: